

### STM32F72xxx and STM32F73xxx device limitations

## Applicability

This document applies to the part numbers of STM32F72xxx and STM32F73xxx devices listed in [Table 1](#) and their variants shown in [Table 2](#).

[Section 1](#) gives a summary and [Section 2](#) a description of / workaround for device limitations, with respect to the device datasheet and reference manual RM0431.

**Table 1. Device summary**

Reference	Part numbers
STM32F72xxx	STM32F722IE, STM32F722ZE, STM32F722VE, STM32F722RE, STM32F722IC, STM32F722ZC, STM32F722VC, STM32F722RC, STM32F723IE, STM32F723ZE, STM32F723VE, STM32F723IC, STM32F723ZC, STM32F723VC
STM32F73xxx	STM32F732IE, STM32F732ZE, STM32F732VE, STM32F732RE, STM32F733IE, STM32F733ZE, STM32F733VE STM32F730R8, STM32F730V8, STM32F730Z8, STM32F730I8

**Table 2. Device variants**

Reference	Silicon revision codes	
	Device marking <sup>(1)</sup>	REV_ID <sup>(2)</sup>
STM32F72xxx	A and 1	0x1000
STM32F73xxx		

1. Refer to the device data sheet for how to identify this code on different types of package.
2. REV\_ID[15:0] bit field of DBGMCU\_IDCODE register. Refer to the reference manual.

# Contents

<b>1</b>	<b>Summary of device limitations</b>	<b>4</b>
<b>2</b>	<b>Description of device limitations</b>	<b>6</b>
2.1	Arm® 32-bit Cortex®-M7 core	6
2.1.1	Cortex®-M7 data corruption when using data cache configured in write-through	6
2.2	System	7
2.2.1	Internal noise impacting the ADC accuracy	7
2.2.2	Wakeup from Standby mode when the back-up SRAM regulator is enabled	8
2.2.3	Full JTAG configuration without NJTRST pin cannot be used	8
2.2.4	PCROP-protected areas in Flash memory may be unprotected	8
2.3	FMC	9
2.3.1	Dummy read cycles inserted when reading synchronous memories	9
2.3.2	Wrong data read from a busy NAND memory	9
2.3.3	Spurious clock stoppage with continuous clock feature enabled	9
2.3.4	Data read might be corrupted when the write FIFO is disabled	10
2.4	QUADSPI	11
2.4.1	First nibble of data not written after a dummy phase	11
2.4.2	Wrong data from memory-mapped read after an indirect mode operation	11
2.4.3	Memory-mapped read operations may fail when timeout counter is enabled.	12
2.5	ADC	12
2.5.1	ADC sequencer modification during conversion	12
2.6	DAC	12
2.6.1	DMA underrun flag management	12
2.6.2	DMA request not automatically cleared by clearing DMAEN	13
2.7	LPTIM	14
2.7.1	MCU may remain stuck in LPTIM interrupt when entering Stop mode	14
2.8	RTC	14
2.8.1	RTC calendar registers are not locked properly	14
2.9	I2C	15
2.9.1	Wrong data sampling when data setup time ( $t_{SU,DAT}$ ) is shorter than one I2C kernel clock period	15

---

2.9.2	Spurious bus error detection in master mode .....	16
2.9.3	10-bit master mode: new transfer cannot be launched if first part of the address is not acknowledged by the slave .....	16
2.9.4	Last-received byte loss in reload mode .....	16
2.10	USART .....	17
2.10.1	nRTS is active while RE or UE = 0 .....	17
2.11	SPI/I2S .....	18
2.11.1	BSY bit may stay high at the end of a data transfer in Slave mode ....	18
2.12	SDMMC .....	19
2.12.1	Wrong CCRCFAIL status after a response without CRC is received ...	19
2.12.2	MMC stream write of less than 8 bytes does not work correctly .....	19
2.13	BxCAN .....	20
2.13.1	BxCAN time triggered mode communication not supported .....	20
<b>3</b>	<b>Revision history .....</b>	<b>21</b>

# 1 Summary of device limitations

The following table gives a quick references to all documented device limitations of STM32F72xxx and STM32F73xxx and their status:

A = limitation present, workaround available

N = limitation present, no workaround available

P = limitation present, partial workaround available

“-” = limitation absent

Applicability of a workaround may depend on specific conditions of target application. Adoption of a workaround may cause restrictions to target application. Workaround for a limitation is deemed partial if it only reduces the rate of occurrence and/or consequences of the limitation, or if it is fully effective for only a subset of instances on the device or in only a subset of operating modes, of the function concerned.

**Table 3. Summary of device limitations**

Function	Section	Limitation	Status
			Rev. A and 1
Arm® 32-bit Cortex®-M7 core	2.1.1	Cortex®-M7 data corruption when using data cache configured in write-through	A
System	2.2.1	Internal noise impacting the ADC accuracy	A
	2.2.2	Wakeup from Standby mode when the back-up SRAM regulator is enabled	A
	2.2.3	Full JTAG configuration without NJTRST pin cannot be used	A
	2.2.4	PCROP-protected areas in Flash memory may be unprotected	A
FMC	2.3.1	Dummy read cycles inserted when reading synchronous memories	N
	2.3.2	Wrong data read from a busy NAND memory	A
	2.3.3	Spurious clock stoppage with continuous clock feature enabled	A
	2.3.4	Data read might be corrupted when the write FIFO is disabled	A
QUADSPI	2.4.1	First nibble of data not written after a dummy phase	A
	2.4.2	Wrong data from memory-mapped read after an indirect mode operation	A
	2.4.3	Memory-mapped read operations may fail when timeout counter is enabled.	A
ADC	2.5.1	ADC sequencer modification during conversion	A
DAC	2.6.1	DMA underrun flag management	A
	2.6.2	DMA request not automatically cleared by clearing DMAEN	A
LPTIM	2.7.1	MCU may remain stuck in LPTIM interrupt when entering Stop mode	A
RTC	2.8.1	RTC calendar registers are not locked properly	P

**Table 3. Summary of device limitations (continued)**

Function	Section	Limitation	Status
			Rev. A and 1
I2C	2.9.1	<i>Wrong data sampling when data setup time (<math>t_{SU,DAT}</math>) is shorter than one I2C kernel clock period</i>	A
	2.9.2	<i>Spurious bus error detection in master mode</i>	A
	2.9.3	<i>10-bit master mode: new transfer cannot be launched if first part of the address is not acknowledged by the slave</i>	A
	2.9.4	<i>Last-received byte loss in reload mode</i>	A
USART	2.10.1	<i>nRTS is active while RE or UE = 0</i>	A
SPI/I2S	2.11.1	<i>BSY bit may stay high at the end of a data transfer in Slave mode</i>	A
SDMMC	2.12.1	<i>Wrong CCRCFAIL status after a response without CRC is received</i>	A
	2.12.2	<i>MMC stream write of less than 8 bytes does not work correctly</i>	A
BxCAN	2.13.1	<i>BxCAN time triggered mode communication not supported</i>	N

## 2 Description of device limitations

The following sections describe limitations of the applicable devices with Arm<sup>®(a)</sup> core and provide workarounds if available. They are grouped by device functions.



### 2.1 Arm<sup>®</sup> 32-bit Cortex<sup>®</sup>-M7 core

An errata notice of the STM32F72xxx and STM32F73xxx core is available from <http://infocenter.arm.com>.

All the described limitations are minor and related to the revision r1p0 of the Cortex<sup>®</sup>-M7 core. Refer to:

- Arm processor Cortex<sup>®</sup>-M7 (AT610) and Cortex<sup>®</sup>-M7 with FPU (AT611) software developer errata notice
- Arm embedded trace macrocell CoreSight ETM-M7 (TM975) software developer errata notice

[Table 4](#) summarizes these limitations and their implications on the behavior of STM32F72xxx and STM32F73xxx devices.

**Table 4. Cortex<sup>®</sup>-M7 core limitations and impact on microcontroller behavior**

Arm ID	Arm category	Impact on STM32F72xxx and STM32F73xxx devices
851031	Cat C	Minor
850725	Cat C	Minor
850724	Cat C	Minor

#### 2.1.1 Cortex<sup>®</sup>-M7 data corruption when using data cache configured in write-through

##### Description

This limitation is registered under Arm<sup>®</sup> ID number 1259864 and classified into “Category A”.

If a particular sequence of stores and loads is performed to write-through memory, and some timing-based internal conditions are met, then a load might not get the last data stored to that address.

a. Arm is a registered trademark of Arm Limited (or its subsidiaries) in the US and/or elsewhere.

This erratum only occurs if the loads and stores are to write-through memory. This is due to any of the following:

- The MPU has been programmed to set this address as write-through.
- The default memory map is being used and this address is write-through in that map.
- The memory is cacheable, and the CM7\_CACR.FORCEWT bit is set.
- The memory is cacheable, shared, and the CM7\_CACR.SIWT bit is set.

The following sequence is required for this erratum to occur:

1. The address of interest must be in the cache.
2. A write-through store to the same doubleword as the address of interest.
3. One of the following:
  - A linefill is started (to a different cacheline to the address of interest) that allocates to the same set as the address of interest.
  - An ECC error.
  - A cache maintenance operation without a following DSB.
4. A store to the address of interest.
5. A load from the address of interest.

If certain specific timing conditions are met, the load gets the data from the first store, or from what was in the cache at the start of the sequence instead of the data from the second store.

The effect of this erratum is that load operations can return incorrect data.

### Workaround

There is no direct workaround for this erratum.

Where possible, Arm® recommends the use of the MPU to change the attributes on any write-through memory to write-back memory. If this is not possible, it might be necessary to disable the cache for sections of code that access write-through memory.

## 2.2 System

### 2.2.1 Internal noise impacting the ADC accuracy

#### Description

An internal noise generated on  $V_{DD}$  supplies and propagated internally may impact the ADC accuracy.

This noise is always active whatever the power mode of the MCU (Run or Sleep).

#### Workaround

To adapt the accuracy level to the application requirements, set one of the following options:

- Option1  
Set the ADCDC1 bit in the PWR\_CR register.
- Option2  
Set the corresponding ADCxDC2 bit in the SYSCFG\_PMC register.

Only one option can be set at a time.

For more details on option1 and option2 mechanisms, refer to AN4073

## 2.2.2 Wakeup from Standby mode when the back-up SRAM regulator is enabled

### Description

When writing to the PWR\_CSR1 register to enable or disable the back-up SRAM regulator, if the EIWUP bit is overwritten 0, the RTC wakeup event (alarm, RTC Tamper, RTC TimeStamp or RTC wakeup time) does not wake up the system from Standby mode.

### Workaround

For each write access on the PWR\_CSR1 register to enable or disable the back-up SRAM regulator, the EIWKUP bit must be set to 1 in order to enable a wakeup from Standby mode using RTC events.

## 2.2.3 Full JTAG configuration without NJTRST pin cannot be used

### Description

When using the JTAG debug port in debug mode, the connection with the debugger is lost if the NJTRST pin (PB4) is used as a GPIO. Only the 4-wire JTAG port configuration is impacted.

### Workaround

Use the SWD debug port instead of the full 4-wire JTAG port.

## 2.2.4 PCROP-protected areas in Flash memory may be unprotected

### Description

In case of readout protection level regression from level 1 to level 0, the PCROP protected areas in Flash memory may become unprotected.

### Workaround

The user application must set the readout protection level to level 2 to avoid PCROP-protected areas from being unprotected.



## 2.3 FMC

### 2.3.1 Dummy read cycles inserted when reading synchronous memories

#### Description

When performing a burst read access from a synchronous memory, two dummy read accesses are performed at the end of the burst cycle whatever the type of burst access.

The extra data values read are not used by the FMC and there is no functional failure.

#### Workaround

None.

### 2.3.2 Wrong data read from a busy NAND memory

#### Description

When a read command is issued to the NAND memory, the R/B signal gets activated upon the de-assertion of the chip select. If a read transaction is pending, the NAND controller might not detect the R/B signal (connected to NWAIT) previously asserted and sample a wrong data. This problem occurs only when the MEMSET timing is configured to 0x00 or when ATTHOLD timing is configured to 0x00 or 0x01.

#### Workaround

Either configure MEMSET timing to a value greater than 0x00 or ATTHOLD timing to a value greater than 0x01.

### 2.3.3 Spurious clock stoppage with continuous clock feature enabled

#### Description

With the continuous clock feature enabled, the FMC\_CLK clock may spuriously stop when:

- the FMC\_CLK clock is divided by 2, and
- an FMC bank set as 32-bit is accessed with a byte access.

division ratio set to 2, the FMC\_CLK clock may spuriously stop upon an

*Note:* With static memories, a spuriously stopped clock can be restarted by issuing a synchronous transaction or any asynchronous transaction different from a byte access on 32-bit data bus width.

#### Workaround

With the continuous clock feature enabled, do not set the FMC\_CLK clock division ratio to 2 when accessing 32-bit asynchronous memories with byte access.

### 2.3.4 Data read might be corrupted when the write FIFO is disabled

#### Description

When the write FIFO is disabled, the FIFO empty event is generated for every write access. During a write access, if a new read access occurs, the FMC grants the read access and waits till the FIFO gets empty. If another read access occurs in a very short window (one cycle the FIFO empty event), the returned data are corrupted. This issue occurs only when the write FIFO is disabled (the WFDIS bit in the FMC\_BCR1 register is set).

#### Workaround

Enable the write FIFO.

## 2.4 QUADSPI

### 2.4.1 First nibble of data not written after a dummy phase

#### Description

The first nibble of data to be written to the external Flash memory is lost when the following conditions are met:

- The QUADSPI is used in the indirect write mode
- At least one dummy cycle is used

#### Workaround

Use alternate bytes instead of dummy phase to add latency between the address phase and the data phase. This works only if the number of dummy cycles to substitute corresponds to a multiple of eight bits of data.

Example:

- To substitute one dummy cycle, send one alternate byte (only possible in DDR mode with four data lines).
- To substitute two dummy cycles, send one alternate byte in SDR mode with four data lines.
- To substitute four dummy cycles, send two alternate bytes in SDR mode with four data lines, or one alternate byte in SDR mode with two data lines.
- To substitute eight dummy cycles, send one alternate byte in SDR mode with one data line.

### 2.4.2 Wrong data from memory-mapped read after an indirect mode operation

#### Description

The first memory-mapped read in indirect mode can yield wrong data if the QUADSPI peripheral enters memorymapped mode with bits ADDRESS[1:0] of the QUADSPI\_AR register both set.

#### Workaround

Before entering memory-mapped mode, apply the following measure, depending on access mode:

- Indirect read mode: clear the QUADSPI\_AR register then issue an abort request to stop reading and to clear the BUSY bit.
- Indirect write mode: clear the QUADSPI\_AR register.

**Caution:** The QUADSPI\_DR register must not be written after clearing the QUADSPI\_AR register.

### 2.4.3 Memory-mapped read operations may fail when timeout counter is enabled.

#### Description

In memory-mapped mode with the timeout counter enabled (by setting the TCEN bit of the QUADSPI\_CR register), the QUADSPI peripheral may hang and the memory-mapped read operations fail. This occurs if the timeout flag TOF is set at the same clock edge as a new memory-mapped read request..

#### Workaround

Disable the timeout counter. To raise the chip select, perform an abort at the end of each memory-mapped read operation.

## 2.5 ADC

### 2.5.1 ADC sequencer modification during conversion

#### Description

If an ADC conversion is started by software (writing the SWSTART bit), and if the ADC\_SQRx or ADC\_JSQRx registers are modified during the conversion, the current conversion is reset and the ADC does not restart a new conversion sequence automatically. If an ADC conversion is started by hardware trigger, this limitation does not apply. The ADC restarts a new conversion sequence automatically.

#### Workaround

When an ADC conversion sequence is started by software, a new conversion sequence can be restarted only by setting the SWSTART bit in the ADC\_CR2 register.

## 2.6 DAC

### 2.6.1 DMA underrun flag management

#### Description

If the DMA is not fast enough to input the next digital data to the DAC, as a consequence, the same digital data is converted twice. In these conditions, the DMAUDR flag is set, which usually leads to disable the DMA data transfers. This is not the case: the DMA is not disabled by DMAUDR=1, and it keeps serving the DAC.

#### Workaround

To disable the DAC DMA stream, reset the EN bit (corresponding to the DAC DMA stream) in the DMA\_SxCR register.

## 2.6.2 DMA request not automatically cleared by clearing DMAEN

### Description

Upon an attempt to stop a DMA-to-DAC transfer, the DMA request is not automatically cleared by clearing the DAC channel bit of the DAC\_CR register (DMAEN) or by disabling the DAC clock.

If the application stops the DAC operation while the DMA request is pending, the request remains pending while the DAC is reinitialized and restarted, with the risk that a spurious DMA request is serviced as soon as the DAC is enabled again.

### Workaround

Apply the following sequence to stop the current DMA-to-DAC transfer and restart the DAC::

1. Check if DMAUDR bit is set in DAC\_CR.
2. Clear the DAC channel DMAEN bit.
3. Disable the DAC clock.
4. Reconfigure the DAC, DMA and the triggers.
5. Restart the application.

## 2.7 LPTIM

### 2.7.1 MCU may remain stuck in LPTIM interrupt when entering Stop mode

#### Description

This limitation occurs when disabling the low power timer (LPTIM).

When the firmware clears the LPTIM\_CR.ENABLE bit within a small time window around one LPTIM interrupt occurrence, then the LPTIM interrupt signal used to wake up the MCU from Stop mode may be frozen in active state. Consequently, when trying to enter Stop mode, this limitation prevents the MCU from entering low-power mode and the firmware remains stuck in the LPTIM interrupt routine.

This limitation applies to all Stop modes and to all instances of the LPTIM. Note that the occurrence of this issue is very low.

#### Workaround

In order to disable a low power timer (LPTIMx) peripheral, do not clear its ENABLE bit in its respective LPTIMx\_CR register. Instead, reset the whole LPTIMx peripheral via the RCC controller by setting and resetting its respective LPTIMxRST bit in the RCC\_APBxRSTRz register.

## 2.8 RTC

### 2.8.1 RTC calendar registers are not locked properly

#### Description

When reading the calendar registers with BYPSHAD = 0, the RTC\_TR and RTC\_DR registers may not be locked after reading the RTC\_SSR register. This happens if the read operation is initiated one APB clock period before the shadow registers are updated. This can result in a non-consistency of the three registers. Similarly, the RTC\_DR register can be updated after reading the RTC\_TR register instead of being locked.

#### Workaround

Apply one of the following measures:

1. Use BYPSHAD = 1 mode (bypass shadow registers), or
2. If BYPSHAD = 0, read the RTC\_SSR register again after reading the RTC\_SSR, RTC\_TR, RTC\_DR registers to confirm that RTC\_SSR is still the same, otherwise read the values again.

## 2.9 I2C

### 2.9.1 Wrong data sampling when data setup time ( $t_{\text{SU;DAT}}$ ) is shorter than one I2C kernel clock period

#### Description

The I<sup>2</sup>C-bus specification and user manual specify a minimum data setup time ( $t_{\text{SU;DAT}}$ ) as:

- 250 ns in Standard mode
- 100 ns in Fast mode
- 50 ns in Fast mode Plus

The MCU does not correctly sample the I<sup>2</sup>C-bus SDA line when  $t_{\text{SU;DAT}}$  is smaller than one I2C kernel clock (I<sup>2</sup>C-bus peripheral clock) period: the previous SDA value is sampled instead of the current one. This can result in a wrong receipt of slave address, data byte, or acknowledge bit.

#### Workaround

Increase the I2C kernel clock frequency to get I2C kernel clock period within the transmitter minimum data setup time. Alternatively, increase transmitter's minimum data setup time. If the transmitter setup time minimum value corresponds to the minimum value provided in the I2C-bus standard, the minimum I2CCLK frequencies are as follows:

- In Standard mode, if the transmitter minimum setup time is 250 ns, the I2CCLK frequency must be at least 4 MHz.
- In Fast mode, if the transmitter minimum setup time is 100 ns, the I2CCLK frequency must be at least 10 MHz.
- In Fast-mode Plus, if the transmitter minimum setup time is 50 ns, the I2CCLK frequency must be at least 20 MHz.

## 2.9.2 Spurious bus error detection in master mode

### Description

In master mode, a bus error can be detected spuriously, with the consequence of setting the BERR flag of the I2C\_SR register and generating bus error interrupt if such interrupt is enabled. Detection of bus error has no effect on the I<sup>2</sup>C-bus transfer in master mode and any such transfer continues normally.

### Workaround

If a bus error interrupt is generated in master mode, the BERR flag must be cleared by software. No other action is required and the ongoing transfer can be handled normally.

## 2.9.3 10-bit master mode: new transfer cannot be launched if first part of the address is not acknowledged by the slave

### Description

An I<sup>2</sup>C-bus master generates STOP condition upon non-acknowledge of I<sup>2</sup>C address that it sends. This applies to 7-bit address as well as to each byte of 10-bit address.

When the MCU set as I<sup>2</sup>C-bus master transmits a 10-bit address of which the first byte (5-bit header + 2 MSBs of the address + direction bit) is not acknowledged, the MCU duly generates STOP condition but it then cannot start any new I<sup>2</sup>C-bus transfer. In this spurious state, the NACKF flag of the I2C\_ISR register and the START bit of the I2C\_CR2 register are both set, while the START bit should normally be cleared.

### Workaround

In 10-bit-address master mode, if both NACKF flag and START bit get simultaneously set, proceed as follows:

1. Wait for the STOP condition detection (STOPF = 1 in I2C\_ISR register).
2. Disable the I2C peripheral.
3. Wait for a minimum of three APB cycles.
4. Enable the I2C peripheral again.

## 2.9.4 Last-received byte loss in reload mode

### Description

If in master receiver mode or slave receive mode with SBC = 1 the following conditions are all met:

- I<sup>2</sup>C-bus stretching is enabled (NOSTRETCH = 0)
- RELOAD bit of the I2C\_CR2 register is set
- NBYTES bitfield of the I2C\_CR2 register is set to N greater than 1
- byte N is received on the I<sup>2</sup>C-bus, raising the TCR flag
- N - 1 byte is not yet read out from the data register at the instant TCR is raised,

then the SCL line is pulled low (I<sup>2</sup>C-bus clock stretching) and the transfer of the byte N from the shift register to the data register inhibited until the byte N-1 is read and NBYTES bitfield reloaded with a new value, the latter of which also clears the TCR flag. As a consequence,



the software cannot get the byte N and use its content before setting the new value into the NBYTES field.

For I2C instances with independent clock, the last-received data is definitively lost (never transferred from the shift register to the data register) if the data N - 1 is read within four APB clock cycles preceding the receipt of the last data bit of byte N and thus the TCR flag raising. Refer to the product reference manual or datasheet for the I2C implementation table.

### Workaround

- In master mode or in slave mode with SBC = 1, use the reload mode with NBYTES = 1.
- In master receiver mode, if the number of bytes to transfer is greater than 255 bytes, do not use the reload mode. Instead, split the transfer into sections not exceeding 255 bytes and separate them with repeated START conditions.
- Make sure, for example through the use of DMA, that the byte N - 1 is always read before the TCR flag is raised. Specifically for I2C instances with independent clock, make sure that it is always read earlier than four APB clock cycles before the receipt of the last data bit of byte N and thus the TCR flag raising.

The last workaround in the list must be evaluated carefully for each application as the timing depends on factors such as the bus speed, interrupt management, software processing latencies, and DMA channel priority.

## 2.10 USART

### 2.10.1 nRTS is active while RE or UE = 0

#### Description

The nRTS line is driven low as soon as the RTSE bit is set, even if the USART is disabled (UE = 0) or the receiver is disabled (RE = 0), that is, not ready to receive data.

#### Workaround

Upon setting the UE and RE bits, configure the I/O used for nRTS into alternate function.

## 2.11 SPI/I2S

### 2.11.1 BSY bit may stay high at the end of a data transfer in Slave mode

#### Description

The BSY flag may sporadically remain high at the end of a data transfer in slave mode. This occurs upon coincidence of internal CPU clock and external SCK clock provided by master.

In such an event, if the software only relies on BSY flag to detect the end of SPI slave data transaction (for example to enter low-power mode or to change data line direction in half-duplex bidirectional mode), the detection fails.

As a conclusion, the BSY flag is unreliable for detecting the end of data transactions.

#### Workaround

Depending on SPI operating mode, use the following means for detecting the end of transaction:

- When NSS hardware management is applied and NSS signal is provided by master, use NSS flag.
- In SPI receiving mode, use the corresponding RXNE event flag.
- In SPI transmit-only mode, use the BSY flag in conjunction with a timeout expiry event. Set the timeout such as to exceed the expected duration of the last data frame and start it upon TXE event that occurs with the second bit of the last data frame. The end of the transaction corresponds to either the BSY flag becoming low or the timeout expiry, whichever happens first.

Prefer one of the first two measures to the third as they are simpler and less constraining. Alternatively, apply the following sequence to ensure reliable operation of the BSY flag in SPI transmit mode:

1. Write last data to data register
2. Poll the TXE flag until it becomes high, which occurs with the second bit of the data frame transfer
3. Disable SPI by clearing the SPE bit mandatorily before the end of the frame transfer
4. Poll the BSY bit until it becomes low, which signals the end of transfer

*Note: The alternative method can only be used with relatively fast CPU speeds versus relatively slow SPI clocks or/and long last data frames. The faster is the software execution, the shorter can be the duration of the last data frame.*

## 2.12 SDMMC

### 2.12.1 Wrong CCRCFAIL status after a response without CRC is received

#### Description

The CRC is calculated even if the response to a command does not contain any CRC field. As a consequence, after the SDIO command IO\_SEND\_OP\_COND (CMD5) is sent, the CCRCFAIL bit of the SDIO\_STA register is set.

#### Workaround

The CCRCFAIL bit in the SDIO\_STA register must be ignored by the software. CCRCFAIL must be cleared by setting the CCRCFAILC bit in the SDIO\_ICR register after reception of the response to the CMD5 command.

### 2.12.2 MMC stream write of less than 8 bytes does not work correctly

#### Description

When the SDMMC host starts a stream write (WRITE\_DAT\_UNTIL\_STOP CMD20), the number of bytes to transfer is not known by the card.

The card writes data from the host until a STOP\_TRANSMISSION (CMD12) command is received.

Use the WAITRESP value equal to "00" to indicate to SDMMC CPSM that no response is expected.

The WAITPEND bit 9 of the SDMMC\_CMD register is set to synchronize the sending of the STOP\_TRANSMISSION (CMD12) command with the data flow.

When WAITPEND is set, the transmission of this command stays pending until 50 data bits (including the Stop bit) remain to transmit.

For a stream write of less than 8 bytes, the STOP\_TRANSMISSION (CMD12) command must be started before the data transfer starts. Instead of this, the data write and the command sending are started simultaneously.

It implies that when less than 8 bytes must be transmitted, (8 - DATALENGTH) bytes are programmed to 0xFF in the card after the last byte programmed (where DATALENGTH is the number of data bytes to be transferred).

#### Workaround

Do not use stream write WRITE\_DAT\_UNTIL\_STOP (CMD20) with a DATALENGTH less than 8 bytes. Use set block length (SET\_BLOCKLEN: CMD16) followed by the single block write command (WRITE\_BLOCK\_CMD24) instead of the stream write (CMD20) with the desired block length.

## 2.13 BxCAN

### 2.13.1 BxCAN time triggered mode communication not supported

#### Description

The time triggered communication mode described in the reference manual is not supported. As a result the time stamp values are not available. The TTCM bit of the CAN-MCR register must be kept cleared (time-triggered communication mode disabled).

#### Workaround

None.

### 3 Revision history

**Table 5. Document revision history**

Date	Revision	Changes
02-Feb-2017	1	Initial release.
22-Aug-2017	2	<p>Updated whole document in line with the new errata sheet structure.</p> <p>FMC limitation:</p> <ul style="list-style-type: none"> <li>– Added <a href="#">Section 2.3.4: Data read might be corrupted when the write FIFO is disabled.</a></li> </ul> <p>QUADSPI limitation:</p> <ul style="list-style-type: none"> <li>– Updated <a href="#">Section 2.4.1: First nibble of data not written after a dummy phase.</a></li> </ul> <p>SPI/I2S limitation:</p> <ul style="list-style-type: none"> <li>– Moved <a href="#">Section 2.11.1: BSY bit may stay high at the end of a data transfer in Slave mode</a> from I2C to SPI/I2S limitation.</li> </ul>
28-Jun-2018	3	<p>Updated <a href="#">Table 1: Device summary</a> adding STM32F730x8 part numbers.</p> <p>Added Revision 1:</p> <ul style="list-style-type: none"> <li>– Updated <a href="#">Table 2: Device variants.</a></li> <li>– Updated <a href="#">Table 3: Summary of device limitations</a></li> </ul> <p>QUADSPI limitation:</p> <ul style="list-style-type: none"> <li>– Added <a href="#">Section 2.4.3: Memory-mapped read operations may fail when timeout counter is enabled..</a></li> </ul> <p>I2C limitations:</p> <ul style="list-style-type: none"> <li>– Added <a href="#">Section 2.9.4: Last-received byte loss in reload mode.</a></li> <li>– Updated limitation in line with I2C2 errata sheet.</li> </ul> <p>FMC limitations:</p> <ul style="list-style-type: none"> <li>– Updated <a href="#">Section 2.3.1: Dummy read cycles inserted when reading synchronous memories.</a></li> <li>– Updated <a href="#">Section 2.3.2: Wrong data read from a busy NAND memory.</a></li> <li>– Updated <a href="#">Section 2.3.3: Spurious clock stoppage with continuous clock feature enabled.</a></li> <li>– Updated <a href="#">Section 2.3.4: Data read might be corrupted when the write FIFO is disabled.</a></li> </ul> <p>RTC limitation:</p> <ul style="list-style-type: none"> <li>– Added <a href="#">Section 2.8.1: RTC calendar registers are not locked properly.</a></li> </ul> <p>LPTIM limitation:</p> <ul style="list-style-type: none"> <li>– Added <a href="#">Section 2.7.1: MCU may remain stuck in LPTIM interrupt when entering Stop mode.</a></li> </ul> <p>SPI/I2S limitation:</p> <ul style="list-style-type: none"> <li>– Updated <a href="#">Section 2.11.1: BSY bit may stay high at the end of a data transfer in Slave mode.</a></li> </ul>

Table 5. Document revision history (continued)

Date	Revision	Changes
07-Aug-2019	4	Added: <ul style="list-style-type: none"><li>– <i>Section 2.1.1: Cortex<sup>®</sup>-M7 data corruption when using data cache configured in write-through.</i></li><li>– <i>Section 2.2.3: Full JTAG configuration without NJTRST pin cannot be used.</i></li></ul>
05-Feb-2020	5	Added: <ul style="list-style-type: none"><li>– <i>Section 2.2.4: PCROP-protected areas in Flash memory may be unprotected.</i></li></ul>

**IMPORTANT NOTICE – PLEASE READ CAREFULLY**

STMicroelectronics NV and its subsidiaries (“ST”) reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST’s terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers’ products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. For additional information about ST trademarks, please refer to [www.st.com/trademarks](http://www.st.com/trademarks). All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2020 STMicroelectronics – All rights reserved