April 14, 2022

## PTN
# Withdrawal of ERU 16 and ERU 19 chokes

To streamline the product range, the following EPCOS chokes of the B82559A*A016 and B82559A*A019 series are being withdrawn. For alternative parts please contact your regional sales contact.

**Affected products**

| Ordering code of withdrawn product | Type | Ordering code of substitute product |
|---|---|---|
| **B82559A**0153A016 | ERU16 | **B82559B**0153A016 |
| B82559A0203A016 | ERU16 | B82559B0203A016 |
| B82559A0303A016 | ERU16 | B82559B0303A016 |
| B82559A2102A016 | ERU16 | B82559B2102A016 |
| B82559A3152A016 | ERU16 | B82559B3152A016 |
| B82559A4222A016 | ERU16 | B82559B4222A016 |
| B82559A5332A016 | ERU16 | B82559B5332A016 |
| B82559A5472A016 | ERU16 | B82559B5472A016 |
| B82559A6682A016 | ERU16 | B82559B6682A016 |
| B82559A7103A016 | ERU16 | B82559B7103A016 |
| B82559A0203A019 | ERU19 | B82559B0203A019 |
| B82559A0303A019 | ERU19 | B82559B0303A019 |
| B82559A2102A019 | ERU19 | B82559B2102A019 |
| B82559A3152A019 | ERU19 | B82559B3152A019 |
| B82559A4222A019 | ERU19 | B82559B4222A019 |
| B82559A5332A019 | ERU19 | B82559B5332A019 |
| B82559A5472A019 | ERU19 | B82559B5472A019 |
| B82559A6682A019 | ERU19 | B82559B6682A019 |
| B82559A7103A019 | ERU19 | B82559B7103A019 |
| B82559A9153A019 | ERU19 | B82559B9153A019 |

Deadline for last orders: April 1, 2023
Last shipments by:      July 1, 2023

The withdrawn A series will be replaced by the new B series B82559B* with a smaller footprint, higher saturation current, and lower DC resistance. All further technical changes are described in the related family data sheet that may be downloaded from LINK

**Contact** Florian Velden, MAG TF PM, Munich

**Customers are asked to address inquiries directly to their sales contacts.**