Broadcom
408 E. Plumeria Drive
San Jose, CA 95134
broadcom.com

BROADCOM®

Product Obsolescence Notification

PON#: PON-20210528-F06A0
Issue Date: May 28 2021

Dear Customer,

Broadcom announces the obsolescence of the following **40G SR4, iSR4 and eSR4** OSD Products.

These part numbers have approached the end of product life cycle. A suggested replacement with the same form factor and reach is indicated in the table below. These replacements may not interoperate with the original products.

Broadcom P/Ns	Product Description	Suggested replacements
AFBR-79EADZ-xxx AFBR-79EQxZ-xxx AFBR-79FIPZ-xxx	40G QSFP+ SR4	AFBR-89CDHZ
AFBR-79EIxZ-xxx	40G QSFP+ iSR4	
AFBR-79E3PZ-xxx AFBR-79EEPZ-xxx	40G QSFP+ eSR4	AFBR-89CEHZ

This notification is effective May 28, 2021. The key milestones are:

Last Time Buy Date is November 28, 2021, allowing 6 months for final customer orders.

Last Time Ship Date is May 28, 2022, allowing 6 months for final shipments.

Please note that orders will be accepted on a non-cancellable, non-returnable (NCNR) basis only. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

If you have any questions about this obsolescence, please contact your Broadcom Field Sales Engineer or Contact Center (https://www.broadcom.com/company/contact) for any questions or support requirements.