

TE Connectivity

Product Change Notification: P-22-022199

PCN Date: 18-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| General Product Description: | |
|-------------------------------|--|
| Terminal and splices products | |

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from TE Lickdale to TE Collegno.

Reason for Changes:

Dear Customer, PNs listed in this notification are currently produced in TE Lickdale Plant. To optimize supply chain, manufacturing process and delivery, source will be switched to TE Collegno Plant. No tools transfer and no new tools are involved in this process, this is just source switch (TE Collegno Plant has capacity and it was already source for these parts in the past). Estimated Dates: Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):

| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
|----------------------------------------|------------------------------------------------------|
| | 15-MAR-2022 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Dant Number | Part Discontinued | Customer | Customer Part | | Substitute Part | Substitute Alias Part | Description Of |
|-------------------|-------------------|----------|---------------|--------------------------------------|-----------------|-----------------------|----------------|
| Part Number | per PCN | Drawing | Number | Alias Part Number(s) | Number | Number(s) | Difference |
| 1-160655-1 | NO | | | | | | |
| 1-160759-1 | NO | | | | | | |
| 154717-3 | NO | | | | | | |
| <u>154718-1</u> | NO | | | | | | |
| <u>154718-3</u> | NO | | | | | | |
| <u> 160655-2</u> | NO | | | "F49671-000", "AMPS-0- 0160655-2" | | | |
| 160655-4 | NO | | | | | | |
| <u> 160655-6</u> | NO | | | | | | |
| <u>160684-2</u> | NO | | | | | | |
| 160684-4 | NO | | | | | | |
| <u>160860-2</u> | NO | | | | | | |
| 160860-4 | NO | | | | | | |
| <u>160864-2</u> | NO | | | | | | |
| <u> 160913-4</u> | NO | | | | | | |
| <u> 160914-2</u> | NO | | | | | | |
| <u> 160914-4</u> | NO | | | | | | |
| <u> 160928-2</u> | NO | | | | | | |
| <u> 160928-4</u> | NO | | | | | | |
| <u>42238-2</u> | NO | | | | | | |
| <u>5-160446-2</u> | NO | | | | | | |
| <u>5-160446-5</u> | NO | | | | | | |
| <u>5-160446-8</u> | NO | | | | | | |
| <u>5-160526-7</u> | NO | | | | | | |
| <u>5-160526-9</u> | NO | | | | | | |
| <u>6-160526-1</u> | NO | | | | | | |
| <u>6-160526-2</u> | NO | | | | | | |
| <u>62833-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u> 160684-2</u> | NO | | | | | | |
| <u> 160864-2</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u>1-160655-</u> <u>1</u> | NO | | | | | | |
| 160655-4 | NO | | | | | | |
| 160684-2 | NO | | | | | | |
| <u>160684-4</u> | NO | | | | | | |
| 160864-2 | NO | | | | | | |
| <u>160913-4</u> | NO | | | | | | |
| <u>42238-2</u> | NO | | | | | | |
| <u>62833-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u>1-160655-</u> <u>1</u> | NO | | | | | | |
| 160655-4 | NO | | | | | | |
| <u>160684-2</u> | NO | | | | | | |
| 160684-4 | NO | | | | | | |
| <u>160864-2</u> | NO | | | | | | |
| 160913-4 | NO | | | | | | |
| <u>42238-2</u> | NO | | | | | | |
| <u>62833-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u>42238-2</u> | NO | | | | | | |
| <u>5-160526-</u> <u>9</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part | Part Discontinued | Customer | Customer Part | Alias Part Number(s) | Substitute Part | Substitute Alias Part | Description Of |
|-----------------------|-------------------|----------|---------------|----------------------|-----------------|-----------------------|----------------|
| Number | per PCN | Drawing | Number | | Number | Number(s) | Difference |
| <u>1-</u> 160759-1 | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------|------------------------------|---------------------|-------------------------|--------------------------------------|---------------------------|------------------------------------|------------------------------|
| 154717-3 | | Diamig | | | | indiniber (6) | Difference |
| <u>154718-1</u> | | | | | | | |
| 154718-3 | NO | | | | | | |
| <u> 160655-2</u> | NO | | | "F49671-000", "AMPS-0- 0160655-2" | | | |
| 160655-4 | NO | | | | | | |
| <u> 160655-6</u> | NO | | | | | | |
| <u> 160684-4</u> | NO | | | | | | |
| <u> 160860-2</u> | NO | | | | | | |
| <u> 160860-4</u> | NO | | | | | | |
| <u> 160864-2</u> | NO | | | | | | |
| <u> 160913-4</u> | NO | | | | | | |
| <u> 160914-2</u> | NO | | | | | | |
| <u> 160914-4</u> | NO | | | | | | |
| <u> 160928-2</u> | NO | | | | | | |
| <u> 160928-4</u> | NO | | | | | | |
| <u>42238-2</u> | NO | | | | | | |
| <u>5-</u> 160446-2 | NO | | | | | | |
| <u>5-</u> 160446-5 | NO | | | | | | |
| <u>5-</u> 160446-8 | NO | | | | | | |
| <u>5-</u> 160526-7 | NO | | | | | | |
| <u>5-</u> 160526-9 | NO | | | | | | |
| <u>6-</u> 160526-1 | NO | | | | | | |
| <u>6-</u> 160526-2 | NO | | | | | | |
| <u>62833-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u> 160684-2</u> | NO | | | | | | |
| <u> 160864-2</u> | NO | | | | | | |