

TE Connectivity

Product Change Notification: P-21-021270 PCN Date: 02-AUG-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DYNAMIC D1000 HDR ASSEMBLY

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from TECC to Vendor of TECC, and TECC continue to have response of Quality, delivery and Cost TECC: TE Connectivity Connectors (Suzhou) Co., Ltd.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

O4-OCT-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

| Part Number | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|--------------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| <u>1-1827873-5</u> | NO | | | | | | |
| 1-1827876-2 | NO | | | | | | |
| <u>1-1939638-4</u> | NO | • | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 1-1827873-5 | NO | | | | | | |
| 1-1827876-2 | NO | | | | | | |
| 1-1939638-4 | NO | | | | | | |

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of | |
|-------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|--|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference | |
| 1-1827873-5 | NO | | | | | | | |
| 1-1827876-2 | NO | | | | | | | |
| 1-1939638-4 | NO | | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 1-1827873-5 | NO | | | | | | |
| 1-1827876-2 | NO | | | | | | |