

Document Number: PS0019F210

Date: 08. 31, 2019

New Design In Stop Notice

(Product Type)LDB18*C, LDB18*G, LDB18*K, LDB21*C, LDB31, LDB32, LDC18*B, LDC18*F, LDC18*G, LDC21*B, LDC21*H, LDC31, LDC32, LDC43, LDD18*A, LDD21*A, LDF18, LDF32, LFB21*BA, LFB21*BB, LFB32*SA, LFE32*EB, LFL18*TC, LFL18*TD, LFL21*TC, LFD18*DP3/4/B/C, LFD21*DC1/2/3/4, LFD21*DP1/2/3/4/5/6, LFD32*DC1/2, LFP15*004/033/038/045/089 Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.

This is the official notification that some of our products detailed below

shall be out of sales promotion with the immidiate effect.

Please review this, and refrain from designing the products affected into your new models and projects.

Your understanding and support are highly appreciated.

1. Product Type, Customer/Murata/Alternative Part Numbers:

(Product Type)LDB18*C, LDB18*G, LDB18*K, LDB21*C, LDB31, LDB32, LDC18*B, LDC18*F, LDC18*G, LDC21*B, LDC21*H, LDC31, LDC32, LDC43, Product Type: LDD18*A, LDD21*A, LDF18, LDF32, LFB21*BA, LFB21*BB, LFB32*SA, LFE32*EB, LFL18*TC, LFL18*TD, LFL21*TC, LFD18*DP3/4/B/C, LFD21*DC1/2/3/4, LFD21*DP1/2/3/4/5/6, LFD32*DC1/2, LFP15*004/033/038/045/089 Series

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

End-of-Life (EOL) of the products mentioned above has been decided

due to the discontinuance of materials used in the products.

Also, please be informed that these parts will be withdrawn as per the schedule below. The official notification of the Product Withdrawal will be submitted about one year later.

Last Time Order Due: 03. 31, 2022 Last Shipment Date: 09. 30, 2022

3. Contact Window:

Should you have any questions or concerns,

please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

(PD Section/Title Description) RF Discrete Products Department/Senior Manager

(Name) Jiro Shibata