

Product Advisory

Issue Date: 18-November-2022

Change Description:

Product Advisory: Partial label descriptions/content changed – From text “COO:” to text “REF:”.

Parts Affected:

ACFM-2113-BLK	ACPF-7824-BLK	ACPF-W055-TR1	AFEM-9140-SG1
ACFM-2113-SG1	ACPF-7824-TR1	ACPF-W056-BLK	AFEM-9140-SG2
ACFM-2113-TR1	ACPF-7A24-BLK	ACPF-W056-TR1	AFEM-9140-TR1
ACFM-2213-BLK	ACPF-7A24-TR1	ACPF-W060-BLK	AFEM-9146-SG1
ACFM-2213-TR1	ACPF-7A24-TR2	ACPF-W060-TR1	AFEM-9146-SG2
ACFM-2S13-TR1	ACPF-7B24-BLK	ACPF-W065-BLK	AFEM-9146-TR1
ACFM-7745-BLK	ACPF-7B24-TR1	ACPF-W065-TR1	AFEM-9186-TR1
ACFM-7745-TR1	ACPF-8241-BLK	ACPF-W066-BLK	
ACFM-W026-BLK	ACPF-8241-TR1	ACPF-W066-TR1	
ACFM-W026-TR1	ACPF-9050-BLK	ACPM-7788-TR1	
ACFM-W2G1-BLK	ACPF-9050-TR1	AFEM-9130-SG2	
ACFM-W2G1-SG1	ACPF-W050-BLK	AFEM-9130-TR1	
ACFM-W412-BLK	ACPF-W050-TR1	AFEM-9136-SG1	
ACFM-W412-TR1	ACPF-W055-BLK	AFEM-9136-TR1	

Description and Extent of Change:

CUSTOMERS RECEIVING PRODUCTS WITH THE STANDARD BROADCOM LABEL (INN_GEN1 or LS0058):

- Be ready to receive inner packs/boxes where the standard Broadcom label (mother label) has a “REF:” text, instead of “COO:” text, with a 2-digit barcode (with plain text value removed). Refer to the images below for illustration.
- Shipments can contain labels with either format (“COO:” versus “REF:”).
- If customer needs to register in their system for the COO of the material, they can do so by scanning either the “COO:” or the “REF:” barcode.

Notes: - COO: Country of Origin
REF: Reference





Reasons for Change:

For Custom purposes.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No change to the product's Form, Fit, Function, Quality or Reliability.

Effective Date of Change:

Product shipments using this change will begin in March-2023.

Qualification Data:

Not applicable.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery.