



# Product Change Notice

PCN Number: 17-0310-01  
Issue Date: 17-MARCH-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

XRP2526IDTR-1-F	SP3203ECY-L/TR	SP3249EEY-L/TR	SP211EHCT-L
SP6128AEY-L/TR	SP3203EEY-L/TR	SP2209EEY-L/TR	SP3226EEY-L/TR

**CHANGE CATEGORY:**

<input checked="" type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input type="checkbox"/> Other:		

**DESCRIPTION OF CHANGE:**

Qualification of copper wire bonding assembly in Carsem.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 19-JUNE-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.