

Finisar Corporation 1389 Moffett Park Drive Sunnyvale, CA USA 94089

Date Issued: 15-July-2021

End of Life Notification EOL 21.014

This document is an End of Life Notification (EOL) for Finisar® electric loopback SFP transceivers

Affected Part Numbers and Recommended Replacement Part Numbers

The Finisar part numbers affected by this EOL notice are as follows:

Finisar EOL Part	Suggested
Number	Replacement
FTRJ-0019-7-BS2	FTLF0078P2BTL

Reason for Discontinuation

FTRJ-0019-7-BS2 is not RoHS-compliant.

There is no shipment during recent several years.

End of Life Dates

All purchases should be for the replacement module with immediate effect.

RMA Replacements

After **July 15**, **2021**, II-VI reserves the right to replace any of the discontinued products listed above returned under RMA (Return Material Authorization) with a credit, at II-VI's discretion.

We apologize in advance for any inconvenience this may cause. Please do not hesitate to call on your local distributor, rep, or local II-VI sales manager for any additional information you need.

MATERIALS THAT MATTER



Finisar Corporation 1389 Moffett Park Drive Sunnyvale, CA USA 94089

For More Information

II-VI Incorporated 375 Saxonburg Boulevard Saxonburg, PA 16056 photonics.sales@ii-vi.com www.ii-vi.com