

RF-403-002 September 30, 2013

Overview

The purpose of this notification is to communicate that OmniVision Technologies, Inc. (OVT) is discontinuing product(s) identified below. The timeline and terms & conditions associated with the product discontinuance are contained within this notification.

Description

The demand for the products contained in this notification has significantly declined. A more cost effective device with more features and improved performance metrics is available as a superior replacement. OVT is discontinuing these devices to ensure we manage our inventory and supply chain to offer our customers the best level of service as well as the most economic supply chain.

Product(s) Affected

Please see attached table below.

Timeline

Effective Date: September 30, 2013

Last Time Order Date: March 30, 2014 (6 months from PDN notification)

Last Time Ship Date: September 30, 2014 (6 months from Last Time Order date; 1

year from PDN notification.

OVT will continue to accept orders for products contained in this notification between the effective date and last time order date noted above. During this period, all orders will be subject to non-cancelable, non-returnable (NCNR) terms. After the last time order date, OVT will no longer accept new orders for any product contained in this notification.

OVT will discontinue shipment of all products contained in this notification after the last time ship date noted above. All orders for these products must request delivery on or prior to the last time ship date.

Response

No response is required to this notification. For additional information regarding this notification, please contact your local OVT Sales Representative.

This notification can also be found on www.ovt.com/support. The notification link will be located on the bottom right hand corner of the web page.

www.ovt.com/support Page 1 of 2



RF-403-002 September 30, 2013

OVT Part Number	Replacement Device
OV03640-EAAA-AA0A	Please see Note 1.
OV03640-EAAF-AA0A	Please see Note 1.
OV03640-EAAF-AA0F	Please see Note 1.
OV03640-EBJA-AA0A	Please see Note 1.
OV03640-EBXA-AA0A	Please see Note 1.
OV03640-ECJA-BA0A	Please see Note 1.
OV03640-ECJF-BA1A	Please see Note 1.
OV03640-ECJF-BA1A	_
	Please see Note 1.
OV03640-ECXA-BA0A	Please see Note 1.
OV03640-ECXF-AA1A	Please see Note 1.
OV03640-ECXF-BA1A	Please see Note 1.
OV03640-ECXF-BA1F	Please see Note 1.
OV03640-ECXR-BA1A	Please see Note 1.
OV03640-ERZA-BM0A	Please see Note 1.
OV03640-ETJA-BA0A	Please see Note 1.
OV03640-ETXA-BA0A	Please see Note 1.
OV03640-G04A	Please see Note 1.
OV03640-G04A-2D	Please see Note 1.
OV03640-G04B	Please see Note 1.
OV03640-G04B-2D	Please see Note 1.
OV03640-G04C	Please see Note 1.
OV03640-G04C-2D	Please see Note 1.
OV03640-MFSG-A50A	Please see Note 1.
OV03640-MFSL-A50A	Please see Note 1.
OV03640-MFSL-A64K	Please see Note 1.
OV03640-MFZL-F580	Please see Note 1.
OV03640-MRBG-A51A	Please see Note 1.
OV03640-MRSG-A00A	Please see Note 1.
OV03640-MRSL-A00A	Please see Note 1.
OV03640-V56A	Please see Note 1.
OV03640-V56A-2D	Please see Note 1.
OV03640-V56B	Please see Note 1.
OV03640-V56B-2D	Please see Note 1.
OV03640-V56C	Please see Note 1.
OV03640-V56C-2D	Please see Note 1.

www.ovt.com/support Page 2 of 2



RF-403-002 September 30, 2013

OV03640-V56D	Please see Note 1.
OV03640-V56H	Please see Note 1.
OV03640-V56H-2D	Please see Note 1.
OV03640-V56T	Please see Note 1.
OV03640-W24D	Please see Note 1.
OV05642-A63A	Please see Note 1.
OV05642-A63A-Z	Please see Note 1.
OV05642-A63B	Please see Note 1.
OV05642-A63C	Please see Note 1.
OV05642-A63H	Please see Note 1.
OV05642-A63T	Please see Note 1.
OV05642-EAAA-AA0A	Please see Note 1.
OV05642-EBJA-AA0A	Please see Note 1.
OV05642-ECJA-BA0A	Please see Note 1.
OV05642-ECJF-BA0A	Please see Note 1.
OV05642-ECJF-BA1A	Please see Note 1.
OV05642-ECJF-BA1F	Please see Note 1.
OV05642-ECJR-BA1F	Please see Note 1.
OV05642-ETJA-BA0A	Please see Note 1.
OV05642-G04A	Please see Note 1.
OV05642-G04A-1F	Please see Note 1.
OV05642-G04A-Z	Please see Note 1.
OV05642-G04B	Please see Note 1.
OV05642-MC00-0002	Please see Note 1.
OV05642-MFSL-A00A	Please see Note 1.
OV05642-MFSL-F000	Please see Note 1.
OV05642-MRSL-A00A	Please see Note 1.
OV05642-MRSL-A01A	Please see Note 1.
OV07740-A32T-SS	Please see Note 1.
OV07950-G04N	Please see Note 1.
OV08850-G04A-2B	Please see Note 1.
OV08850-G04A-2B-Z	Please see Note 1.
OV09665-EAAA-AA0A	Please see Note 1.
OV09665-ECHA-BA0A	Please see Note 1.
OV09665-ECJA-BA0A	Please see Note 1.
OV09665-ECJF-BA1A	Please see Note 1.
OV09665-ECXA-BA0A	Please see Note 1.

www.ovt.com/support Page 3 of 2



RF-403-002 September 30, 2013

	<u>, </u>
OV09665-ECXF-AA1A	Please see Note 1.
OV09665-ECXF-BA1A	Please see Note 1.
OV09665-ETXA-BA0A	Please see Note 1.
OV09665-G03A	Please see Note 1.
OV09665-G03B	Please see Note 1.
OV09665-G04A	Please see Note 1.
OV09665-G04B	Please see Note 1.
OV09665-G20A	Please see Note 1.
OV09665-MFSL-F000	Please see Note 1.
OV09665-V26A	Please see Note 1.
OV09665-V26B	Please see Note 1.
OV09665-V26C	Please see Note 1.
OV09665-V26H	Please see Note 1.
OV09665-V26T	Please see Note 1.
OV09710-C48A	Please see Note 1.
OV09710-EAAA-AA0A	Please see Note 1.
OV09710-EBJA-AA0A	Please see Note 1.
OV09710-ECJA-BA0A	Please see Note 1.
OV09710-ECJC-BA0A	Please see Note 1.
OV09710-ECJF-AA1A	Please see Note 1.
OV09710-ECJQ-BA0A	Please see Note 1.
OV09710-ECXA-BA0A	Please see Note 1.
OV09710-ECXF-AA1A	Please see Note 1.
OV09710-ETXA-BA0A	Please see Note 1.
OV09710-F48V	Please see Note 1.
OV09710-G04A	Please see Note 1.
OV09710-G04B	Please see Note 1.
OV09710-G20A-Z	Please see Note 1.
OV09710-MFSL-F000	Please see Note 1.
OV09710-V28A	Please see Note 1.
OV09710-V28B	Please see Note 1.
OV09710-V28C	Please see Note 1.
OV09710-V28T	Please see Note 1.
OVC3620-Q40G-1G	Please see Note 1.
OVC3660-Q48G-1C	Please see Note 1.
OVC3660-Q48G-1H	Please see Note 1.
OVC3660-Q48G-1I	Please see Note 1.

www.ovt.com/support Page 4 of 2



RF-403-002	September 30, 2013
111 103 002	3cptc1115c1 30, 2013

OVC3803-G20A-1G	Please see Note 1.
OVC3803-Q48G-1G	Please see Note 1.
OVC3850-Q48G-1G	Please see Note 1.

Note 1. Please contact your local Sales Representative for assistance with identifying a suitable replacement device.

www.ovt.com/support Page 5 of 2