



Product Change Notification

TE Connectivity

Product Change Notification: P-19-016787

PCN Date: 15-JAN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Tubing products impacted by new Prop 65

Description of Changes

This PCN is to inform our customers of additional labelling on some Tubing products. The requirements of the Proposition 65 (Prop 65) a Californian Safe water and Toxic Enforcement Act of 1986 now requires that we warn customers that some of our tubing products contain Antimony in the material make up. This requirement only applies to customer in California. However, as TE cannot predict which products will arrive with customers in California we have to label all Antimony containing products, of course these products will be delivered also to customers outside of California. No Action needs to be taken by our customers outside of California unless the products you receive are directly being forwarded through the supply chain to further customer in California USA in which case the warning must accompany the product. Please share this information with your colleagues so they will also be informed.

Reason for Changes:

Product improvement.To comply with Californian Prop 65 regulations.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	16-JAN-2019

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
003347-000	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
003701-000	NO			"1-1190028-6", "VERSAFIT-1/2-2-FSP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
1927574004	NO			"1-1201462-2", "ATUM-6/2-2-SP"			
217225J001	NO			"5-1191585-7", "V4-3.0-0-SP-SM"			
2283774002	NO			"3-1191680-6", "RNF-150-3/4-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
251143-000	NO			"6-1191840-4", "V4-3/32-0-SP"			
2687054004	NO			"1-1191983-5", "CGAT-18/6-0-SP"			
3081144004	NO			"8-1192333-1", "V4-1/2-0-SP"			
386997J001	NO			"6-1192902-2", "V4-10.0-0-FSP-SM"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
451555J001	NO			"1193391-3", "V4-2.0-0-SP-SM"			
4623554001	NO			"6-1193467-2", "CGPT-32/16-0-SP"			
4812454003	NO			"5-1193602-6", "VERSAFIT-3-0-SP"			
5023224004	NO			"1193770-8", "RP-4800-NO.8-0-SP"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5051514001	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052962027	NO			"6-1193829-7", "RNF-100-3/32-4-STK"			
5053044060	NO			"9-1193838-7", "RNF-100-3/16-0-SP"			
5053054012	NO			"3-1193841-6", "RNF-100-3/16-2-SP"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053074047	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
5053084107	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053114035	NO			"4-1193849-0", "RNF-100-1/4-4-SP"			
5053134034	NO			"6-1193851-9", "RNF-100-1/4-9-SP"			
5053232077	NO			"1193868-6", "RNF-100-1/2-WH-STK"			
5053284031	NO			"1-1193875-2", "RNF-100-3/4-9-SP"			
5053344027	NO			"3-1193882-8", "RNF-100-1-1/2-0-SP"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5433694001	NO			"9-1194261-9", "CGPT-24/8-0-SP"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5673904001	NO			"1194486-7", "DCPT-38/19-45-SP"			
5677554004	NO			"2-1194493-3", "RNF-3000-1.5/0.5-0-SP"			
5677614009	NO			"4-1194498-5", "RNF-3000-39/13-0-SP"			
5677784003	NO			"8-1194503-2", "RNF-3000-6/2-6-SP"			
5873234003	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"3-1194648-2", "CGAT-3/1-0-SP"			
594045J001	NO			"8-1194696-7", "V2-13.0-0-FSP-SM"			
5960714002	NO			"8-1194714-1", "RNF-3000-18/6-8-SP"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
7024704015	NO			"1-1195512-2", "ATUM-52/13-0-SP"			
729987-000	NO			"1195703-2", "VERSAFIT-3/8-6-FSP"			
7523674005	NO			"1-1195866-1", "RNF-150-3/32-0-SP"			
763665J001	NO			"8-1195945-1", "V2-25.0-0-FSP-SM"			
8014644009	NO			"3-1196196-3", "ATUM-16/4-0-SP"			
815581-000	NO			"1196356-9", "V4-3/64-0-SP"			
8278434002	NO			"3-1196465-5", "NETM2000-10-0-SP"			
8638624002	NO			"4-1196727-8", "RNF-3000-18/6-0-SP"			
8839744009	NO			"7-1196879-5", "ATUM-4/1-0-SP"			
892275J001	NO			"7-1196940-4", "V2-16.0-0-FSP-SM"			
939259-000	NO			"6-1197274-7", "VERSAFIT-3/4-9-FSP"			
985923J001	NO			"3-1197616-2", "V2-6.0-0-SP-SM"			
CB5066-000	NO			"9-1899832-3"			
CB5082-000	NO			"9-1899832-7"			
CB5090-000	NO			"1-1899833-4"			
CB5128-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5378-000	NO						
CF6053-000	NO						
CF6163-000	NO						
CL0859-000	NO			"SST-48-04/FR/97"			
E42160-000	NO			"6-1201151-2", "DWP-125-KIT3"			
NB07086001	NO			"BATTU-12.7/6.1-A1-2-32MM", "8-1899840-4"			
NB07146001	NO			"BATTU-25.4/12.7-A1-0-51MM", "7-1899840-8"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07276001	NO			"BATTU-25.4/12.7-A1-0-39MM"			
NB09524001	NO						
NB10132001	NO						
NB10364001	NO						
NB10784001	NO						
NB10802001	NO						
NB11014001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11802001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1927574004	NO			"1-1201462-2", "ATUM-6/2-2-SP"			
217225J001	NO			"5-1191585-7", "V4-3.0-0-SP-SM"			
2283774002	NO			"3-1191680-6", "RNF-150-3/4-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
251143-000	NO			"6-1191840-4", "V4-3/32-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
451555J001	NO			"1193391-3", "V4-2.0-0-SP-SM"			
4812454003	NO			"5-1193602-6", "VERSAFIT-3-0-SP"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5051514001	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052962027	NO			"6-1193829-7", "RNF-100-3/32-4-STK"			
5053074047	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
5053084107	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053232077	NO			"1193868-6", "RNF-100-1/2-WH-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5677554004	NO			"2-1194493-3", "RNF-3000-1.5/0.5-0-SP"			
5677614009	NO			"4-1194498-5", "RNF-3000-39/13-0-SP"			
594045J001	NO			"8-1194696-7", "V2-13.0-0-FSP-SM"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
7024704015	NO			"1-1195512-2", "ATUM-52/13-0-SP"			
8014644009	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"3-1196196-3", "ATUM-16/4-0-SP"			
8638624002	NO			"4-1196727-8", "RNF-3000-18/6-0-SP"			
892275J001	NO			"7-1196940-4", "V2-16.0-0-FSP-SM"			
985923J001	NO			"3-1197616-2", "V2-6.0-0-SP-SM"			
E42160-000	NO			"6-1201151-2", "DWP-125-KIT3"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11802001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
003347-000	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
003701-000	NO			"1-1190028-6", "VERSAFIT-1/2-2-FSP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
1927574004	NO			"1-1201462-2", "ATUM-6/2-2-SP"			
217225J001	NO			"5-1191585-7", "V4-3.0-0-SP-SM"			
2283774002	NO			"3-1191680-6", "RNF-150-3/4-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
251143-000	NO			"6-1191840-4", "V4-3/32-0-SP"			
3081144004	NO			"8-1192333-1", "V4-1/2-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
451555J001	NO			"1193391-3", "V4-2.0-0-SP-SM"			
4812454003	NO			"5-1193602-6", "VERSAFIT-3-0-SP"			
5023224004	NO			"1193770-8", "RP-4800-NO.8-0-SP"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5051514001	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052962027	NO			"6-1193829-7", "RNF-100-3/32-4-STK"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053074047	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
5053084107	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053232077	NO			"1193868-6", "RNF-100-1/2-WH-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP"			
5058704033	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"1193906-3", "VERSAFIT-1/8-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5673904001	NO			"1194486-7", "DCPT-38/19-45-SP"			
5677554004	NO			"2-1194493-3", "RNF-3000-1.5/0.5-0-SP"			
5677614009	NO			"4-1194498-5", "RNF-3000-39/13-0-SP"			
5677784003	NO			"8-1194503-2", "RNF-3000-6/2-6-SP"			
594045J001	NO			"8-1194696-7", "V2-13.0-0-FSP-SM"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
7024704015	NO			"1-1195512-2", "ATUM-52/13-0-SP"			
729987-000	NO			"1195703-2", "VERSAFIT-3/8-6-FSP"			
8014644009	NO			"3-1196196-3", "ATUM-16/4-0-SP"			
815581-000	NO			"1196356-9", "V4-3/64-0-SP"			
8638624002	NO			"4-1196727-8", "RNF-3000-18/6-0-SP"			
8839744009	NO			"7-1196879-5", "ATUM-4/1-0-SP"			
892275J001	NO			"7-1196940-4", "V2-16.0-0-FSP-SM"			
985923J001	NO			"3-1197616-2", "V2-6.0-0-SP-SM"			
CB5066-000	NO			"9-1899832-3"			
CB5082-000	NO			"9-1899832-7"			
CB5090-000	NO			"1-1899833-4"			
CB5128-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5378-000	NO						
CF6053-000	NO						
CF6163-000	NO						
CL0859-000	NO			"SST-48-04/FR/97"			
E42160-000	NO			"6-1201151-2", "DWP-125-KIT3"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11802001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
003347-000	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
003701-000	NO			"1-1190028-6", "VERSAFIT-1/2-2-FSP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
1927574004	NO			"1-1201462-2", "ATUM-6/2-2-SP"			
2283774002	NO			"3-1191680-6", "RNF-150-3/4-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
251143-000	NO			"6-1191840-4", "V4-3/32-0-SP"			
2687054004	NO			"1-1191983-5", "CGAT-18/6-0-SP"			
3081144004	NO			"8-1192333-1", "V4-1/2-0-SP"			
386997J001	NO			"6-1192902-2", "V4-10.0-0-FSP-SM"			
4623554001	NO			"6-1193467-2", "CGPT-32/16-0-SP"			
4812454003	NO			"5-1193602-6", "VERSAFIT-3-0-SP"			
5023224004	NO			"1193770-8", "RP-4800-NO.8-0-SP"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5051514001	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
5053044060	NO			"9-1193838-7", "RNF-100-3/16-0-SP"			
5053054012	NO			"3-1193841-6", "RNF-100-3/16-2-SP"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053074047	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
5053084107	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
5053114035	NO			"4-1193849-0", "RNF-100-1/4-4-SP"			
5053134034	NO			"6-1193851-9", "RNF-100-1/4-9-SP"			
5053284031	NO			"1-1193875-2", "RNF-100-3/4-9-SP"			
5053344027	NO			"3-1193882-8", "RNF-100-1-1/2-0-SP"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5433694001	NO			"9-1194261-9", "CGPT-24/8-0-SP"			
5673904001	NO			"1194486-7", "DCPT-38/19-45-SP"			
5677554004	NO			"2-1194493-3", "RNF-3000-1.5/0.5-0-SP"			
5677614009	NO			"4-1194498-5", "RNF-3000-39/13-0-SP"			
5677784003	NO			"8-1194503-2", "RNF-3000-6/2-6-SP"			
5873234003	NO			"3-1194648-2", "CGAT-3/1-0-SP"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
7024704015	NO			"1-1195512-2", "ATUM-52/13-0-SP"			
729987-000	NO			"1195703-2", "VERSAFIT-3/8-6-FSP"			
7523674005	NO			"1-1195866-1", "RNF-150-3/32-0-SP"			
763665J001	NO			"8-1195945-1", "V2-25.0-0-FSP-SM"			
8014644009	NO			"3-1196196-3", "ATUM-16/4-0-SP"			
815581-000	NO			"1196356-9", "V4-3/64-0-SP"			
8278434002	NO			"3-1196465-5", "NETM2000-10-0-SP"			
8638624002	NO			"4-1196727-8", "RNF-3000-18/6-0-SP"			
8839744009	NO			"7-1196879-5", "ATUM-4/1-0-SP"			
892275J001	NO			"7-1196940-4", "V2-16.0-0-FSP-SM"			
939259-000	NO			"6-1197274-7", "VERSAFIT-3/4-9-FSP"			
CB5066-000	NO			"9-1899832-3"			
CB5082-000	NO			"9-1899832-7"			
CB5090-000	NO			"1-1899833-4"			
CB5128-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5378-000	NO						
CF6053-000	NO						
CF6163-000	NO						
CL0859-000	NO			"SST-48-04/FR/97"			
NB09524001	NO						
NB10364001	NO						
NB10784001	NO						
NB11014001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
003347-000	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
003701-000	NO			"1-1190028-6", "VERSAFIT-1/2-2-FSP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
1927574004	NO			"1-1201462-2", "ATUM-6/2-2-SP"			
251143-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"6-1191840-4", "V4-3/32-0-SP"			
3081144004	NO			"8-1192333-1", "V4-1/2-0-SP"			
4812454003	NO			"5-1193602-6", "VERSAFIT-3-0-SP"			
5023224004	NO			"1193770-8", "RP-4800-NO.8-0-SP"			
5051514001	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053074047	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
5673904001	NO			"1194486-7", "DCPT-38/19-45-SP"			
5677554004	NO			"2-1194493-3", "RNF-3000-1.5/0.5-0-SP"			
5677614009	NO			"4-1194498-5", "RNF-3000-39/13-0-SP"			
5677784003	NO			"8-1194503-2", "RNF-3000-6/2-6-SP"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
7024704015	NO			"1-1195512-2", "ATUM-52/13-0-SP"			
729987-000	NO			"1195703-2", "VERSAFIT-3/8-6-FSP"			
8014644009	NO			"3-1196196-3", "ATUM-16/4-0-SP"			
815581-000	NO			"1196356-9", "V4-3/64-0-SP"			
8638624002	NO			"4-1196727-8", "RNF-3000-18/6-0-SP"			
8839744009	NO			"7-1196879-5", "ATUM-4/1-0-SP"			
892275J001	NO			"7-1196940-4", "V2-16.0-0-FSP-SM"			
CB5066-000	NO			"9-1899832-3"			
CB5082-000	NO			"9-1899832-7"			
CB5090-000	NO			"1-1899833-4"			
CB5128-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5378-000	NO						
CF6053-000	NO						
CF6163-000	NO						
CL0859-000	NO			"SST-48-04/FR/97"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
003347-000	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
003701-000	NO			"1-1190028-6", "VERSAFIT-1/2-2-FSP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
1927574004	NO			"1-1201462-2", "ATUM-6/2-2-SP"			
2283774002	NO			"3-1191680-6", "RNF-150-3/4-0-SP"			
2509914004	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"6-1191839-5", "RNF-150-3/16-0-SP"			
251143-000	NO			"6-1191840-4", "V4-3/32-0-SP"			
2687054004	NO			"1-1191983-5", "CGAT-18/6-0-SP"			
3081144004	NO			"8-1192333-1", "V4-1/2-0-SP"			
386997J001	NO			"6-1192902-2", "V4-10.0-0-FSP-SM"			
4623554001	NO			"6-1193467-2", "CGPT-32/16-0-SP"			
4812454003	NO			"5-1193602-6", "VERSAFIT-3-0-SP"			
5023224004	NO			"1193770-8", "RP-4800-NO.8-0-SP"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5051514001	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
5053044060	NO			"9-1193838-7", "RNF-100-3/16-0-SP"			
5053054012	NO			"3-1193841-6", "RNF-100-3/16-2-SP"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053074047	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
5053084107	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
5053114035	NO			"4-1193849-0", "RNF-100-1/4-4-SP"			
5053134034	NO			"6-1193851-9", "RNF-100-1/4-9-SP"			
5053284031	NO			"1-1193875-2", "RNF-100-3/4-9-SP"			
5053344027	NO			"3-1193882-8", "RNF-100-1-1/2-0-SP"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5433694001	NO			"9-1194261-9", "CGPT-24/8-0-SP"			
5673904001	NO			"1194486-7", "DCPT-38/19-45-SP"			
5677554004	NO			"2-1194493-3", "RNF-3000-1.5/0.5-0-SP"			
5677614009	NO			"4-1194498-5", "RNF-3000-39/13-0-SP"			
5677784003	NO			"8-1194503-2", "RNF-3000-6/2-6-SP"			
5873234003	NO			"3-1194648-2", "CGAT-3/1-0-SP"			
5960714002	NO			"8-1194714-1", "RNF-3000-18/6-8-SP"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
7024704015	NO			"1-1195512-2", "ATUM-52/13-0-SP"			
729987-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"1195703-2", "VERSAFIT-3/8-6-FSP"			
7523674005	NO			"1-1195866-1", "RNF-150-3/32-0-SP"			
763665J001	NO			"8-1195945-1", "V2-25.0-0-FSP-SM"			
8014644009	NO			"3-1196196-3", "ATUM-16/4-0-SP"			
815581-000	NO			"1196356-9", "V4-3/64-0-SP"			
8278434002	NO			"3-1196465-5", "NETM2000-10-0-SP"			
8638624002	NO			"4-1196727-8", "RNF-3000-18/6-0-SP"			
8839744009	NO			"7-1196879-5", "ATUM-4/1-0-SP"			
892275J001	NO			"7-1196940-4", "V2-16.0-0-FSP-SM"			
939259-000	NO			"6-1197274-7", "VERSAFIT-3/4-9-FSP"			
CB5066-000	NO			"9-1899832-3"			
CB5082-000	NO			"9-1899832-7"			
CB5090-000	NO			"1-1899833-4"			
CB5128-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5378-000	NO						
CF6053-000	NO						
CF6163-000	NO						
CL0859-000	NO			"SST-48-04/FR/97"			
NB07086001	NO			"BATTU-12.7/6.1-A1-2-32MM", "8-1899840-4"			
NB07146001	NO			"BATTU-25.4/12.7-A1-0-51MM", "7-1899840-8"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07276001	NO			"BATTU-25.4/12.7-A1-0-39MM"			
NB09524001	NO						
NB10364001	NO						
NB10784001	NO						
NB11014001	NO						