BOURNS

## PRODUCT OBSOLESCENCE MEMO MULTIFUSE® PPTC RESETTABLE FUSES



## **Bourns® MF-R/600 Model Series to be Discontinued**

*Riverside, California* – June 13, 2019 – In accordance with our ongoing product lifecycle management, Bourns has discontinued the <u>Multifuse® MF-R/600 series</u>. Diminishing demand necessitates this action.

Obsolete Part Numbers			
MF-R015/600-0	MF-R015/600-B-0	MF-R016/600-0	MF-R016/600-A-0
MF-R015/600-2	MF-R015/600-B-2	MF-R016/600-2	MF-R016/600-A-2
MF-R015/600-2-V7	MF-R015/600-B05-0	MF-R016/600-1-0	MF-R016/600-A05-0
MF-R015/600-A-0	MF-R015/600-B05-2	MF-R016/600-1-2	MF-R016/600-A05-2
MF-R015/600-A-2	MF-R015/600-F-0	MF-R016/600-105-0	
MF-R015/600-A05-0	MF-R015/600-F-2	MF-R016/600-105-2	
MF-R015/600-A05-2	MF-R015/600-F05-0		
	MF-R015/600-F05-2		

Regrettably, no replacement products are available from Bourns at this time. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be "sole sourced" by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued products. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-returnable.

Please plan for the following deadlines:

Last Time Buy Date: *September 30, 2019* Last Time Ship Date: *December 31, 2019* 

Should you have any questions or need additional information, please feel free to contact <u>Customer Service/Inside</u> <u>Sales</u>.

MF1934