



Initial Product/Process Change Notification

Document #: IPCN24751X1

Issue Date: 08 Aug 2022

| Title of Change: | Update to IPCN24751X: To inform customers that change to 0.8mil soft PCC wire will not be implemented for the list of products below. | | | | | | | |
|--|--|-----------------------------|--|---------------------------|--------------------------|-----------|-----------------------------|-----------------------------|
| Proposed First Ship date: | 08 Aug 2022 or earlier if approved by customer | | | | | | | |
| Contact Information: | Contact your local onsemi Sales Office or Gretel.Ines@onsemi.com | | | | | | | |
| PCN Samples Contact: | Contact your local onsemi Sales Office. Sample requests are to be submitted no later than 30 days from the date of first notification, Initial PCN or Final PCN, for this change. Samples delivery timing will be subject to request date, sample quantity and special customer packing/label requirements. | | | | | | | |
| Type of Notification: | This is an Initial Product/Process Change Notification (IPCN) sent to customers. An IPCN is an advance notification about an upcoming change and contains general information regarding the change details and devices affected. It also contains the preliminary reliability qualification plan. The completed qualification and characterization data will be included in the Final Product/Process Change Notification (FPCN). This IPCN notification will be followed by a Final Product/Process Change Notification (FPCN) at least 90 days prior to implementation of the change. In case of questions, contact < PCN.Support@onsemi.com > | | | | | | | |
| Marking of Parts/ Traceability of Change: | There will be no change on product marking. | | | | | | | |
| Change Category: | Assembly Change | | | | | | | |
| Change Sub-Category(s): | Material Change | | | | | | | |
| Sites Affected: | | | | | | | | |
| onsemi Sites | External Foundry/Subcon Sites | | | | | | | |
| onsemi Carmona, Philippines | None | | | | | | | |
| Description and Purpose: | | | | | | | | |
| <p>This update notification is to inform the customers that the define change in IPCN24751X (Qualification of Tanaka 0.8mil Soft PCC wire) for products mentioned in List of Affected Parts will no longer take effect, so as below.</p> <p>Heraeus 0.8mil bare copper wire will be used which is the same as what is being used.</p> <table border="1" data-bbox="125 1465 1531 1591"> <thead> <tr> <th></th> <th>Before Change Description</th> <th>After Change Description</th> </tr> </thead> <tbody> <tr> <td>Bond Wire</td> <td>Heraeus 0.8 mil Bare Copper</td> <td>Heraeus 0.8 mil Bare Copper</td> </tr> </tbody> </table> | | | | Before Change Description | After Change Description | Bond Wire | Heraeus 0.8 mil Bare Copper | Heraeus 0.8 mil Bare Copper |
| | Before Change Description | After Change Description | | | | | | |
| Bond Wire | Heraeus 0.8 mil Bare Copper | Heraeus 0.8 mil Bare Copper | | | | | | |
| There is no product marking change. | | | | | | | | |
| Qualification Plan: | | | | | | | | |
| Not applicable. | | | | | | | | |



Initial Product/Process Change Notification

Document #: IPCN24751X1

Issue Date: 08 Aug 2022

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

| Part Number | Qualification Vehicle |
|------------------|------------------------------------|
| MC74HC373ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4094ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4538ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC597ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT365ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT374ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74VHC4052DTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4066ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74LV594ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4060ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT125ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC20ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC573ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT244ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC00ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT04ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC02ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC595ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4053ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74VHC4053DTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4051ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4052ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74VHC4051DTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4051ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC595ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT595ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4851ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC374ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC273ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |



Initial Product/Process Change Notification

Document #: IPCN24751X1

Issue Date: 08 Aug 2022

| | |
|------------------|------------------------------------|
| MC74HC365ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC393ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT14ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT574ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4852ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC04ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4040ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC11ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC32ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| NLHV4051DTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4046BDTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC373ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC273ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT245ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC10ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC30ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT132ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT20ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCU04ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT259ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT138ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4020ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC112ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC163ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4094ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74VHC4066DTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT4051ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4052ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4053ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4066ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4851ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| M74HCT4852ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC03ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC160ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |



Initial Product/Process Change Notification

Document #: IPCN24751X1

Issue Date: 08 Aug 2022

| | |
|------------------|------------------------------------|
| MC74HC589ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC574ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC573ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC541ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC541ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC540ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT86ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT595ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT573ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT541ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT373ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT366ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT32ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT273ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT245ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT241ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HCT241ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC86ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC73ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC4051ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC390ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC377ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC367ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC259ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC05ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC05ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC139ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC157ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC161ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC161ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC163ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC368ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC251ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC251ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |



Initial Product/Process Change Notification

Document #: IPCN24751X1

Issue Date: 08 Aug 2022

| | |
|-----------------|------------------------------------|
| MC74HC245ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC245ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC244ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC244ADTG | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC240ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC238ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC175ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC174ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC165ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |
| MC74HC164ADTR2G | NLV74HCT4051ADTR2G/NLVHC4851ADTR2G |

Appendix A: Changed Products

DIKG: DIGI-KEY (page 1 of 2)

| Product | Customer Part Number | Qualification Vehicle | New Part Number | Replacement Supplier |
|------------------|----------------------|------------------------------|-----------------|----------------------|
| MC74HC373ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC597ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT365ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT374ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74VHC4052DTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4066ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74LV594ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4060ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT125ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC20ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC573ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT244ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC00ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT04ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC02ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC595ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4053ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4094ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74VHC4053DTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| M74HCT4051ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4052ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74VHC4051DTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4051ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4538ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT595ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC595ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC273ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4851ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC365ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC374ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT14ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC393ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4852ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT574ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4040ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC04ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC373ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC32ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT245ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC30ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC273ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT259ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT132ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT138ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC04ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC163ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74VHC4066DTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4020ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| M74HCT4052ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT4051ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC03ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC574ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC589ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC541ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC541ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC573ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT86ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC540ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT541ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT595ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |

Appendix A: Changed Products

PCN#: IPCN24751X1
Issue Date: Aug 08, 2022

DIKG: DIGI-KEY (page 2 of 2)

| Product | Customer Part Number | Qualification Vehicle | New Part Number | Replacement Supplier |
|------------------|----------------------|------------------------------|-----------------|----------------------|
| MC74HCT273ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT573ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT245ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC86ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HCT241ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC390ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC73ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC259ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC4051ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC139ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC05ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC157ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC251ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC161ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC245ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC245ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC244ADTG | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC244ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC238ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC240ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC165ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC175ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC164ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |
| MC74HC174ADTR2G | | NLV74HCT4051ADTR2G/NLVHC4851 | ADTR2G | |