



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001079

DATE: 01-Aug-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS21372T+	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX15005AAUE/V+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX15005AAUE/V+T	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX256ASA/V+	MAX256ASA+	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX256ASA/V+T	MAX256ASA+T	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX406BCPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX410CPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX410EPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX492CPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX494EPD+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX77752AETL+	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752AETL+T	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752BETL+	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752BETL+T	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752CETL+	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752CETL+T	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752DETL+	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX77752DETL+T	N/A	01-Aug-2022	28-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX942CPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX942EPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX951EPA+	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX96753FGT/V+CTH	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX96753FGT/V+TCTH	N/A	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX98372EWW+	MAX98396EWB+T	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX98372EWW+T	MAX98396EWB+T	01-Aug-2023	28-Jan-2024	Part can no longer be manufactured
Discontinuance	PM20S-020-124	N/A	01-Aug-2022	01-Aug-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 01-Sep-2022

Discontinuance	PM25S-048-314	N/A	01-Aug-2022	01-Aug-2022	Part can no longer be manufactured
Discontinuance	PM35S-048-324F	N/A	31-Jan-2023	31-Jan-2023	Part can no longer be manufactured
Discontinuance	PM42L-048-285D	N/A	31-Jan-2023	31-Jan-2023	Part can no longer be manufactured
Discontinuance	TMC2300-MOTOR-EVAL	TMC2300-EVAL-KIT	31-Jan-2023	31-Jan-2023	Part can no longer be manufactured
Discontinuance	TMC2300-THERMO-BOB	TMC2300-EVAL-KIT	31-Jan-2023	31-Jan-2023	Part can no longer be manufactured
Discontinuance	TMC4671+TMC6100-	N/A	31-Jan-2023	31-Jan-2023	The eval kit is no longer supported
Discontinuance	TMC4671-TOSV-REF	N/A	31-Jan-2023	31-Jan-2023	The eval kit is no longer supported
Discontinuance	TMC8461-BA	TMC8462A-BA	01-Aug-2022	01-Aug-2022	Part can no longer be manufactured
Discontinuance	TMC8461-EVAL	TMC8462A-EVAL	31-Jan-2023	31-Jan-2023	Part can no longer be manufactured
Discontinuance	TMC8670-BI	TMC4671-LA	01-Aug-2022	01-Aug-2022	Part can no longer be manufactured
Discontinuance	TMC8670-EVAL	TMC4671-EVAL	01-Aug-2022	01-Aug-2022	Part can no longer be manufactured
Discontinuance	TMCM-4112-SH V1.1	N/A	01-Aug-2022	01-Aug-2022	Part can no longer be manufactured