



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000797

DATE: 27-Feb-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX394MJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Reactivation	MAX17023BAUI/V+T	MAX17023CAUI/V+T			Reactivation
Reactivation	MAX17023BAUI/V+	MAX17023CAUI/V+			Reactivation
Reactivation	DS3905U-020+	N/A			Reactivation
Reactivation	MAX7461EUK+T	N/A			Reactivation
Reactivation	MAX7461EUK+TC45	N/A			Reactivation
Reactivation	MAX7461EUK+	N/A			Reactivation
Reactivation	MAX7461EUK+C45	N/A			Reactivation
Reactivation	MAX7461EUK+TG071	N/A			Reactivation
Reactivation	MAX7461EUK+TG05	N/A			Reactivation
Reactivation	MAX7461EUK+G05	N/A			Reactivation
Reactivation	MAX7461EUK+G071	N/A			Reactivation
Reactivation	DS3905U-020+T&R	N/A			Reactivation
Discontinuance	MAX4027EUD+	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7224TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX230MJP/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX333MJP/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX529MJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-9318001MRA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7225UQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7581TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7628TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7535SQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7548BQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX238MRG	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX7326ATG+	MAX7325ATG+	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 30-Mar-2015

Discontinuance	MAX44245AUD+	MAX44267AUD+	30-Aug-2015	29-Aug-2017	The part was not released
Discontinuance	MAX44247AUA+	MAX44267AUD+	27-Feb-2015	27-Feb-2017	The part was not released
Discontinuance	MAX44247EVKIT#	MAX44267EVKIT#	27-Feb-2015	27-Feb-2017	The part was not released
Discontinuance	MAX1441EVSYS+	N/A	27-Feb-2015	27-Feb-2017	The eval kit is no longer supported
Discontinuance	MAX7328AAP+	MAX7323AEE+	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX7328AAP+T	MAX7323AEE+T	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX186DMJP/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7541ASQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX236ERG	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX7365EWA70+	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7541BQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7528TQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX11288EWX+	N/A	30-Aug-2015	29-Aug-2017	The part was not released
Discontinuance	MX7820TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7541ABQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX186AMJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8948102VA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7226TQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX186AMJP-C01051	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG506AAK	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG528AK/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8770102RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7521UQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7548SQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7541ATQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX333AMJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX242MJN/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	IH5352MJE/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG529AK/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8770204RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-9456504MVA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG507AAK	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX222MJN	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX306MJI	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7224UQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7545TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 30-Mar-2015

Discontinuance	MX7820UQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8865002RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX395MRG	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX236MRG	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX238ERG	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX7365EVKIT#	N/A	27-Feb-2015	27-Feb-2017	Part can no longer be manufactured
Discontinuance	MAX7365EWA70+T	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8770201RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG406AK	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG528AK	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7541SQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7536SQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX242MJN	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-9455602MEA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX11288EWX+T	N/A	30-Aug-2015	29-Aug-2017	The part was not released
Discontinuance	5962-8770203RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7225TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7581SQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7528UQ/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7548TQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX188CMJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8780201RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7545UQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX222MJN/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX333MJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8768901VA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-9456502MVA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	DG506ACK	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	5962-8770103RA	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MX7226BQ	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX230MJP	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX88922EFD+	MAX88922AEFD+	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX88922EFD+T	MAX88922AEFD+T	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured
Discontinuance	MAX310MJE/883B	N/A	30-Aug-2015	29-Aug-2017	Part can no longer be manufactured