

PCN Number:	20160408000	PCN Date:	04/13/2016
Title:	Datasheet for TLC2272/TLC2272A/TLC2272M/TLC2272AM TLC2274/TLC2274A/TLC2274M/TLC2274AM		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:	<input type="checkbox"/> Assembly Site <input type="checkbox"/> Assembly Process <input type="checkbox"/> Assembly Materials <input type="checkbox"/> Mechanical Specification <input type="checkbox"/> Packing/Shipping/Labeling <input type="checkbox"/> Design <input checked="" type="checkbox"/> Data Sheet <input type="checkbox"/> Part number change <input type="checkbox"/> Test Site <input type="checkbox"/> Test Process <input type="checkbox"/> Wafer Bump Site <input type="checkbox"/> Wafer Bump Material <input type="checkbox"/> Wafer Bump Process <input type="checkbox"/> Wafer Fab Site <input type="checkbox"/> Wafer Fab Materials <input type="checkbox"/> Wafer Fab Process		

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification.
The product datasheet(s) is updated as seen in the change revision history below:



TLC2272, TLC2272A, TLC2272M, TLC2272AM
TLC2274, TLC2274A, TLC2274M, TLC2274AM

SLOS190H – FEBRUARY 1997 – REVISED MARCH 2016

www.ti.com

Changes from Revision G (May 2004) to Revision H

Page

- Added Feature Description section, Device Functional Modes, Application and Implementation section, Power Supply Recommendations section, Layout section, Device and Documentation Support section, and Mechanical, Packaging, and Orderable Information section. 1
- Added ESD Rating table for the D and PW package devices. 5

Device Family	Change From:	Change To:
TLC2272/TLC2272A/TLC2272M/TLC2272AM TLC2274/TLC2274A/TLC2274M/TLC2274AM	SLOS190G	SLOS190H

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/tlc2272>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TLC2272AMD	TLC2272MD	TLC2274AMDG4	TLC2274MDR
TLC2272AMDG4	TLC2272MDG4	TLC2274AMDRG4	TLC2274MDRG4
TLC2272AMDR	TLC2272MDR	TLC2274AQD	TLC2274MN
TLC2272AMDRG4	TLC2272MDRG4	TLC2274AQDG4	TLC2274QD
TLC2272AQD	TLC2272QDG4	TLC2274AQDR	TLC2274QDG4
TLC2272AQDG4	TLC2272QDR	TLC2274AQDRG4	TLC2274QDRG4
TLC2272AQDR	TLC2272QPWRG4	TLC2274MD	
TLC2272AQDRG4	TLC2274AMD	TLC2274MDG4	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com