



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001034

DATE: 08-Apr-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX77759EWN+	MAX77759AEWN+	08-Apr-2021	05-Oct-2021	Part can no longer be manufactured
Discontinuance	MAX77759EWN+T	N/A	08-Apr-2021	05-Oct-2021	Part can no longer be manufactured
Discontinuance	VT1156SAFQX	N/A	08-Apr-2022	05-Oct-2022	Part can no longer be manufactured
Discontinuance	VT1157SAFQX	N/A	08-Apr-2022	05-Oct-2022	Part can no longer be manufactured
Discontinuance	VT1193SAFQX	N/A	08-Apr-2022	05-Oct-2022	Part can no longer be manufactured
Discontinuance	VT1656SAFQ	N/A	08-Apr-2022	05-Oct-2022	Part can no longer be manufactured
Discontinuance	VT1656SAFQX	N/A	08-Apr-2022	05-Oct-2022	Part can no longer be manufactured
Discontinuance	VT1676SBFQX+CM6	N/A	08-Apr-2022	05-Oct-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 09-May-2021