Amphenol

Production Change Note

Code: TS0201D-202103-00			page : 1/1	
Customer :	All customers	Date	2021/Mar/22	
Change Items :	AMPHENOL marking will be added on shell instead of housing surface.			
Change Reason :	Since both PBT and PA9T plastic mold with Amphenol logo were worn out,			
	the shared tooling without logo is to step in as replacement instead. The only			
	different of molding tools is with or without Amphenol logo.			
Change Range :	L17HTNXXXXXX, *SD*A4*, Right Angle, Military Footprint, Male and Female			
Before Change:		After Change:		
"AMPHENOL" marking on housing surface.		AMPHEN	AMPHENOL marking will be added on shell instead of	
		housing surface		
AMPHEN	IOL D			
			AMPHENOL marking vill be added on shell	
Approved by : Tony	Prepared by :	Bella	Date: 2021/Mar/12	
Reply by Customer:				
	_			
Approved by: Date:				
Remarks: Please confirm within three days in order to offer you the better products.				
Amphenol will do the change after your approval.				