

Product Change Notification

TE Connectivity

Product Change Notification: E-17-009865 PCN Date: 10-JUL-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMPLIMITE Crimp Contacts and TE product using them

Description of Changes

Increasing internal manufacturing capacity for AMPLIMITE, size 20 Crimp Pin and Socket Contacts. Specifically, TE PNs 205089-1 (AS39029/64-369), 205089-4 (NASA G-10-P1) and 205090-1 (AS39029/63-368). Previous notification completed for part numbers 205090-1, 205089-1, 4 on P-17-014333. Previous notification completed for part number 204370-2 on P-17-014090.

Reason for Changes:

Manufacturing / Process Requirements. TE Connectivity is adding additional internal capacity in other TE facilities in anticipation of increased demand. This product will continue to conform to AS39029 and NASA S-311-P-4/09 specifications. Agency notifications to NAVAIR and NASA are in process. Parts affected include AMPLIMITE Connector Kits and Assemblies, LGH Connectors, and PNP Cable Assemblies which use these contacts.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

01-AUG-2017

Last Ship Date (Obsolete Parts Only):

No Mixed Shipments: (Changed Parts Only):

Part Number(s) being Modified:

Part Number	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
	per PCN	Drawing	Number		Number	Part Number(s)	Difference
<u> 204351-1</u>	NO			"CJ9840-000", "AMP-0-0204351-1"			
204370-2	NO			"CJ8670-000", "AMP-0-0204370-2"			
<u>204370-8</u>	NO						
205089-1	NO		A2160-ND	"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
205089-4	NO						
205090-1	NO		A2161-ND	"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211- 7507"			

Part Number(s) being Modified:

· · · · · · · · · · · · · · · · · ·												
Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of					
Number	per PCN	Drawing	Number		Number	Part Number(s)	Difference					
204351-1	NO			"CJ9840-000", "AMP-0-0204351-1"								
204370-2	NO			"CJ8670-000", "AMP-0-0204370-2"								
204370-8	NO											
205089-1	NO		IA216()-NII)	"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"								
205089-4	NO											
205090-1	NO		IA2161-NII)	"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"								