

## **Product Discontinuation Notice**

## Purpose

We would like to notify customers that the following Sharp part numbers will be discontinued for sale in North America. The reason is that the parts are manufactured in an old production facility with no remaining Sharp engineers to provide technical support.

Sharp P/N	Reason for Discontinuation
GL100MN0MP1	No Engineers & Old production facility
GL100MN1MP1	No Engineers & Old production facility
GL480E00000F	No Engineers & Old production facility
IS471FE	No Engineers & Old production facility
IS485E	No Engineers & Old production facility
IS486E	No Engineers & Old production facility
PD100MC0MP1	No Engineers & Old production facility
PD413PI2E00F	No Engineers & Old production facility

## Effective Date

This change is effective April 4, 2019.

If you have any questions concerning this notification, please contact your Socle representatives at: <a href="mailto:Socle-see">Socle Sales NA@socle-tech.com</a>