PCN Number:	mber: 20170731001 PCN Date: August 02, 2017		2017					
Title: Datasheet for	SN74AUP1G80	· · ·						
Customer Contact:	CN Manager		D	Dept:		Quality Services		
Change Type:						-		
Assembly Site		Design				Wafer	Bump Site	
		Data Sheet					Bump Material	
Assembly Materials			er change				Bump Process	
		Fest Site				Wafer	Fab Site	
Packing/Shipping/La					Wafer	Fab Materials		
						Wafer	Fab Process	
Notification Details								
Description of Change:								
Texas Instruments Incorporated is announcing an information only notification.								
The product datasheet(s				٧.				
The following change history provides further details.								
TEXAS								
TEXAS INSTRUMENTS							SN74AUP1G80	
				SC	CES	593F – JULY	2004-REVISED JULY 2017	
Changes from Revision E (Ma	y 2010) to Revision F						Page	
Added DPW (X2SON) packs	age preview only						1	
	• • •							
<ul> <li>Added Device Information table, Pin Configuration and Functions section, ESD Ratings table, Thermal Information table, Feature Description section, Device Functional Modes, Application and Implementation section, Power Supply</li> </ul>								
Recommendations section, Layout section, Device and Documentation Support section, and Mechanical,								
Packaging, and Orderable Information section								
Deleted Ordering Information table, see Mechanical, Packaging, and Orderable Information at the end of the data sheet								
Added Junction temperature, T <sub>J</sub> in <i>Absolute Maximum Ratings</i> table								
The datasheet number v	vill be changing							
Device Family	Change From:			Change To:				
SN74AUP1G80		SCES593E			SCES593F			
These changes may be reviewed at the datasheet links provided.								
http://www.ti.com/product/SN74AUP1G80								
Reason for Change:								
To accurately reflect device characteristics.								
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):								
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.								
Changes to product identification resulting from this PCN:								
None.								
Product Affected:								
PSN74AUP1G80DPWR	SN74AUP1G80D	BVR SN74AUP1G80D		DBV	RG	64 5	SN74AUP1G80DBVT	
SN74AUP1G80DBVTG4	SN74AUP1G80D	DCKR	KR SN74AUP1G80D		RE	4 5	SN74AUP1G80DCKRG4	
SN74AUP1G80DCKT	SN74AUP1G80D	OCKTG4 SN74AUP1G80D		DRYI	RYR SI		SN74AUP1G80DSFR	
SN74AUP1G80YFPR	SN74AUP1G80Y	ZPR						

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com