

Product Discontinuing Notification

1. PDN No.:	<i>PDN17015-1</i>
2. To:	<i>All involved customer</i>
3. Issued by:	<i>HQ (Headquarters) QA Sunnie Pan</i>
4. Issue date:	<i>2017/7/14</i>
5. Affected product/ product family:	6. Recommended replacement:
<i>See attached detailed Part-No. list.</i>	<i>See attached detailed Part-No. list.</i>
7. Reason for discontinuing:	
<i>EOL</i>	
8. Last time buy/ order entry:	<i>2018/7/13</i>
9. Last shipment date:	<i>2018/10/12</i>
10. Please let us know if you have any question/ comment:	
11. Customer feedback required latest: (should we receive no feedback, the change will be deemed as accepted!)	<i>2017/8/14</i>
12. Approved by:	<i>Owen Wang</i>

PDN17015-1_Involved P/N list

Family	Package	TSC P/N	New TSC P/N
2.495V Reference Voltage	SOP-8	TS431CS RLG	TS431ACS RLG
N-Channel	ITO-220	TSM10N60CI C0	TSM10NC60CF C0G
N-Channel	ITO-220	TSM10N60CI C0G	TSM10NC60CF C0G
N-Channel	ITO-220	TSM10NB60CI C0G	TSM10NC60CF C0G
N-Channel	ITO-220	TSM230N06CI C0G	None
N-Channel	ITO-220	TSM340N06CI C0G	None
N-Channel	SOP-8	TSM1N45DCS RL	None
N-Channel	TO-220	TSM10N60CZ C0	None
N-Channel	TO-220	TSM10N60CZ C0G	None
N-Channel	TO-220	TSM230N06CZ C0G	None
N-Channel	TO-220	TSM340N06CZ C0G	None
P-Channel	ITO-220	TSM22P10CI C0G	None
P-Channel	ITO-220	TSM480P06CI C0G	None
P-Channel	ITO-220	TSM680P06CI C0G	None
P-Channel	SOT-23	TSM2301CX RFG	TSM2301ACX RFG
P-Channel	SOT-23	TSM2311CX RFG	TSM500P02CX RFG
P-Channel	SOT-23	TSM2311CX-01 RFG	None
P-Channel	TO-220	TSM22P10CZ C0G	None
P-Channel	TO-220	TSM480P06CZ C0G	None
P-Channel	TO-220	TSM680P06CZ C0G	None

***** This document contains TSC business confidential information. Further distribution should not be made without TSC permission *****