



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000927I

DATE: 05-Jul-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	MAX130C/D	N/A	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1921EUT18	MAX1921EUT18+	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1921EUT30	MAX1921EUT30+	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5026EUT	MAX5026EUT+	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5401EKA-T	MAX5401EKA+T	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX6339AUT-T	MAX6339AUT+T	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX6370KA	MAX6370KA+	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MX7574J/D	N/A	05-Jul-2017	05-Jul-2017	Part is leaded. Request information on lead-free version
Discontinuance	DS1629S-C05+	DS1629S+	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	DS17885-3+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1833-10+T&R/STR	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1833-10+TRL/C01	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX104CHC	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX108CHC-WB50105	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX11044BETN+T	MAX11044ETN+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX11046BECB+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX1457KEY+	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX16087XS17H/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16087XS17H/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16132AKA/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16132AKA/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16132KA/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16132KA/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16133AKA/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16133AKA/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16134AKA/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Aug-2017

Discontinuance	MAX16134AKA/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135AKA/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135AKA/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135FNBA+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135FNBA+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135FNBA/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135FNBA/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135IDGB+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135IDGB+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135IDGB/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135IDGB/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135OIMB+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135OIMB+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135OIMB/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135OIMB/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135VGPC+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135VGPC+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135VGPC/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16135VGPC/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16140A285KM+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16140A285KM+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16140G250IM+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16140G250IM+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16140G355KM+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16140G355KM+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16920AATJ/V+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX16920AATJ/V+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX265ACWI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265ACWI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265AEWI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265AEWI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265BCPI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265BCWI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265BCWI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265BEPI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX265BEWI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Aug-2017

Discontinuance	MAX266BCPI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX266BCWI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX266BCWI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX266BEPI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX266BEWI+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX266BEWI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX31875PMB#	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX38902AETA+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX38902BETA+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX38902CENT+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX38902CENT+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX38902DENT+	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX38902DENT+T	N/A	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX4090EUT+G51	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5702AATB+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5704ATB+T	MAX5705BATB+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5715AUD+	MAX5715BAUD+	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5800ATB+	MAX5802BATB+	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5800ATB+T	MAX5802BATB+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5801ATB+T	MAX5802BATB+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5802AATB+	MAX5802BATB+	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5802AATB+T	MAX5802BATB+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5803ATA+	MAX5805BATB+	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5803ATA+T	MAX5805BATB+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5803ATB+T	MAX5805BATB+T	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX5815AUD+	MAX5815BAUD+	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX6931AUI+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX7432EUD/GG8	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX8685AETD+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9539/40EVKIT+	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX9539EVKIT+	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX9665ETP+T	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9665EVKIT+	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX9673ETI+G0E	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9775EVKIT+	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX98096AEVKIT#	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Aug-2017

Discontinuance	MAX98373ENA+	MAX98373EWA+	05-Jul-2017	05-Jul-2017	The part was not released
Discontinuance	MAX98705DEV#	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAX9880EVKIT+	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	MAXREFDES150HDK#	N/A	05-Jul-2017	05-Jul-2017	EVKIT is No Longer Supported
Discontinuance	SD220+	N/A	05-Jul-2017	05-Jul-2017	Part can no longer be manufactured