



Product Change Notification / NTDO-19HYTI032

Date:

26-Oct-2021

PCN Type:

Manufacturing Change

Notification Subject:

CCB 4652 Final Notice: Implement Microchip Aging Policy, Combination rules, Packing Materials and Labels, Shipping Materials, Labels and Documentation Changes for selected Microsemi VOP-MHS, VOP-NBH and RFSP-TLT products.

Notification Text:

PCN Status: Final notification.

PCN Type: Manufacturing Change

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

Description of Change:Implement Microchip Aging Policy, Combination rules, Packing Materials and Labels, Shipping Materials, Labels and Documentation Changes for selected Microsemi VOP-MHS, VOP-NBH and RFSP-TLT products.

Pre and Post Change Summary:NOTE: See attached Packing Pre and Post Changes for the changes of the following.

Details	PRE-CHANGE (Microsemi)	POST CHANGE (Microchip)
Aging Policy	No age limit with shipment of products. Anything older than 6 months, with solder dipped leads will be subjected to re-tinning/solderability testing.	<ul style="list-style-type: none">No change For more information related to Microchip's part aging strategy please visit the following link on

		Anything older than 12 months must be retested at room ambient temperature prior to shipment.	our website. Please visit the following link on our website: Component Age Policy
Combination rules	Tube	<ul style="list-style-type: none"> ▪ 1 device type per tube. ▪ multiple date codes permitted, unless specified otherwise by customer. ▪ No limit to number of production lots, unless specified otherwise by customer 	Keep existing rules. No change.
	Tape and Reel	<ul style="list-style-type: none"> • 1 device type per tube. • multiple date codes permitted, unless specified otherwise by customer. • No limit to number of production lots, unless specified otherwise by customer • For VOP-NBH - Max 2 Date codes per reel 	Keep existing rules. No change.
Reel/Bag/Inner/Outer Carton Label		Microsemi Branded labels	Microchip Branded labels
Packing Material	Refer to Pre and Post Change summary for complete details		
Packing Method	Refer to Pre and Post Change summary for complete details		
Packing list	Microsemi format with Microchip logo	Microchip format with Microchip logo	
Commercial Invoice	Microsemi format with Microchip logo	Microchip format with Microchip logo	
CoC document	Microsemi format with Microchip logo	Microchip format with Microchip logo	

Impacts to Data Sheet: None

Change Impact:None

Reason for Change:To improve productivity by standardizing the packing method as part of the

integration of Microsemi and Microchip.

Change Implementation Status:In Progress

Estimated Implementation Date:

December 1, 2021 (date code: 2149)

Note: The earliest implementation date is the earliest date that we may implement any combination of the changes listed in this PCN as we will not implement any of the proposed changes prior to this date. After the earliest implementation date these changes may occur to any product over the course of many months depending on inventory levels and business conditions.

Time Table Summary:

	October 2021					December 2021				
Workweek	40	41	42	43	44	49	50	51	52	1
Final PCN Issue Date				X						
Estimated Implementation Date						X				

Method to Identify Change: Traceability, label, inner and outer boxes

Contact Microchip:You may contact your local **Microchip Sales and Distribution**. Contact information is also provided on the attached Frequently Asked Questions (FAQ).

If applicable, please also copy your local Microchip field sales and/or field quality representative.

Revision History:

October 26, 2021 Issued final notification. Provided estimated ship date to be December 01, 2021.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachments:

[PCN NTDO-19HYTI032_Pre and Post Change Comparison.pdf](#)

[PCN_NTDO-19HYTI032_Affected CPN.pdf](#)

[PCN_NTDO-19HYTI032_Affected CPN.xlsx](#)

[Frequently Asked Questions Microsemi updated December Version.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

PCN_NTDO-19HYTI032
Affected CPN list
1108R12M00000AS
2205R20M00000TAS
VC-840-1039-25M0000000
C4400A1-0061-16M384
FX-102-DFF-S6071G
VS-751-LFF-HNN-P2-R5
VS-751-LFF-GNN-P2-P4
VS-500-LFF-GNN-693M483000
FX-424-DFF-S6118G
VC-501-DFF-GFM-112M000000
VTC1-J01E-10M0000000
FX-500-LAF-NNK-A3-E6
VCC1-B3F-25M0000000
VS-500-KEF-GNN-622M080000
C2260A1-0153-26M2144
VCC1-B2D-25M0000000
TRU050-GALGA-12M6240000
MC741A1-1300_SNPB
TC-350-DAC-106A-80M0000000
STFHLA-32M0000000
VDUNLB-25M0000000
TFS71C
0950BTXX30M0000
0428BCXB40M0000
7411ABX10M00000
TRU050-GCLCA-51M8400000
TRU050-TALGA-16M8960000
6006
C4550B2-0048
C4998A1-0020
TRU050-GACGB-16M3840000
TRU050-GBLHA-20M0000000
1105D80M26000BX
M55310/26-B62A64M000000
TRU050-GCCGB-32M7680000
TRU050-GALGB-16M8960000
CO-484A-0XR-13.56MHZ
CO-449A-2B-64MHZ
VDUNLB-40M0000000
VCC1-A2D-20M0000000
EX-385-DAF-ST3G-12M8000000
MC929X2-037E
M55310/27-B01A2M0000000
SGSFLS-19M4400000
M55310/16-B31A20M000000

PCN_NTDO-19HYTI032
Affected CPN list
252-6160-8.247423MHZ
1116R33M00000AF
MC044X5-202
CO-447A-7B-5.5296MHZ
0336CCE25M00000
CO-401D-1X-87.9709MHZ
487Y4525-31.1125MHZ
1105R04M00000AF
454Y4745-1-200MHZ
454Y6181-160MHZ
1110R5M357600AF
C1250A1-0206_SNPB
C2501A1-0025
233Y5262-50MHZ
C1300A1-0149
C1460A1-0019
C4550A2-0146-10M0000000
MC704A1-016
C4998A1-0016
JCMGCMEP-155.52MHZ
C1250A1-0096
M55310/19-B01A12M500000
CO-402C-2B-25.000MHZ
M55310/16-B41A29M491200
TC-400-CGF-156C-29M9100000
1105R24M00000AF
C1300B1-0193
C1250B1-0042_SNPB
EX-380-DAF-ST3F-12M8000000
CO-446V-BX-20.460MHZ
CO-441A-1X-25MHZ
CO-406B-0X-16MHZ
CO-441A-1X-6.9MHZ
CO-449A-2X-8MHZ
MC348X5-028
C6999A1-0001
0429ACXB32M0000
0426CCX08M00000
C1370A1-0010
C1250B1-0231_SNPB
5116R50M00000BF
C1460B1-0005
403-6186-1-8MHZ
MC741A1-996
MC6035X4-001W

PCN_NTDO-19HYTI032
Affected CPN list
C4408A1-0017
CO-231V-0-1.151075MHZ
408-5769-40MHZ
C6998A1-0013
C4600A1-0021-5M00000000
MC997X1-002W_SNPB
1110R5M320960AF
EX-380-DAF-107A-11M6800000
CO-401E-7B-20.000MHZ
1104X24M00000AX
C2620A1-0031
1116C8M000000BB
0921CBX32M00000
C4710C1-0022-10M0000000
8006-5MHz
M55310/21-B21B50M000000
MC044X5-121
0950BX64M000000_SNPB
566Y5269-16.777216_MHZ
C4710C1-0023-10M0000000
EX-381-DHF-107A-11M6800000
C1405A1-0038
MC853X4-046W
TC-210-DFF-106A-27M0000000
0429DCEX80M0000
PCL1-21-19-70
CO-434B-2B-240MHZ
JDUGLMEP-100MHZ
CO-449A-1X-39.988MHZ
MC958X2-019W
0953BX32M000000
MC061A1-101
566Y5269-GB2EM
MC597X4-016W
MC741A1-1363
MC704A1-017
566Y5269-20 MHZ
CO-401B-2X-497.664KHZ
C2560A1-0055
M55310/16-B34A11M059000
XO-500-DFC-205E-173.3707MHZ
MC070-267
CO-448A-7X-10MHZ
MC623X2-061E
M55310/26-B53B40M000000

PCN_NTDO-19HYTI032
Affected CPN list
CO-402A-2B-40MHZ
457Y1945-6-600MHZ
CO-401B-2B-17.2414MHZ
C5250A1-0023
MC622X2-009
C1250A1-0115
MC623X2-055H
1105D32M00000BX
M55310/19-B11A25M000000
OC-160-BKS-S5946-10MHZ
C1300A1-0015
CO-446V-KX-12.352MHZ
MC877X4-003W
M55310/26-B37C6M0000000
EX-381-CGS-S6090-12.8MHZ
C1250A1-0055_SNPB
MC973X1-003
CO-718SA28-10MHZ
MC704A1-011
0429ACXB25M0000_SNPB
MC728A1-054
233Y5262-40MHZ
CO-402B-2X-358.400KHZ
C1460A1-0016
JDUGLMEP-125MHZ
6268
0427BTEX20M0000
566Y5724-40.00_MHZ
6328
1104R24M00000AA
1104R16M00000AF
0426CCEX32M00000
CO-446A-2X-16MHZ_SNPB
CO-406C-2B-40MHZ
1110R5M321760AF
718Y4373-3.2MHZ
XO-500-SFC-S5921-20MHZ
JDUGLMUS-155.52MHZ
MC929X2-032S
217-4530-12.352MHZ
401Y5224-22.06896MHZ
MC2001X4-006W
XO-500-DFC-205E-167.3316MHZ
7419BX20M000000
M55310/16-B41A32M00000

PCN_NTDO-19HYTI032
Affected CPN list
1116D60M00000BX
566Y5936-104.7500MHZ
C1405A1-0022
CO-448A-2B20MHZ
CO-770H27-10MHZ
0429ATEB40M0000
EX-380-DAD-S5843-19.44MHZ
8537-10MHZ
C1300A1-0025
M55310/16-B44A32M00000
CO-402B-2X-331.776KHZ
C6998A1-0035
MC091A1-090S
1104R24M00000AX
MC623X2-060S
XO-500-DFC-505E-161.1328MHZ
441-9999A-7X-32MHZ
0429ATEX30M0000_SNPB
3425DCXX59M0000
CO-484V-MB-70MHZ
1116C24M00000BX
252-8034-9.9MHZ
403Y1090-24MHZ
432Y2109-26.049MHZ_SNPB
CO-426A-1X-153.6KHZ
C1250A1-0067_SNPB
700Y5064-1-120MHZ
CO-401B-2X-560.853KHZ
C1250A1-0106_SNPB
1110R5M393206AF
M55310/21-B01A1M230000
0426CCXX12M0000_SNPB
6622-10MHZ
MC032X1-025
0429CCXB20M0000_SNPB
MC061A1-024_SNPB
356CC020M000000R6
MC091A1-088E
0426CCXX12M00000
MC091A1-088S
566Y6146-269.5833MHZ
M55310/28-B04A8M0000000
MC623X2-030H
7481AX28M000000
CO-442-9X-15.876MHZ

PCN_NTDO-19HYTI032
Affected CPN list
6574-12.8MHZ
1110R5M393056AF
C4550A1-0127-10M0000000
CO-448A-2B-2.4576MHZ
253Y4543-65MHZ
C5300B1-0034
M55310/16-B41A33M330000
EX-380-CAF-207A-10M0000000
XO-500-DFC-505E-41.67MHZ
1103C32M00000BX
C1250B1-0232
1104R48M00000AA
0428BCXB32M0000
JDUGCMUP-99.84MHZ
C2570A1-0002
446Y4578-13.5MHZ
TC-350-DAC-507A-27M0000000
0429ACXB16M0000
0751AB03M686400
CO-441A-2B-40MHZ
1105R02M00000AE
C1250A1-0222_SNPB
C2570A1-0010
484Y4921-1-60MHZ
0611AX24M000000
441Y5340-300KHZ
1116R36M00000BF
M55310/16-B31A12M00000
1113R24M00000BF
TC-350-CAF-106A-70M0000000
CO-446A-7X-16MHZ
MC095-049E
407Y5363-13.33MHZ
MC6021X4-004W
566Y3890-2-35.507812MHZ
6620-20.48MHZ
MC046X5-017
MC623X2-038W
TC-210-DFC-S5711-100MHZ
CO-402D-2X-2.461540
487Y4981-187MHZ
402Y0828-20MHZ
MC623X2-050H
MC042X1-113
MC047X5-025_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
C2400A3-0023
JN00158-163.84MHZ
C1300A1-0020
1103C33M00000BX
CO-401B-2B-14.7456MHZ
M55310/28-B01A14M745600
XO-400-DFC-C-155.52M
CO-285W-1-48MHZ
C2560A1-0077
C2560A1-0077
CO-448A-2B-16.0MHZ
623CB33M55443BN
MC091A1-095
1108D16M00000AX
MC049X5-040
C1250A1-0175
C2525A1-0006
XO-400-DFC-C-125MHZ
CO-436B-5X-170.666667MHZ
TC-350-DAF-106A-10M0000000
1116R48M00000AF
MC741A1-1161
1116D80M00000BX
447Y5034-3.6864MHZ
437Y4251-3-540MHZ
C1300A1-0170
21B21A25M000000
C4998A1-0019
M55310/16-B41A40M000000
C1300A1-0052_SNPB
MC037X1-005
C5250B1-0071
C1520A1-0005
CO-252A58X-10MHZ
MC061A1-023_SNPB
0751AB12M500000
487Y4981-190MHZ
C5400B1-0021
0425DCXX10M0000
EX-385-DAD-ST3A-10M0000000
MC534X7-002W
EX-380-DAF-507F-62M5000000
CO-402A-0X-100MHZ
402Y5488-24MHZ
MC728A1-104

PCN_NTDO-19HYTI032
Affected CPN list
442Y1189-20MHZ
1101D4M000000BX
447Y5034-24MHZ
JCUGLMUP-92.16MHZ
TC-140-BKS-S5900-24.000MHZ
431Y4019-155.52MHZ
4598GD20M000000
MC348X5-039
C4710C1-0021-10M0000000
C2525A1-0009
C4550C1-0195-10M0000000
0335DCE22M00000
6664-12.8MHZ
233Y5497-155.52MHZ
CO-224D38WL2-100MHZ
CO-406A-0X-20MHZ
XO-500-DFC-205E-173.3708MHZ
EX-385-CAD-758A-10M0000000
7411BX40M000000
7226BCX20M00000
0429ATEX20M0000_SNPB
MC955X5-035W
487Y4981-193MHZ
0426CTE16M67000
3896-44.736MHZ
566Y3383-2-26.2144MHZ
M55310/28-B24A40M000000
0611AB48M000000
R5Y5625-2.048MHZ
C1250A1-0091
JDUGLMEP-155.52MHZ
0335DCE17M40000
0945BXX14M31800
1110R20M00000AF
MC728A1-035
TC-140-CBS-S5998-20.48MHZ
0429DCEX20M0000
1110R40M00000AF
C1250B1-0195_SNPB
CO-484A-1X-5.002MHZ
EX-240-CAS-S5597-11.68MHZ
1116R40M00000BF
M55310/26-B06A1M0000000
M55310/16-B24A5M0000000
1103R33M00000AD

PCN_NTDO-19HYTI032
Affected CPN list
TC-210-DFC-507A-64M0000000
0425DCEB37M5000_SNPB
233Y5375-155.52MHZ
0950BX40M000000
447Y5034-40MHZ
7411BX50M000000
MC092A1-004_SNPB
0427BTX20M00000
C2998A1-0007
0429ACEB20M00000
MC049X5-020_SNPB
457Y1613-512MHZ
0429ACXB08M8064
CO-402B-2B-16MHZ
CO-408A-2X-24MHZ
1104R02M45760AF
EX-380-CAD-107A-10M0000000
CO-406V-KX-10.24MHZ
233Y5350-155.52MHZ
MC959X2-014W
C2560A1-0080
MC623X2-026H
CO-427B-2B-1MHZ
CO-449C-1B-15.6672MHZ
CO-446A-1X-48MHZ
MC728A1-081
0425DTEX20M0000
CO-446C-2X-16MHZ
6755-12.8MHZ
1113D24M00000BX
CO-449A-2X-7.5MHZ
C5300B1-0032
0429CTXB16M0000
C1435A1-0001
1110R5M392256AF
1116R48M00000BF
1104R20M00000BE
EX-380-DAF-ST3F-20M0000000
CO-441D-2B-16MHZ
CO-402B-2X-10MHZ
MC717-070
XO-500-DFC-205E-155.52MHZ
C2555A1-0005
454Y1650-1-566MHZ
432Y2109-14.84375MHZ_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
231-2470-1-160KHZ
C1250A1-0118_SNPB
JDFCCMEP-156.25MHZ
JDMFLMUP213.333MHZ
C4550A2-0140-30M7200000
MC853X4-003W
MC091A1-063
MC061A1-107A
MC046X5-059_SNPB
MC095-048
CO-449A-1X-3.93216MHZ
C5570A1-0001
CO-442B-2B-32MHZ
CO-401A-7D-8MHZ
XO-500-DFF-505E-200MHZ
MC2001X4-001W
EX-380-DAF-107A-20M0000000
484Y6115-70MHZ
MC887X4-047W
M55310/16-B21A2M097152
C1250B1-0179_SNPB
C1250A1-0105
MC712-002H
1110R64M00000AD
CO-422A-7D-1.6MHZ
TC-400-CAF-S5807-10.00MHZ
C2570A1-0013
5504-34.4MHz
447Y5034-33.554432MHZ
OC-160-AJF-108DA-10MHZ
C4408A2-0018
566Y5677-8MHZ
MC093A1-008A
M55310/16-B34C10M000000
1105V60M00000BF
M55310/16-B31B10M000000
3895-34.368MHZ
1110R5M357800AF
TC-400-CBF-156A-115M200000
MC929X2-030H
441-9999A-2D-64MHZ
MC095-023
CO-286W-1000MHZ
623CA32M76800SN
C1250A1-0199

PCN_NTDO-19HYTI032
Affected CPN list
484Y3717-100MHZ
MC741A1-1326
623CJ24M00000RN
C5250A1-0019
0425DCEB33M0000_SNPB
CO-442A-1D-80MHZ
6088-3.6864MHZ
CO-406V-EX-32MHZ
M55310/26-B42C24M000000
C1640A1-0006
C2555A1-0018
C1250A1-0221_SNPB
EX-381-CHF-147A-10M0000000
1110R5M392656AF
C1250A1-0092
CO-441A-2B-16MHZ
441-9999A-7X-16MHZ
MC859X4-010W
5116R64M00000BF
1102R153K6000AF
XO-400-DFC-C-147.456MHZ
371Y1228-165MHZ
0426CCX24M00000
1102C20M00000BX
CO-441A-1X-32MHZ
M55310/26-B43A24M000000
C1250A1-0099
C5300B1-0033
568Y6205-6 (formed leads)
1111R34M00000AF
8026-1MHZ
0427BTEX25M0000
C1300A1-0008
566Y5783-10.01MHZ
MC720A1-033
C1250A1-0056_SNPB
M55310/26-B32A16M000000
MC928X2-002H
3428BCE20M00000
724Y4774-100MHZ
MC128A2-019W
6565-12.8MHZ
C1300A1-0035
0949CBX20M00000
441Y0866-1-2.4576MHZ_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
3255-1-22.068966MHZ_SNPB
EX-385-DAF-107A-20M0000000
6267-10MHZ
M55310/16-B41A24M000000
441Y1644-9.216MHZ
1105R18M43200AF
CO-441A-2B-12MHZ
CO-407A-2X-32MHZ
JDFCCMEP-167.332MHZ
CO-407C-0X-40MHZ
C1250A1-0009
CO-442B-2B-12.798MHZ
1116C40M00000BX
1104R24M00000AF
566Y3383-1-26.2144MHZ
MC032X1-027
8063-1MHZ
XO-500-DFC-205E-161.1328MHZ
C2560A1-0037
C2560A1-0037
449Y2724-75MHZ
446Y4578-16.384MHZ
8468-10MHZ
SO-502-CGF-S6153-480MHZ
MC623X2-058H
MC034X5-010
6589-2.580419MHZ
1104R10M00000AF
1102C80M00000BX
0618BX66M660000_SNPB
OSC91-87A
1111R4M096000AF
MC741A1-1325
6099-04
M55310/16-B31A8M0000000
CO-614V-J-155.52MHZ
MC704A1-015
448Y2428-50MHZ
0426CCXX16M00000
0426CTEB20M0000
623TJ48M00000SN
C1300A1-0183
568Y6205-7
959HBB025M60000
C1300B1-0058_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
T0581DY6MHZ
MC093A1-009A
CO-408A-2B-11.0592MHZ
0427BCXX32M0000
MC741A1-1340
M55310/21-B22C40M00000_SNPB
MC029X1-006
CRH1000B_diced_chip
568Y6240
MC042X1-101
MC061A1-186
M55310/19-B01A3M0625000
C1470A1-0017
253Y5659-150MHZ
MC440X7-005W
484Y1636-1-243MHZ
M55310/16-B31A16M384000
286Y4939-1250MHZ
MC2002X4-002W
447Y2666-3-12MHZ
441Y2103-7.5MHZ
CO-446A-1X-30MHZ
3422CCE003M6864
4087-34.368MHZ
MC091A1-058
C1250A1-0026_SNPB
7411BX16M000000
1105R40M00000AF
231-4501-1-10MHZ
CO-441E-2B-24MHZ
C1250A1-0017_SNPB
CO-406B-6X-40MHZ
C4408A1-0001
1110R5M356800AF
MC047X5-034
MC044X5-S011
C2400A2-0002
0429DCEX16M0000_SNPB
MC724A1-059
M55310/16-B11A1K5000000
0950BX25M000000
1103D24M00000AX
1116B01M00000BG
C1998A1-0001
MC044X5-138

PCN_NTDO-19HYTI032
Affected CPN list
CO-407A-7B-22.118MHZ
CO2155
TC-400-CAF-256A-8M87304700
OC-260-DAD-S5886-10MHZ
1104R40M00000AF
281Y3465-900HZ
TC-210-DFC-ST3A-77M7770000
725Y3127-1-32.768MHZ
448Y2428-12.5MHZ
TC-400-CAS-S5700-100MHZ
1116R32M00000BF
1104R10M00000AX
700Y1951-2-5MHZ/10MHZ
M55310/16-B41A54M000000
0425DCEB64M0000_SNPB
1111R08M19200AF
C1470A1-0018
CO-442A-2B-40MHZ
C1460A1-0009_SNPB
M55310/26-B07C32K768000
C5300A1-0020_SNPB
M55310/26-B32A20M000000
MC958X2-066W
JDUGCMEP-155.52MHZ
CO-431A-0X-124.320MHZ
MC623X2-054E
VS-502-DFF-GNN-640MHZ
402-5699-1-12MHZ
C4550A2-0125-10M0000000
1104R16M38400AF
C2500A1-0001
236-4743-1-3.2KHZ/12.8KHZ
6418
EX-385-DAF-S6150-20MHZ
352Y4514-709.3MHZ
623CL48M00000RN
M55310/16-B41A80M000000
1105R1M000000AF
1103R33M00000BF
OC-160-BAS-S5981-10MHZ
0335DCE14M74560_SNPB
TC-400-CAF-156A-70M0000000
1103R50M00000BD
0428DCEX15M3600
402Y1094-53.3334MHZ

PCN_NTDO-19HYTI032
Affected CPN list
C4710A2-0041-10M0000000
C5116A1-0001
3354-3.199884MHZ
C1250A1-0203_SNPB
1110R5M357200AF
TC-350-DAF-206A-19M2000000
MC853X4-031W
1110R12M00000AD
0425DCEB24M4000_SNPB
MC853X4-008W
CO-484A-1X-280MHZ
MC704A1-020
1105R32M00000AF
1104R56M00000AF
CO-406A-1X-24MHZ_SNPB
C1300A1-0031
1104D16M38400AX
1103V96M00000BE
441Y2525-32MHZ
CO-402C-2B-39.3216MHZ
TC-210-CAC-106A-65M5360000
EX-380-CAD-758A-50M0000000
MC066A1-021
M55310/16-B41A30M000000
MC728A1-033
C1300A1-0016_SNPB
3427ACEX12M0000
CO-406C-2B-32MHZ
1105R20M00000AF
CO-441A-1X-40MHZ
MC092A1-030
0429ACXB20M0000_SNPB
MC042X1-118
MC623X2-033W
CO-406A-7X-9.830MHZ
C5300A1-0002
M55310/16-B34B12M000000
MC721A1-010 (28.2624MHZ)
CO-441A-1X-18.432MHZ
CO-441D-2B-11.034482MH
1116R75M00000AF
M55310/19-B11A40M000000
1116R33M55442BF
CO-427B-2B-2.4576MHZ
C1250A1-0029_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
M55310/19-B21A48M000000
MC895X4-018W
CO-449A-1X-10KHZ
C1340A1-0006
MC741A1-1364
JDUFCMEP-245.76MHZ
C2400A3-0047
5885
MC959X2-024W
CO-441B-2B-16MHZ
XO-500-DFF-505E-156.25MHZ
1105R16M00000AF
6605-128MHZ
CO-449A-2B-66.66MHZ
3429ACXB14M31800
C1300A1-0197
JDUGCMUP-155.52MHZ
0421DCEX3M68640
M55310/26-B33A20M000000
VS-502-CJF-GNN-840-MHZ
3425DCX66M000000
XO-500-DFF-S6102-100MHZ
JCUGCMUP-139.264MHZ
MC597X4-029W
M55310/09-B11A10M000000
MC2001X4-004W
TC-400-DAH-S5572-80MHZ
1105R10M00000AF
C6998A1-0043
1623E32M00000EN
6558-40MHZ
CO-441D-2X-16.3636MHZ
C4408A2-0002
M55310/16-B24A1M6000000
C1435A1-0002
0425DCXX01M00000
CO-402B-2B-40MHZ
MC741A1-1361
EX-380-DAF-147A-10M0000000
MC741A1-085
M55310/21-B11B20M000000
MC906X5-017
SO-345-CJS-S6079-1000MHZ
MC1623X2-100E
CO-402A-0X-20.4672MHZ

PCN_NTDO-19HYTI032
Affected CPN list
C2525A1-0005
M55310/09-B05A3M6864000
283Y4985-720MHZ
EX-385-CAF-ST3A-20M0000000
JCUGLMEP-155.52MHZ
M55310/19-B11A33M300000
MC044X5-041_SNPB
1104R50M00000BF
CO-402C-2B-10MHZ
0429CTXB19M6608
CO-484A-0X-200MHZ
MC859X4-019W
1105R24M00000AE
EX-385-DAF-S5892-10MHZ
C2400C1-0054
0425DTEX32M0000
XO-500-DFC-205E-200MHZ
MC037X1-004
614Y5501-245.76MHZ
1104X60M00000AX
0426CTE50M00000
CO-286WT-3-1005MHZ
566Y5269-GB2EQM
C1300A1-0050
MC042X1-117
M55310/16-B14A2K0000000
XO-500-DFF-104N-200MHZ
EX-385-DAF-107F-40M0000000
401Y2009-40MHZ
C1250A1-0185
FX-156Y5873-640MHZ
0953BX40M000000_SNPB
C5250A1-0014
M55310/16-B41A30M720000
3429CCEX17M0000_SNPB
0429ACXB14M3180
447Y4587-25MHZ
SMOCSYA10M00000
MC859X4-021W
C1300A1-0033
MC049X5-043_SNPB
EX-385-CAD-ST3A-10M0000000
5116R80M00000BF
EX-380-DAF-107A-10M0000000
MC956X2-005W

PCN_NTDO-19HYTI032
Affected CPN list
CO-402A-2B-16MHZ
1102C50M00000BX
CO-449A-2X-18.432MHZ
TC-400-DAF-156A-60M0000000
EX-385-DAF-147A-10M0000000
6206-8.046875MHZ
545Q1
MC623X2-057H
MC046X5-022_SNPB
C1250B1-0134
CO-401A-0X-20KHZ
MC741A1-1352
M55310/16-B34A12M000000
1102R96M00000AF
252-4819-5-3.2MHZ
C2555A1-0019
MC349X5-014
MC741A1-1365
M55310/16-B21A1M843200
CO-401B-2B-24MHZ
EX-380-DAG-S6151-80MHZ
M55310/21-B11A20M000000
C1250A1-0117_SNPB
406Y4834-44.2368MHZ
MC704A1-014
5116D66M00000BX
M55310/19-B11A20M00000
C1300A2-0059
EX-385-DAF-507F-10M0000000
CO-402B-2B-20MHZ
615Y5333-155.52MHZ
TC-400-DAF-156C-14M7456000
M55310/16-B41A48M00000
XO-500-DFF-505E-100MHZ
MC955X5-010W
1116R20M00000BF
0429ACEB50M0000
3429ACEB35M0000
0426CCXX16M00000_SNPB
706Y0767-1-32.768MHZ
1116D32M00000BX
C1250A1-0220
0326CTE40M00000
7481AX20M000000
373Y4116-50MHZ_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
401Y5049-15.36MHZ
M55310/21-B12C10M00000_SNPB
717Y1310-10MHZ
C5570A1-0015
CO-401B-7B-48MHZ
C1300B1-0126_SNPB
JDUGCMEP-125MHZ
XO-500-DFF-505E-196.608MHZ
579AB009M900000
231-8894-60MHZ
C6998A1-0042
3246-6MHZ
0429ACXB64M0000_SNPB
T0581CZ-7.68MHZ
7411BX16M384000
MC093A1-001A
1103C12M00000BX
MC089A1-001
C1582A1-0001
1111R08M00000AF
M55310/09-B11A16M000000
CO-446A-1X-40MHZ
MC2001X4-009W
402-7323-32MHZ
4068-10MHZ
1103R40M00000AD
634Y5157-200MHZ
MC741A1-1349
C4999A1-0012
MC061A1-180_SNPB
CO-406B-1X-42.84MHZ
3429ACXB25M0000
434Y2342-147.456MHZ
CO-402C-2B-32MHZ
C5502A1-0021
MC342X1-030_SNPB
1116R28M00000BF
MC741A1-1222
JDUGLMEP-77.76MHZ
MC061A1-186E
MC342X1-021
MC997X1-001W_SNPB
8008-9.6MHZ
C1300A1-0134_SNPB
MC6001X4-003W

PCN_NTDO-19HYTI032
Affected CPN list
MC091A1-081
M55310/19-B13A33M000000
566Y5269-GB2
373Y2267-39MHZ
1110R12M00000AF
M55310/26-B32A5M242880_SNPB
1114R4M000000AF
434Y2342-137.088MHZ
JDUGLMEP-188.8598MHZ
EX-385-DAD-107A-20M0000000
738Y3642-15.84MHZ
MC453X2-004W
MC047X5-047
0945BXX12M28800
1110R5M321560AF
0429ACEB40M0000
EX-385-CAF-S5679-20MHZ
C2560A1-0054
4007-95MHZ
5116D64M00000BX
C1250B1-0030_SNPB
MC042X1-093
1102D100M0000BX
CO-401C-2D-12MHZ
CO-449A-2B-32MHZ
CO-449A-7X-32MHZ
MC2003X4-001W
432-9570-40MHZ
930Y5009-155.52 MHZ
C1435A1-0003
617Y5141-155.52MHZ
C1400A1-0043
C5250A1-0027
XO-500-DFC-S5880-245.76MHZ
XO-500-DFD-S6102-50MHZ_SNPB
MC1623X2-001S
C1250F1-0112_SNPB
1110R5M357400AF
484Y3808-75MHZ
CO-406A-0X-80MHZ
EX-380-CAD-107A-16M7772160
566Y3890-34.546875MHZ
M55310/26-B42A20M000000
1103V84M00000BX
MC032X1-026

PCN_NTDO-19HYTI032
Affected CPN list
457Y2384-300MHZ
C5300B1-0048
M55310/28-B04B10M000000
3467-20MHZ
C2400A3-0110
0428BCXB43M0000
C1250A1-0094
MC597X4-032W
M55310/27-B11A20M000000
371-9942-40MHZ
6649-93.65782MHZ
CO-285W-R-50MHZ
MC623X2-032W
C1460A1-0015
M55310/16-B41A20M000000
MC035X5-079
407Y1283-60MHZ
1104X24M00000AB
0426ATXX32M0000_SNPB
449Y3603-12MHZ
MC623X2-025H
M55310/21-B21A24M000000
M55310/16-B14A10K000000
445Y4611-21.4MHZ
CO-406A-7X-16MHZ
JDUFCMEP-122.88MHZ
330Y4783-1-5MHZ
M55310/16-B31A16M000000
1116B60M00000BG
1103V96M00000BX
MC741A1-1351
484Y2261-1-175MHZ
3429ACEB33M0000
M55310/26-B43A27M000000
JDUGLMEP-78.6432MHZ
566Y5724A
1110R5M321960AF
MC032X1-028
CO-402B-2X-423.920KHZ
3425DCEB20M0000
MC553X2-012W
CO-408A-1B-5MHZ
CO-402A-2X-63MHZ
3425DCX50M00000
M55310/16-B21A5M0000000

PCN_NTDO-19HYTI032
Affected CPN list
MC741A1-1354
MC061A1-041
MC061A1-149_SNPB
CO-449A-2X-2.4567MHZ
7202BX615K00000
C2400A3-0029
CO-724SG17L2-100MHZ
1113R24M00000BB
M55310/16-B41A50M000000
C1300A1-0034
CO-401A-2B-4.9152MHZ
CO-484A-2B-33MHZ
1110R5M321160AF
M55310/16-B21A2M457600
CO-442A-1D-24MHZ
1104R60M00000BF
C2400A3-0104
CO-233-R-45MHZ
MC959X2-019W-25.6MHz
M55310/28-B24A48M000000
0429ACEB01M5000_SNPB
C5300C1-0014
1107R48M00000BA
CO-447B-2B-16MHZ
MC623X2-024H
0336CCE34M90000
4597SH5C99R@10M000
4006-100MHZ
MC348X5-010
MC047X5-068_SNPB
1110X64M00000AX
407Y5294-40MHZ
C1250A1-0095
CO-402C-2B-26.2146MHZ
1104R1M152000AF
1102C16M00000BX
MC349X5-006
C1300A1-0198
484Y4144-153.6MHZ
MC741A1-1299_SNPB
MC958X2-046W
MC061A1-146_SNPB
XO-500-DFC-505E-66MHZ
C5570A1-0005
484Y2674-360.6MHZ_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
VC-415-DFC-205G-155.52MHZ
M55310/19-B01A1M000000
0429ACXB08M0000_SNPB
CO-402C-1X-44.2368MHZ
C2560A1-0036
C2560A1-0036
C1300B1-0120
EX-385-DAF-ST3F-20M0000000
401-9999A-2B 7.3728MHZ
C1300A1-0019
MC091A1-065
566Y5724A-1
0425DCXX80M0000_SNPB
4598SAP10M000000
EX-380-DAD-758A-10M0000000
C1400A1-0014
0425DCEB25M0000_SNPB
1108B48M00000AX
XO-400-CFC-C-260MHZ
CO-233-R-40-MHZ
406Y2995-8MHZ
1101B60M00000BX
1103R32M00000BB
1107R04M00000AF
5116D80M00000BX
C1250F1-0107
CO-401E-2B-16MHZ
MC623X2-056H
MC032X1-024
0429ACEB33M0000_SNPB
M55310/27-B11A29M491200
566Y5937-102.3125MHZ
0425DCEX40M0000
C1250F1-0125
1108V33M00000AF
0425DCEB29M4500_SNPB
0325CCE20M00000
0427ACE050M0000
5116R66M00000BF
7414BX01M000000
MC047X5-011
566Y6207-1
400-7562-12 MHZ
M55310/16-B31A4M0000000
TC-350-DAC-106A-33M6000000

PCN_NTDO-19HYTI032
Affected CPN list
M55310/16-B34A16M000000
1104R10M00000BE
MC1623X2-001E
CO-442-9X-960HZ
C1250A1-0187
1104D60M00000BX
C4550A2-0121-10M0000000
MC597X4-040W
0426CCXX08M0000_SNPB
7411BX33M554430
1116B32M00000AB
MC622X2-004
TC-140-CGF-106A-10M0000000
CO-402A-0X-10.0000KHZ
M55310/19-B11A30M000000
MC728A1-086
447Y2585-40MHZ
M55310/16-B34B16M000000
1105R12M00000AF
CO-407A-2X-33MHZ
C1250A1-0210_SNPB
1103R20M00000BF
0429CCEX43M2564_SNPB
447Y5267-16.384MHZ
1116R24M00000BX
C1300A1-0026_SNPB
434Y6139-160MHz
1103R44M00000BE
VS-502-CJF-GNN-400-MHZ
MC623X2-103H
7202BX461K50000
C1250A1-0205
C1250B1-0181_SNPB
MC833X4-006W
CO-401B-2B-9.8304MHZ
MC049X5-042_SNPB
MC741A1-1353
C1250A1-0036_SNPB
0949CBX12M50000
C4999A1-0006
431-9999A-1X-100 MHZ
0425CCEX20M4672
1105R25M00000AF
3484Y4628-331.8_MHZ
CO-401B-6X-50MHZ

PCN_NTDO-19HYTI032
Affected CPN list
566Y3890-3
XO-400-CFC-C-160MHZ
M55310/16-B31A10M000000
0427BTEX32M0000
CO-407A-2B-32MHZ
C6999A1-0004
1103V48M00000BE
566Y5930-1 21.4 MHZ
0950BX50M000000
MC728A1-055
442Y1189-32MHZ
XO-500-DFC-205E-25MHZ
EX-385-DAF-107A-10M0000000
M55310/27-B21A32M00000_SNPB
CO-484A-2X-120MHZ
CO-484A-2XR-500MHZ
0426CCEX48M00000_SNPB
431Y2196-80MHZ
CO-449A-1X-64MHZ
1111R25M00000AF
0426CTE32M00000
1104R96M00000AF
CO-446A-1X-8MHZ
402Y3495-18.432MHZ
0426CCXX2M29376
MC1623X2-100S
JDFCCMEP-95MHZ
M55310/16-B34A4M9152000
CO-402C-2X-16MHZ
CO-449E-1X-3.6864MHZ
C5250B1-0051
1116D50M00000BX
1117R40M00000AF
M55310/16-B41B40M960000
MC597X4-015W
TC-210-DFC-507A-104M857600
431Y3205-1-200MHZ
5973_68_MHz
M55310/16-B41B30M000000
0429ACEB33M5600
CO-252F26-1MHZ
231-2421-10KHZ
1111R31M45728AF
M55310/16-B44A24M000000
C2490A1-0015

PCN_NTDO-19HYTI032
Affected CPN list
C1300A1-0037
MC741A1-1288
3425BCXX30M0000_SNPB
484Y4879-75MHZ
CO-446D-1X-2.4KHZ
CO-441A-1X-30MHZ
TC-400-DBC-106A-100M000000
MC597X4-054W
EX-380-CAF-107A-10M0000000
EX-380-CAF-107F-10M0000000
MC091A1-090E
MC1000B1-006
TC-410-DAD-S6092-3.996MHZ
1103V84M00000BE
C1250A1-0119
6522-10MHZ
0428DCEX32M0000
MC061A1-022_SNPB
CO-408C-1X-35.00MHZ
C2570A1-0005
EX-380-DAD-107A-10M0000000
1110X12M00000AX
M55310/27-B04B10M000000
CO-441A-2B-1MHZ
566Y4995-27MHZ
3429ACEB04M0000
M55310/27-B21A40M000000
MC099A1-002
MC348X5-013
0427CCXX02M4576
C1340A1-0005
CO-441A-1X-15MHZ
CO-402C-2B-40MHZ
233Y5374-155.52MHZ
EX-385-DAD-107A-10M0000000
C2400A2-0034
TC-210-DFC-507A-80M0000000
C4600A2-0031-10M0000000
C1250A1-0064
0751BB11M059200
C4710A2-0020-10M0000000
5116R62M50000BF
441-9781-1MHZ
MC858X4-001W
CO-442B-2B-5.12MHZ

PCN_NTDO-19HYTI032
Affected CPN list
958WHADT40M00000
C4550A1-0002-10M0000000
0426ACX59M94161
MC623X2-103E
CO-484E-1XR-305.25MHZ
C1460A1-0022
7211AB24M960000
MC2001X4-005W
3647-12.8MHZ
1104R33M00000BF
0426CCEB11M0590
1116D40M00000BX
LC21.4-3.0/04
VS-751-LFF-GNN-P4-R6
VCC1-B2D-50M0000000
MQF21.4-2000/04
TRU050-GACCA-40M0000000
TRU050-GAEFA-50M0000000
VS-500-LFF-GNN-622M080000
VS-550-LFF-HNN-P2-R3
FX-101-DAF-S5763G
STFHLA-4M09600000
VDUNLB-30M0000000
VS-500-LFF-GNN-644M531300
SGFHLA-12M0000000
VS-751-LFF-HNN-P2-P5
TRU050-GKCFB-34M3680000
TFS280H
FX-700-LAF-GNJ-A5-J3
TFS1080
SGMGCA-44M7360000
TFS1590
TFS170E
TFS188A
TFS418A
VS-550-LFF-HNN-P2-P4
TFS434E
TFS456E
MQF35.25-5000/07
MQF90.0-2000/07
MQF70.0-0660/06
TRU050-GCCGB-51M8400000
VDUNLB-45M0000000
TFS140AN
TFS140G1

PCN_NTDO-19HYTI032
Affected CPN list
MQF70.0-2500/11
QF21.4-10000/08
QF70.0-4000/09
MQF100.0-1500/06
MQF21.4-1500/61
MQF21.4-4600/03
MQF45.0-1500/11
MQF45.0-5000/08
LC21.4-5.0/04
MQF10.7-2000/10
MQF21.4-2200/09
VCC1-B3B-40M0000000
VS-751-LFF-HNN-R3-R6
VCC1-B2D-24M0000000
SGMGCA-25M7889000
TRU050-GALHA-18M4320000
TRU050-GCLGA-32M7680000
TRU051-GTCGA-19M4400000
LC21.4-80000/04
FX-500-LAC-GNK-A3-D6
TRU050-TBLFA-38M7070000
VCC1-B1C-100M000000
JDUGLITN-1M54400000
MQF10.7-2500/10
STFHLA-20M0000000
STULLA-4M09600000
VDLHLA-6M14400000
STFHLA-16M3840000
TRU050-GALGA-38M8800000
MQF21.4-2000/27
TRU050-GAECA-32M7680000
FX-102-DFF-A1C6G
SGUGCA-38M8800000
TRU050-GHLHA-24M5760000
TRU050-GFCHA-65M5360000
TFS70BB
TFH70E
VS-550-LFF-HNN-P4-PB
VS-550-LFF-HNN-R3-R4
TFS110A
CD-700-LAF-GAB-32M0000000
TFS1188
JHLSCKUS-49M1520000
VS-500-LFF-GNN-155M520000
TRU050-GALNA-59M9400000

PCN_NTDO-19HYTI032
Affected CPN list
SGUGLA-4M09600000
TFS171A
TRU050-GACGA-38M8800000
STFHCA-16M0000000
TFS398F
SGUGCA-32M7680000
TRU050-GHLGA-16M3840000
VS-500-KFF-GNN-622M080000
TFS215A
MQF38.4-0600/03
VS-751-LFF-GNN-P2-R3
MQF70.455-4000/07
FX-102-DFC-A1C6G
FX-500-LAF-GNJ-A3-H3
STUHCA-6M17600000
VS-500-LFF-GNN-320M000000
JCUPCJTN-44M7360000
QF172.955-3500/07
JCUHCKTN-20M0000000
TRU050-GCLGA-16M3840000
FX-500-LAC-GNJ-A3-K2
TFS280M
TFS135E
VS-751-LFF-HNN-R4-TG
VCC1-B3B-10M0000000
STUHLA-6M17600000
M55310/16-B41A39M000000
VCC1-A0C-20M0000000
TFS242A
FX-500-LAC-HNJ-A3-D6
TFS248F
TFS150U
VCC1-B3D-25M0000000
TFS340
TFS500
MQF74.7-1000/02
VCC1-B3D-40M0000000
VS-751-LFF-HNN-P2-P4
JDMGCBTN-77M7600000
QF10.7-10000/04
TFS75E
MQF10.7-3000/33V3
FX-500-LAC-GNK-A3-K2
TFS167E1
TFS1176

PCN_NTDO-19HYTI032
Affected CPN list
TFS1237
TFS208B
TFS71M
SGUGCD-32M7680000
TFS37A
TFS215B
TFS190
TFS421
TFS430C
MQF40.025-0800/02
TFS434F
MQF35.25-5000/08
JDUHLKTN-25M1658240
MQF70.455-0800/07
MQF10.7-0840/07
VS-550-LFF-GNN-P2-P5
FX-500-LAF-GNJ-AH-JF
FX-500-LAC-GNK-H2-H2
TFS135D
CD-700-LAC-GAB-65M5360000
TFS140H
1104R40M00000BF
TFS140AS
M55310/16-B41A47M000000
TFS242
VS-750-LFF-HNN-P2-P5
VS-751-LFF-HNN-P4-PB
MQF21.4-0250/04
MQF21.4-1500/73
TFS800
TFS875A
QF21.4-10000/09
TFS914
STFHEA-10M0000000
MQF21.6285-5000/03
CD-700-LAF-GAB-25M6000000
QF10.7-10000/08
MQF70.0-0800/07
VCC1-G3D-25M0000000
MQF21.4-0300/07
MQF10.7-0760/05
MQF21.4-1500/64
MQF10.7-0850/12
MQF10.7-2000/11
TFS90E

PCN_NTDO-19HYTI032
Affected CPN list
TFS840B
MQF40.0-2500/03
TFS915A
TFS92D
MQF21.4-3000/11
MQF21.65-5000/03
MQF40.5-3000/03
MQF45.0-1500/53
FX-500-KAF-SSJ-JD-JD
FX-500-LAC-GTJ-A3-J3
MQF10.7-0240/07
MQF21.4-0750/14
VCC1-BOF-40M0000000
MQF10.0-0500/04
TRU050-GALGB-12M6240000
TRU050-GAECB-38M8800000
VS-500-KEF-GNN-669M326600
TRU050-TACGA-20M0000000
TRU050-GALGA-24M5760000
OBS_TRU050-GBCNA-30M7200000
STUNLA-24M5760000
STUGCA-8M19200000
SGUHLA-16M3840000
VDUGCA-56M0000000
VS-500-KEF-GNN-666M514300
FX-424-DAF-S6194G
SGUFLB-51M8400000
SGUFCA-1M54400000
FX-104-DFC-S5864G
VS-750-LFF-HNN-P8-P9
VS-751-LFF-HNN-R4-R6
TRU050-GALGA-19M4400000
TRU050-GDCFB-24M7040000
FX-102-DFF-A1C2G
SGFHLA-24M7040000
STUGCB-32M7680000
VS-500-LFF-GNN-161M132800
SGFHLA-16M0000000
TRU050-TACGA-16M3840000
SGSHCA-3M08800000
TFS280A
TRU050-GACCA-65M5360000
FX-500-LAF-GNJ-D6-D6
TFS245B
VS-500-KFF-GNN-644M531300

PCN_NTDO-19HYTI032
Affected CPN list
TFS112R
TFS1220
TFS300
JCLGCKTN-66M4370000
TFS1576
VS-550-LFF-GNN-P2-P4
TFS1068A
JDUHLJTN-36M8640000
VS-751-LFF-HNN-P2-R3
TFS70K
TFS770F
FX-500-LAF-GNJ-H8-H8
TFS130A
TFS199D
TFS2010
TFS390B
VCC1-B3C-25M0000000
MQF45.0-5000/13
TFS211C
TFS433S
MQF21.4-4600/08
VCA1-A0B-40M0000000
MQF75.0-3600/02
VC-501-DFF-GFL-125M000000
FX-500-LAF-GNJ-AH-E2
JDSSLJTS-63M8976000
SGUGCA-40M9600000
TFS140A3
FX-500-LAF-GNJ-AH-D9
VS-500-KEF-HNN-690M569200
VS-500-KEF-HNN-644M531300
TFS140AU
TFS141
TFS156A
TFS1575H
MQF70.0-1500/03
VCC1-A3D-7M37280000
MQF41.44-0800/06
VCC6-QCC-156M250000
MQF90.0-2500/08
QF10.7-15000/04
VC-501-DFF-GFM-100M000000
MQF10.0-2000/04
VCC1-B2F-64M0000000
MQF10.7-2600/05

PCN_NTDO-19HYTI032
Affected CPN list
MQF10.0-2000/06
MQF21.4-0800/07
MQF10.7-5000/14
JDMGCJTN-65M5360000
SGUGLA-24M7040000
VCC6-LCF-33M3330000
VCC6-VCD-100M000000
VCC6-VCE-100M000000
STUNLA-32M0000000
JCLGLD-51M8400000
VS-751-LFF-GNN-P2-R5
MQF10.7-1500/04
VS-751-LFF-GNN-PB-TC
MQF10.0-0300/04
MQF10.7-3000/12
TRU050-GACGB-44M7360000
JDUGCATN-61M4400000
TRU050-GAEFB-50M0000000
FX-101-DFC-Y5180G
MQF21.4-1700/10
TFS864
TFS895
TFS915D
MQF20.0-0600/03
TFS935
MQF21.4-3000/20
MQF21.4-2000/06
TFS868M
TRU050-GACCB-44M7360000
VS-550-LFF-GNN-P4-R6
STUGCA-6M17600000
MQF40.625-3000/08
TFS90B
TRU050-GCLGB-16M3840000
TFS915L
TRU050-GFCGA-32M7680000
JDLGLD-6M48000000
STUGLA-24M7040000
TRU050-GBLFA-38M7070000
SGFHEA-12M0000000
FX-104-DFF-S5856G
FX-500-LAF-GNJ-C4-JF
FX-500-LAF-GNJ-C4-JF
MQF21.4-3000/46
VDUNLB-32M7680000

PCN_NTDO-19HYTI032
Affected CPN list
TRU050-TACCA-40M0000000
FX-102-DFC-A1P6G
TRU050-GKCGB-44M7360000
TRU050-GAECA-38M8800000
SGUGCA-26M8435000
TVC-400-DAL-GE-24M5760000
VCC1-G3C-50M0000000
VCC1-G3F-125M000000
VCC1-F3D-100M000000
OSC-1A0-10M0000000
TFS2657
TFS322
VS-500-LFF-GNN-166M628000
SGULLA-4M09600000
VCC1-B3D-16M0000000
TFS2570
TFS611C
TFS1007
VCC1-B3F-10M0000000
TFS360K
JDUGLATN-51M8400000
TFS121
VCC1-B3D-32M0000000
TFS70L14
TRU050-GCCGA-16M3840000
FX-500-LAF-GNJ-K2-K2
FX-500-LAS-MNJ-A3-J6
JDUHLJTN-17M9200000
TFS1575N
TFS243A
VS-550-LFF-GNN-P5-R3
TFS200F
TFS110X
TFS400F
TFS380R
VCC1-B3C-24M5760000
TFS130C
TFS1575G
TFS433R
MQF21.4-4000/12
TFS248H
TFS168A
TFS1750C
TFS464C
MQF71.85-2500/11

PCN_NTDO-19HYTI032
Affected CPN list
TFS199E
JDLGCKTN-61M4400000
TFS211
TFS400
TFS70BD
TRU050-GDCGB-32M7680000
TFS1068
TFR433S
TFS140E
TFS144
TFS433L
C4600A1-0155
MQF50.0-8000/06
MQF71.64-5000/02V1
VCC1-B3D-7M37280000
VCC1-B1D-14M3181800
VCC1-B1F-14M7456000
VTC1-D21C-10M0000000
VS-500-KFF-GNN-666M514300
QF70.0-4000/07
TRU050-GKCFB-44M7360000
TFS110P
FX-500-LAF-GNJ-C4-JR
FX-500-LAF-GNJ-C4-JR
TFS770C
TRU050-GFCHS-65M5360000
VS-500-LFF-HNN-669M326600
TFS140C
TFS1432
C4408A1-0028
VDUNLB-16M3840000
JDUCCJTN-2M04800000
TFS2100
TFS37B
STUHLA-8M19200000
MQF40.5-4600/02
MQF21.4-3000/42
FX-500-LAF-GNJ-A3-D6
QF21.4-12000/06
QF10.7-20000/04
VCC6-LAD-125M000000
TFS140AT
MQF21.4-1500/03
MQF21.4-1800/10
TFS868C

PCN_NTDO-19HYTI032
Affected CPN list
TFS903
TFS1555
MQF21.4-3000/37
MQF90.0-2500/07
QF10.7-10000/09
QF4.9985-0010/08
VTC1-A21C-10M0000000
TFS900
MQF42.2-0800/03
MQF45.0-2500/02
TFS915E
TFS940A
VXA1-1B2-1M84320000
MQF21.4-3000/29
MQF27.0-2400/01
VXB1-1D1-10M0000000
MQF156.8-3000/03
MQF21.4-1500/76
TFS915B
MQF21.4-3000/14
MQF24.3-3600/04
MQF40.625-0750/08
VCC6-QCB-125M0000000
MQF70.0-0800/09
VCC1-F3D-32M00000000
LC21.4-2.0/04V1
MQF21.4-1500/71
JCMGLATN-8M44800000
JDLGCKTN-32M7680000
TRU050-TAEGA-37M5000000
VS-500-KEF-GNN-166M628600
FX-200-DFC-C4XXP2P4G
TRU050-GHLCA-16M3840000
VS-500-LFF-GNN-669M326582
SGUGCA-8M19200000
SGUHLA-6M17600000
TRU050-GHLCB-19M4400000
TRU050-GDLGA-16M0000000
TFS280G
TFS332
TFS675
FX-500-LAC-GNJ-D6-H5
TFS115A
TFS1220E
TFS70Y

PCN_NTDO-19HYTI032
Affected CPN list
TFS1580A
TFS186
TFS403A
TFS434A
MQF35.25-2600/06V1
VS-550-LFF-GNN-P2-R3
TFS140AM
TFS134B
TFS140G
TFS240S
MQF200.0-1500/BSMA
MQF21.4-1500/52
MQF21.4-2000/24
VTC1-B12A-10M0000000
TFS86A
TFS90C
VTC4-B02E-12M8000000
VTC4-C01E-10M0000000
VXB1-1D2-25M0000000
99-319-2-14M800000
V42310-Z114-A1-51-3M5795
810210-30S10-20M0
310524-30_5M120
310510-30-2M9696
C4400A1-0036-N-10M0000000
C4400A1-0036-N-10M0000000
C4500C1-0042-10M0
C4400A1-0012-12M0
C1310A1-0058-12M8
C1310A1-0058-12M8
C4530A2-0025-10M0
C4500A1-0054-26M0
C4500C1-0056-10M0
C4550A2-0110-10M0
C4400A1-0065-20M0
C1310A1-0086-400M0
C1310A1-0095-H
C1310A1-0095-H
1AB124780067-10M0
C4530A2-0046-16M384
C4500C1-0067-10M0
V42311-Z61-B32-51
V42311-Z61-B35-52
1AB124780170-32M0
C4505A1-0004-26M0

PCN_NTDO-19HYTI032
Affected CPN list
C1300B1-0146_SNPB
C4550A2-0153-20M0000000
403-4945-12MHZ
C1250A1-0077
CO-431A-0X-120MHZ
C4600A1-0154-10M0000000
CO-442B-6X-16.393440MHZ
454Y6181-1-160MHZ
718Y4349-5MHZ
JDUGLMUP-125MHZ
MC399X1-004W
0425DCEB66M0000_SNPB
JDUFCMEP-163.84MHZ
C1250A1-0093
CO-401E-5X-30MHZ
MC748A1-097
0953BX64M000000
C1250A1-0200_SNPB
447Y4951-24MHZ
624Y5054-155.52MHz
EX-381-DGF-507A-80M0000000
1105R02M00000AF
930E38M656000EN
C1250A1-0201_SNPB
C2400A3-0064
3424ACXX8M33330
CO-448A-2X-22.118MHZ
MC997X1-003W_SNPB
1116R10M00000BF
C1250A1-0202_SNPB
441-9999A-7X-96KHZ
615Q4
7242BBX10M000000
1118V4M000000AG
C1250B1-0049
C2525A1-0047
CO-408C-5B-20MHZ
C1300A1-0145_SNPB
C4400A1-0116-142M000000
CO-714D17WL2-10MHZ
6422-40.455MHz
283Y3272-915MHZ
C1300A1-0196
C4400A1-0117-148M000000
CO-718SD58WL2-10MHZ

PCN_NTDO-19HYTI032
Affected CPN list
283Y3272-1290MHZ
C1300A1-0199
400-7563-40_MHZ
CO-768SE27-10MHZ
6869-147MHZ
3357-3.200038MHZ
C6998A1-0047
M55310/28-B01B9M8304000
441Y1513-1-9.437184MHZ
CO-484V-KX-60MHZ
C1250A1-0216
JDFGCMUP-156.25MHZ
C1300B1-0190_SNPB
C1300B1-0195_SNPB
C1300B1-0191_SNPB
MC728A1-105
MC775A5-005
MC782A5-002H
MQF21.4-4000/13
TFS245E
C4600A1-0107-10M0000000
7411BX4M0000000
C2550B1-0008
CO-402B-2B-32MHZ
CO-402C-2B24MHZ
C1250A1-0189
C1250A1-0002
MQF70.0-3000/19
M55310/26-B03A1M0000000
432Y2109-34.732MHZ_SNPB
C2400A2-0117
FX-427-DFF-S6223
444Y3721-39.3216MHZ
MC1000B1-036
M55310/26-B32A8M0000000
454Y2440-600MHZ
C4540A1-0016
1101R60M00000BF
TC-350-DAF-106A-5M00000000
C4540A1-0018
C2400A3-0077
VS-705-ECE-KAAN-737M280000
CO-441A-2B-24MHZ
442Y1189-2.4576MHz
C2400A3-0116

PCN_NTDO-19HYTI032
Affected CPN list
TFS125L
TFS190D
TFS1200
FX-500-LAF-SSJ-JD-JD
C2400-F106-SV033-RFH-B1-40MHZ
XO-500-DFC-205E-166.6286MHZ
EX-385-DAF-507A-10M0000000
C4550A3-0162-10M0000000
C4550A2-0222-10M0000000
TFD895B
TFS482
TFS96B
442Y1632 12M
446Y3853 4.9152
TFS70AX
TFS70Z
EX-245-CAF-107ASS-20M0000000
TFS1580B
TFS916
TFS1209
CM031005-18-18M432000
CM031005-25-25M000000
C2555A1-0022
CM031005-12-12M000000
CM031005-16-16M000000
MC623X2-064H
C4700-C029-SV120-RFS-A2-5M000000
CO-718SB59WL2-10MHZ
TFS602
TFS1080A
C4550A2-0227-10M0000000
401Y0948-20MHZ
TFS780
TFS762
CO-402A-2B-20MHZ
442Y6210-15.36MHz
M55310/16-B34A8M0000000
MC639X2-007H
VCC6-VCE-200M000000
TFS622C
TFS320
TFS307
TFS500A
TFS498
TFS622D

PCN_NTDO-19HYTI032
Affected CPN list
TFS672
TFS600A
GJN999850P40-10M0
TFS400L
TFS491A
TFS448B
TFS480C
99-319-1-10M600000
730524-30S10-40M0
TFS1569
MC741A1-086
VTD3-J05E-10M0000000
C1300A1-0207-15MHZ
EX-385-CAF-ST3G-12M8000000
TC-400-CBS-S4225-114MHZ
1103R16M00000BF
1105R24M00000BF
1118V16M00000BF
TFS408
TFS576
TFS550
TFS626
CO-401A-2B-40MHZ
CO-401A-2B-16MHZ
M55310/21-B22C32M00000_SNPBDIP
TFS140AV
TFS153C
C4540A1-0019
C4540A1-0014
1623H56M00000EN
FX-500-KAF-HNJ-C4-C4
MC109A1-179H-19MHZ
MC763A1-001-5MHZ
VTC2-J01E-10M0000000
CO-402A-1X-10MHZ
TC-210-CAC-106A-51M2000000
MQF10.0-0760/01
MQF10.0-1600/04
C4710C1-0051-10M2300000
716Y2690
JDUCCJTN-16M3840000
TC-350-CAF-106A-10M0000000
MQF100.0-0800/01
MC042X1-100_SNPB
C1300B1-0027

PCN_NTDO-19HYTI032
Affected CPN list
CO-402B-2B-24MHZ
MQF70.0-1500/18
MC867X4-003W
TFS678
449Y5461-40MHZ
427Y3298-3.6864MHZ
TFS480D
TFS140V
TFS800A
4043
TFS456AL
EX-380-DAF-107F-10M0000000
TFS35A
CO-402A-2X-8MHZ
627Y5227-160.316MHZ
VCC4-H3D-8M00000000
OX-249-0001-100M0000
0426CCXX20M0000
VS-500-LFF-GNN-200M000000
1105R20M00000BF
C5250A1-0089
TFS1960
TFS1880
TFS325E
TFS666
TFS499A
CS-300-DFC-D6M2P2G
FX-730-LFF-GAA-M4-M4
M55310/16-B31A9M600000
M55310/19-B11A19M34100
M55310/19-B01A13M04900
TFS199G
VS-720-LFF-GAB-300M000000
432-6614-1-100MHZ
C5300A1-0075
TFS1397
TFS1413
TFS455A
C1460A1-0018
MQF10.7-1500/01
TC-400-CGF-156B-29M9100000
1117V25M00000BF
C4530A1-0016-N
1103D16M77722BX
1105R04M32000AF

PCN_NTDO-19HYTI032
Affected CPN list
VS-502-DFF-GNN-1000MHZ
4008-102.4MHZ
M55310/27-B21A50M00000
TFS1370
CO-487E-5X-300MHZ
C1300A1-0200_SNPB
CO-401A-0X-40MHZ
M55310/26-B26A3M686400
C2570A1-0014
TFS707
0425DTEX02M0000
4488311901-6M0
410514-30-4M8
TFS1220A
TC-400-DAF-156C-20M0000000
CO-401B-1B-41.427MHZ
MQF21.4-2200/08
JDUMCJTN-74M1758000
C4550A2-0225-30M7200000
0429CCEX16M0000_SNPB
TFS80G
CO-442D-2B-32MHZ
TFS70AV
TFS403B
OC-260-CJB-107AA-10MHZ
MC937X5-002W
M55310/16-B41A66M00000
C1250B1-0238-106.25MHZ
CO-401A-7B-32MHZ
JDFGCM EP-166.6286MHZ
TC-350-CAF-206F-10M0000000
810110-20-30M0
MC061A1-192-12.288MHZ_SNPB
JDUGCM EP-118.75MHZ
JDUGCM EP-131.25MHZ
C1405A1-0045
C2525A1-0043
HETT402171P240-24M0
CO-402D-2B-64.512MHZ
TFS706
484Y3980-286.08MHZ
M55310/16-B44A40M00000
C1405A1-0034
TFS512
484Y3089-010-249.850MHZ

PCN_NTDO-19HYTI032
Affected CPN list
484Y3089-011-250.150MHZ
XO-500-DFF-505E-155.52MHZ
1109R540K0000AE
CO-402A-7X-32.3624MHZ
CO-402A-7X-20MHZ
CO-442C-2B-32MHZ
CO-442C-2B-200HZ
1116R24M00000BF
C2555A1-0026
810522-30-5M12
HCP2H0D16C-25.6MHZ
402-5699-1-20MHZ
VS-502-DFF-GNN-800MHZ
0429CTXB66M0000
310524-30-4M0
TC-400-CGF-256A-60M0000000
6462-20MHZ
C2555A1-0027E
CO-401A-2X-26.667MHZ
C1300A1-0028-20MHZ_SNPB
TFS250A
CO-402A-0X-100KHZ
M55310/16-B34A15M000000
FX-424-DFC-S6270G
VS-751-LFF-HNN-P7-R3
VS-751-LFF-HNN-PD-P5
GJT113501P6-24M0
TFS180E
M55310/16-B31A14M31818
FX-500-LAF-HNJ-A4-H4
TFS156C
TFS155A
TFS420D
21074576701-129M3
MQF10.7-3000/04
C5300B1-0083-24MHZ
484Y4556-79.69MHZ
C5300B1-0082-80MHZ_SNPB
TQX4141-12M285
TQX6835-9M03167
310222-SS20-27M0969
310222-SS20-27M085408
C4540A1-0021
C1405A1-0047
434Y6065

PCN_NTDO-19HYTI032
Affected CPN list
566Y6067
566Y6066
MC061A1-196
1117R80M00000BF
1117X80M00000BX
TFS1575D
718Y5063-20MHZ
MC704A1-012
TFS70H33
TC-400-CAC-106A-100M000000
CO-441A-2B-18.432MHZ
CO-441A-2B-20MHZ
M55310/16-B21A3M686400
M55310/16-B31A19M20000
C1259A1-0047-25M0
MQF25.0-0600/03
VCC1-F2F-20M0000000
VCC1-F2F-25M0000000
VCC1-F2F-75M0000000
252-9956-1MHZ
CO-432B-2X-68.9655MHZ
C4550-C508-SV050-RFH-A2-1-10M000
1103R40M00000BD
CO-402D-2B-16MHZ
422Y0792-960 KHz
EX-380-DAF-147A-40M0000000
TFS850
C4600-C308-SV033-RFH-A1-0-10M000
OC-260-CAD-107CA-10MHZ
1116R08M00000BF
16S31B16M00000
VXB2-1B2-4M00000000
C1300B1-0201_SNPB
C1300B1-0202_SNPB
C1300B1-0203_SNPB
TFS345A
TFS586
C5300B1-0035
TC-400-CBF-156C-100M000000
XO-500-DFF-104E-80MHZ
403Y1090-30MHZ
403Y1090-36MHZ
EX-381-DGD-107A-10M0000000
VS-502-DFC-GNN-622.08MHZ
TC-350-DBB-106A-20M0000000

PCN_NTDO-19HYTI032
Affected CPN list
717Y5823-16.545MHZ
C2525A1-0042
M55310/26-B37C16M00000
CO-402A-7X-40MHZ
CO-449D-2B-20MHZ
1103B24M00000BX
1103D40M00000BX
VS-705-ECE-KAAN-400M000000
710512-10-19M95424
C4550A2-0212-20M0000000
M55310/26-B52A48M000000
487Y5975-1-100MHZ
TFS600
TFS186A
XO-400-DFF-G-80MHZ
CO-408A-2B-20MHZ
MC044X5-046
C1470A1-0022
1103D30M00000BX
C1470A1-0021
434Y6065-1
CERAMIC_TRANSDUCER
MQF90.0-2500/09
C4998A1-0018
MC720A1-035
3421CCEX30M0000
3421CCEX40M0000
EX-245-CAD-508ABN-20M0000000
M55310/26-B62B55M56000
484Y4604-10.7MHZ
487Y5975-100MHZ
C2570A1-0006
CRH400_diced_chip
CRH644_diced_chip
CRH480_diced_chip
CRH1000_diced_chip
CRH600_diced_chip
CRH640_diced_chip
CRH768_diced_chip
CRH500_diced_chip
CRH312_diced_chip
CRH320_diced_chip
CRH491_diced_chip
CRH324_diced_chip
TFS1747

PCN_NTDO-19HYTI032
Affected CPN list
CO-484A-1B-289MHZ
C1250B1-0240
VXA4-1D6-16M3840000
JDUGLMEP-124.416MHZ
CO-402C-2X-25MHZ
CO-402A-2B-12MHZ
C1460A1-0020
1116R40M00000AF
1116R80M00000BF
1105R32M00000BF
VS-705-ECE-SAAN-125M000000
VS-705-LFF-HAAN-622M080000
TQ5330-13M316
233-8189-1-80MHZ -
81X430P002-167M5
M55310/16-B31A12M80000
CO-401C-2X-16MHZ
1102R24M00000AF
MC741A1-1327
TRU050-GALGA-55M0000000
TRU050-GKCGA-50M0000000
TRU050-TKCHA-30M0000000
SGMGCA-13M1576000
JCUGLATN-14M7500000
FX-500-LAF-NNJ-A4-J7
FX-101-DFF-A120G
FX-500-LAF-GNJ-JT-JT
TRU050-GACGA-20M0000000
VS-720-LFF-SAB-300M000000
VS-500-LFF-GNN-240M000000
VTC1-A03E-10M0000000
VCE1-B3B-40M0000000
VTC1-B01E-19M2000000
VTC1-B21C-12M8000000
VXB2-1D5-16M0000000
VXE4-1H1-19M2000000
VCC1-B3F-80M0000000
VCC1-A3C-36M0000000
VXA4-1C6-29M4912000
C2570A1-0015
TRU050-GALCA-20M0000000
446Y3853-7MHZ
Quartz_16MHz/Spec.617/05_49S
MQF40.048-2000/02
VCB1-E1C-32M000

PCN_NTDO-19HYTI032
Affected CPN list
Quartz_16.5248MHz_Spec.148/99
Quartz_20.945MHz_Spec.24.1/06
Quartz_QAH014AA_14.7456MHz
Quartz_25.000MHz_Spec.704/06
VXB1-1C2-3M6864_Spec.774/07
VXB1-1C2-24M000_Spec.775/07
PCWS_7.0x5.0_BV44.1.A1-A
Quartz_5.000MHz_7020018
Quartz_32.768KHz_spec.22/97
MQF45.0-1500/10
MQF16.9-2000/02
MQF21.4-1500/04
OSC_TX3_801_BS_12.8MHz
Quartz_141.067MHz
Quartz_13.5617MHz_Spec.57/97
TXO_2.592MHz
Quartz_20.945MHz_Spec.25/97
Quartz_4.000MHz_Spec.65/97
MQF70.0-1500/08
QAI115AA_144.566666MHz
Quartz_4.433619MHz_72/97
Quartz_5.52950MHz_PHL_Spec.95/97
OSC_TCXO6_9.6MHz
Quartz_76.075MHz_Spec.54/97
Quartz_12.8MHz_Spec.16/96
Quartz_10.455MHz_Spec.17/96
MQF22.025-0750/02
MQF21.4-1200/02
MQF21.4-1500/25
QAI115AA_144.9MHz
Quartz_20.9450MHz_Spec_268/00
Quartz_20.945MHz/GT_Spec.172/99
Quartz_QAH003AA_3.0900MHz
Quartz_3.9936MHz_Spec_447.1/03
Quartz_10.240MHz_Spec_314.2/01
Quartz_20.480MHz_Spec.327/01
Quartz_44.5441MHz_Spec_295/01
Quartz_81.8425MHz
Quartz_14.112MHz_Spec.406/02
Quartz_10.700MHz_Spec410.1/02
Quartz_4.9152MHz_Spec_447.1/03
Quartz_3.8400MHz_Spec_447.1/03
MQF21.4-4000/10
TFS40
OSC_TCXO6_9.6MHz_Spec63/05

PCN_NTDO-19HYTI032
Affected CPN list
OSC_VCTCX06_13.025MHz_HC3104M
Quartz_4.000MHz_Spec.447.1/03
Quartz_QAI004AA_4.000000MHz
Quartz_50.000MHz_Spec.558/04
Quartz_32.768KHz_Spec.448/03
OSC_TX5-504_HL5_45.0120MHz_59/04
OSC_VT2-802FS_12.8MHz
OSC_VT2-802FS_13.000MHz_61/04
Quartz_16.384MHz_Spec.580.7/04
Quartz_126.233333MHz_368.0000MHz
Quartz_118.658333MHz_345.27500MH
Quartz_153.800000MHz_318.300000M
Quartz_145.300000MHz_301.300000M
Quartz_44.545MHz_Spec.253/00
Quartz_6.400MHz_Spec.430.1/02
TX5-504HL5_45.024MHz
Quartz_155.4500MHz_321.6000MHz
Quartz_17.866667MHz
Quartz_4.194304MHz
Quartz_10.000MHz_Spec.803/07
VCB1-E3C-16M3360000
EX-380-CAD-758A-16
VDUHLB_27.000MHz
TFS318A
TFS370
MQF10.703-0375/04
MQF10.7-0750/23
MQF10.7-1200/04
TFS433V
TFS434
TFS451A
TFS455D
MQF10.7-1500/22
MQF10.7-1500/23
MQF10.7-2200/04
MQF10.7-3000/01
MQF10.7-5000/19
TFS456AH
TFS45C
TFS460
TFS469
TFS471A
MQF16.0-0750/01
MQF168.32-1400/C
MQF21.4-0560/08

PCN_NTDO-19HYTI032
Affected CPN list
MQF21.4-2000/02
MQF21.4-2200/11
TFS506
TFS522
TFS525A
TFS533
TFS546
TFS590
TFS642
MQF21.4-3000/01
MQF21.4-3000/02
MQF21.4-5000/08
MQF21.4-5000/11
MQF26.0-0600/03
MQF45.0-0750/06
MQF45.0-1000/08
MQF45.0-3000/01
MQF45.0-3000/02
MQF50.0-3000/04
TFS897D
TFS940C
MQF60.0-0400/02
MQF70.0-2000/01
MQF73.125-1500/02
MQF73.35-5000/06
MQF92.16-0600/01
QD21.4-4000/01
QF140.0-50000/06
TFS1038
TFS110Y
TFS115F
TFS1204
TFS121B
TFS1220C
TFS1227
TFS1240
TFS1240A
TFS70AC
TFS70AU
TFS70AW
TFS70BE
TFS722
TFS746
TFS761
TFS1284

PCN_NTDO-19HYTI032**Affected CPN list**

TFS130B

TFS1331A

TFS1400

TFS1405

TFS1429A

TFS1455

TFS1485

TFS150AL

TFS1516

TFS153F

TFS155B

TFS156B

TFS1575

TFS1603

TFS160G

TFS160K

TFS1632

TFS1709

TFS1748

TFS177B

TFS776

TFS786

TFS817

TFS826

TFS837

TFS840C

TFS845A

TFS868H

TFS868N

TFS869H

TFS1864

TFS1900

TFS192

TFS192A

TFS192B

TFS1980

TFS2096

TFS2140D

TFS224C

TFS243E

TFS246H4

TFS2533

TFS256

TFS265

TFS280R

PCN_NTDO-19HYTI032
Affected CPN list
1102D24M00000AX
0429ACEB08M2180
1111R32M00000AF
C4999A1-0018
CO-705SB19WL2-10MHZ
MC092A1-029
VS-705-ECE-KAAN-500M000000
5365-10.062MHz
M55310/16-B41A21M42000
FX-424-DFC-A1P8G
VS-705-ECE-KAAN-155M520000
Eval_Board_VS-705/VS-707_LVPECL
CO-442A-1D-64MHZ
VCC1-H3F-25M0000000
403Y1090-2.4576MHZ
C5250A1-0090
XO-500-CFF-505E-163MHZ
VS-705-ECE-KAAN-644M531250
C4550A1-0236-10M0000000
442Y1189-8MHZ
MQF21.4-1500/79
M55310/19-B11A16M000000
M55310/16-B31B8M000000
M55310/19-B11A37M107000
C2525A1-0063
C6998A1-0033C
C4710D1-0054-100M000000
VS-705-ECE-KAAN-983M040000
CO-401A-1X-100MHZ
VS-705-ECE-KAAN-622M080000
CO-442B-1X-20MHZ
SGUGLA-17M7340000
FX-424-DPF-S6329G
C2555A1-0029
TFS140AY
C1455A1-0002
285Y1783-32MHz
285Y1173-250MHz
7122BX10M000000
C1460A1-0029
C4550A2-0240-10M0000000
CO-233-1RL1-29.997MHZ
CO-233-1RL1-91.595MHZ
810322-30S10-11M0592
VC-501-DFF-GFA-125M000000

PCN_NTDO-19HYTI032
Affected CPN list
C4550A2-0210-12M0940000
TFS717
VS-705-ECE-SAAN-669M326582
MQF10.0-1900/07
C1250A1-0234_SNPB
MC728A1-052
C4540A1-0032
EX-245-CAF-107FEN-10M0000000
1116D24M00000AX
TFS1575T
TFS1227A
TFS174H
TFS832
TFS806
C2999A1-0006
C2999A1-0008
0427BCXB32M0000
MQF45.0-1200/14
SO-502-CKF-S6130-1000MHZ
CO-718SB38WL2-10MHz
VS-500-LFF-GNN-250M000000
C1405A1-0057
1101R70M00000BE
VPC1-B1B-51M2000000
C5570A1-0016
EX-380-CAD-758A-16M0000000
TFS562
C2570A1-0016
TFS60D
TFS1220B
TFS1842G
TC-400-CBF-156C-50M0000000
MQF21.4-2000/21
MQF21.4-3000/03
Quartz_521/03_5.24288MHz
Quartz_14.74560MHz
MQF10.7-5000/03
TFS682
TFS802
TFS898
TFS922
HC0581EZ-1.0368MHZ
C4550C1-0246-10M0000000
C2525A1-0064
MQF20.0-0300/01

PCN_NTDO-19HYTI032
Affected CPN list
MQF30.0-7000/03
TFS986A
TFS846A
CO-402A-0X-10MHZ
Quartz_19.44MHz
Quartz_24.083333MHz
Quartz_24.069444MHz
TFS254C
MQF40.048-0800/02
MQF21.4-1500/06
VS-705-ECE-KAAN-819M200000
MQF10.7-3000/02
MQF100.0-0340/01
C2555A1-0031
CO-724SB59WL2-116.44444MHz
C4550A1-0243-38M8800000
C4550C1-0247-99M3600000
C1460A1-0013
CO-449E-1X-20MHZ
CO-449E-1X-25MHZ
VS-502-CJC-CNN-640MHZ
566Y6066-1
1117V60M00000BF
1101R10M00000BF
1116D19M66080BX
1116R19M66080BF
1104R25M00000BX
TFS902
0429ACEB20M00000_SNPB
205422105-10M925
253Y1616-21.4MHZ
0429CTXB04M9152
0429CTEB03M6864
1107R05M00000AF
VS-502-DFF-GNN-480MHZ
QF140.0-5000/07
1116C100M0000BF-3rd OT
1116C100M0000BF-5th OT
MC047X5-040_SNPB
TFS90
C1460A1-0008_SNPB
C4550A2-0053-10M0
0429ACEB41M94000_SNPB
C4550A1-0061-10M0000000
Quartz_4.915MHz_Spec.807/07

PCN_NTDO-19HYTI032
Affected CPN list
Quartz_3.579545MHz_Spec.285/01
255Y2090-21.4MHZ
C6999A1-0001S
MC069A1-006
TFS926
C1405A1-0039
1101R57M14290BE
CO-442D-2B-40MHZ
VS-705-ECE-KAAN-614M400000
MQF30.0-4000/07
CO-402B-0X-16MHZ
CO-233-1RL1-110MHz
CO-484A-2XR-50MHZ
CO-484A-2XR-100MHZ
CO-446C-2X-24MHZ
VS-705-ECE-KAAN-800M000000
0425DCEB37M5000
0425DCEB29M4500
0429ACEB41M94000
MQF70.0-5000/13
CS-427-DFF-S6305
M55310/28-B01A10M000000
M55310/16-B31A10M000000_SNPB
MQF90.0-5000/02
VTC1-A15E-12M8000000
1116R24M00000BE
C4600A1-0165-5M00000000
C4400B1-0136-61M44
C0581DZ-20MHZ-S
C0581DZ-26.667MHZ-S
205422104-10M475
C4400B1-0018-B
OC-160-CJD-508DA-10MHz
CO-724SD58L2-32MHz
MC728A1-106
TFS901
TFS787
TFS781A
FX-424-DPF-S6337G
CO-402C-2X-24MHZ
MC042X1-103_SNPB
1104R10M00000BF
CO-441A-2B-4MHZ
CO-401C-0X-20MHZ
C1250A1-0245

PCN_NTDO-19HYTI032
Affected CPN list
0429CTEX10M00000
C1470A1-0028
VS-705-ECE-KAAN-669M326582
C2525A1-0066
C2525A1-0067
Quartz_141.333333MHz_434.70000MH
TFS70AT
MC741A1-1228
CS-300-DFF-D6M2P2G
OC-160-AJD-509CA-10MHz
MC061A1-044
MQF10.0-0760/06
C5502A1-0030
CO-401B-0B-100MHZ
CO-434V-BB-34.368MHZ
CO-434V-BB-51.84MHZ
CO-484B-0B-140MHZ
CO-431B-0B-34.368MHZ
CO-431B-0B-51.84MHZ
C2555A1-0034
C2555A1-0035
C2555A1-0036
CO-484E-0B-86.4MHZ
CO-484V-DX-100MHZ
437Y3023-184.171983MHZ
MC061A1-140
C1460A1-0040
QF23.1-12500/02
QF23.3-12500/06
C1460A1-0023
310322-30-3M2768
1101R50M00000AX
1107D04M00000AX
MC741A1-1074
CO-441A-0X-8KHZ
MC929X2-041H
MC929X2-042H
MC929X2-043H
MC929X2-044H
MC929X2-045H
MC929X2-046H
010504-0501-10M000000
011126-0503-10M000000
011126-0504-10M000000
044-0075-00-3M355440

PCN_NTDO-19HYTI032
Affected CPN list
10225-2200-02-9M625000
10073-4720-40M000000
10225-2200-01-9M575000
7000022-20M000000
7000030-30M000000
7000100-100M000000
13012-0187-75M000000
205000061-10M000000
7000009-50M000000
2600-3M276800
2610-3M422133
238-601050-000-10M000000
2583-4M915200
2590-2M753623
2619-61M184800
2621-71M884800
2625-22M118400
2647-11M059200
2649-3M686400
4033631-32M001300
44-0019-00-75M000000
44-0019-02-108M000000
44-0019-03-108M100000
44-0076-03-12M000000
44-0092-00-3M002000
44-0092-03-6M000000
81000768-4M096000
A180HHJ-32L-5M529500
CO-402A-0X-7.8336MHZ
TFS342
1101B57M14290BX
1101B70M000000BX
0425BTXX12M2880_SNPB
M55310/16-B31B11M059200
VCC1-B3F-66M6670000
C2555A1-0037
TFS940B
C4550A1-0251-10M0000000
FX-424-DAF-S6267G
FX-424-DAF-S6266G
CO-401A-7X-3.6864MHZ
C2501A1-0031
C2501A1-0034
C2501A1-0035
CO-402A-2B-10MHZ

PCN_NTDO-19HYTI032
Affected CPN list
MC741A1-994
CO-401B-2B-497.664KHZ
CO-401B-2B-537.600KHZ
VS-705-ECE-SAAN-777M600000
CO-401B-2B-560.853KHZ
CO-401B-2B-635.880KHZ
CO-402B-2B-331.776KHZ
EX-245-CAC-308FEN-10M0000000
FX-102-DFF-S6192G
CO-402A-7X-9.83MHZ
MQF20.0-0500/01
M55310/28-C21B40M00000
CO-231V-GT-10MHZ
TFS766
QF140.0-10000/06
C1250A1-0246_SNPB
CO-233FW-160MHZ
1116D12M00000BX
CO-402B-1B-24MHZ
FX-424-DPC-S6342G
CO-402C-2B-8MHZ
HCB3A1G14C-75MHZ
MQF21.4-0600/04
MQF45.0-0750/17
MC1623X2-005S
MC061A1-138
MQF10.7-0750/03
VS-705-ECE-KAAN-491M520000
CO-402B-2B-14.7456MHZ
VX-400-EAZ-F-16M3840000
CO-441A-1X-20.5MHZ
0611AX40M000000
CO-287W-YRL1-1400MHZ
TC-140-BJC-106A-16M0000000
MC6811X4-004W
C5502A1-0031
1116R32M00000AF
1116R37M50000BF
1118D16M00000AX
1118D40M00000BX
FX-424-DFF-S6343G
VXB2-1D6-16M0000000
VS-705-ECE-KAAN-212M500000
CO-402A-2B-25MHZ
CO-402A-2B-30MHZ

PCN_NTDO-19HYTI032
Affected CPN list
MQF70.0-1000/03
VDUGLA-44M8000000
TFS360L
582R219H01-79M996800
582R219H03-99M996500
600-007777-1-9M728000
600-007777-2-12M160000
600-007777-3-8M320000
600-007777-5-14M599609
600-007780-2-4M096000
VS-705-ECE-KAAN-160M000000
VS-705-ECE-KAAN-200M000000
JDUGLMUP-91MHZ
6013-125MHZ
MC567X2-021W
MQF13.0-2500/01
C4540A1-0023
C4540A1-0024
EX-245-CAD-508FSS-10M0000000
TFS1210
TFS2040
0429ATEX20M0000
C4550-D107-SV050-RFH-A1-1-10M000
1116B50M00000BB
CO-402B-2B-358.4KHZ
CO-402B-2B-373.92KHZ
CO-402B-2B-423.92KHZ
TFS225E
C4550E2-0077-20M0000000
MQF45.0-0750/21
GJT113501P4-16M0
MQF45.0-0750/20
MQF45.0-3000/03
M55310/26-B33A7M372800
C6998A1-0143
CO-449C-2B-11.0592MHZ
TFS183C
MQF154.4-3000/01
VK-PCGS_5.0x3.2_04P_BV67.1.A1-B
VK-LCGS_4.9x3.1_CK22.1.A1
C1250A1-0248-127.872MHz_SNPB
1116R16M77722BF
1116R58M72026BF
1116R96M00000BF
0429ACXB08M8064_SNPB

PCN_NTDO-19HYTI032
Affected CPN list
VS-751-LFF-GNN-P2-TX
VS-751-LFF-HNN-TX-TY
TDB2A0D55C-48MHZ
1103R80M00000BE
VS-705-ECE-KCAN-635M040000
1117V10M00000BF
CO-402B-2B-11.059MHZ
C1250B1-0241
VS-705-ECE-KAAN-625M000000
CO-441V-KX-18.432MHZ
MQF45.0-5000/18
MQF45.0-1600/04
1116R32M00000AB
1116B37M50000BB
1116R37M50000BB
1103D10M00000AX
1103D3M686400AX
TFS614
1103D8M000000BX
1103D80M00000BX
1103D500K0000AX
1103R10M00000AD
1103R3M686400AD
1103R8M000000BD
1103R80M00000BD
1103R500K0000AD
TQ3316S_GURT-16M0
TFS90F
1101D20M00000BX
FX-102-DFF-D126G
C1460A1-0047
MQF20.0-0600/06
CO-233-1RL1-91.775MHZ
CO-233-1RL1-91.955MHZ
VS-705-ECE-KABN-622M080000
CO-402A-7B-18MHZ
1105D40M00000BX
449Y3106-16MHZ
CO-446C-0X-20MHZ
CO-446C-0X-25MHZ
C6998A1-0059
TFSS433K
TFS922A
CO-402A-0X-28MHZ
400-7563-20 MHZ

PCN_NTDO-19HYTI032
Affected CPN list
FX-424-DFF-S6251G
TFS250
TFS199M
1116R14M74560BF
PX-402-0008
MC597X4-030W
1116D20M00000BX
VC-501-DFF-GFM-200M000000
VS-751-LFF-HNN-P3-TC
CO-402A-2B-32MHZ
TC-140-CGF-S5831-10MHZ
JCLNLATN-39M3216000
233-6469-243MHZ
1102R80M00000BF
484Y4663-500MHZ
1105D24M00000AX
C2400A2-0122
Quartz_3.6864MHz_Spec.232/00
QF21.4-25000/04
233Y6053-100MHz
M55310/26-B33A16M000000
M55310/26-B07A01M000000
1103R30M00000BF
MQF70.0-0600/04
C1470A1-0031
C1405A1-0058
C1460A1-0049
C2400-F206-SV033-RFH-C1-80MHZ
3429CCXB40M0000
QF21.4-20000/09
TFS224
TFS160B
TFS161A
EX-245-CAF-107AEN-10M0000000
233-2-2-3M686400
CO-441A-2X-32.125KHZ
QAI020AA_20.945MHz
JDSGCKTN-77M7600000
C2560A1-0106
TFS261B
QF21.4-10000/12
1116R21M00000BB
CO-402A-2X-33MHZ_SNPB
M55310/16-B21A819K2000
MQF10.24-0200/01

PCN_NTDO-19HYTI032
Affected CPN list
1118D16M00000BX
M55310/16-B14A1K000000_SNPB
CO-421A-2B-307.2KHZ
OX-990-0001-120M00
OX-990-0001-120M00
C4550A1-0137-10M0000000
MQF21.4-5000/14
M55310/26-B22A1M000000
VS-705-ECE-KAAN-156M250000
FX-500-KAC-GNJ-C4-C4
FX-500-KAC-GNJ-C4-C4
M55310/16-B31A7M987200
M55310/16-B21A1M000000
MQF21.4-4000/14
1101R40M00000BF
1101R50M00000BF
1107R50M00000BF
OX-220-0004-10M0000
1116R24M00000AF
1116R25M00000BF
1116R50M00000BF
CO-401C-2X-11.059MHZ
C6998A1-0064
1116R02M00000AF
1116R04M00000AF
1116R12M00000AF
STULCA-4M09600000
1116R18M43200AF
STULCA-1M54400000
1116R20M00000AF
C6998A1-0065
VXB1-1A0-10M000/V50500-A1-A329
CO-286WT-3-1GHZ
447Y2585-50MHZ
VS-705-EDE-KAAN-155M520000
EX-245-CAF-157AEN-40M0000000
MC042X1-044
CO-441D-0X-1MHZ
CO-441D-0X-4MHZ
CO-441D-0X-12MHZ
CO-441D-0X-18.432MHZ
CO-441D-0X-1.8432MHZ
CO-441D-0X-20MHZ
CO-441D-0X-24MHZ
CO-441D-0X-25MHZ

PCN_NTDO-19HYTI032
Affected CPN list
0427BTXX40M0000
1104D54M00000BX
FX-500-LAF-SNJ-F7-F7
1104D33M00000BX
VS-705-ECE-KAAN-125M000000
C1300B1-0027_SNPB
Quartz_6.144MHz_Spec.326/01
VCC1-B2A-40M0000000
MQF45.0-3000/23
MC1623X2-005B
VS-705-ECE-KAAN-657M421900
SGFHCE-50M0000000
QF10.24-0006/01
M55310/16-B31A14M74560
TFS400F1
JCLHLD-44M7360000
OC-160-CJD-508BF-10MHz
M55310/16-B24A2M000000
C1460A1-0053
VX-4000-EA2-FXXX-24M5760000
VS-502-DFF-GNN-750MHZ
0911AXX66M0000
VS-705-ECE-SAAN-698M812335
GJN999850P65-12M0
C1340A1-0011
C1340A1-0012
1101R20M00000BF
VX-4000-EAZ-F-32M7680000
SGFHCA-8M1920000
VS-705-ECE-SAAN-622M080000
TFS915P
1116R100M0000BF
305-9957-16MHZ
C6998A1-0070
CS-300-DFF-S6070G
VS-705-ECE-KAAN-672M162712
0426CCXX04M0000_SNPB
C1405A1-0059
C1340A1-0013
1118R52M42880BA
1623J48M00000RN
1103R96M00000BF
566Y6067-1
VCC6-QAF-200M000000
CO-401B-2X-537.600KHZ

PCN_NTDO-19HYTI032
Affected CPN list
CO-401B-2X-635.880KHZ
TFS249B
C4550B1-0274-10M0000000
1116D24M00000BX
0426CTEX40M0000
MC623X2-009H
C6998A1-0072
MQF45.0-3800/09
10.694MHz_410.3/04_HC49/U_3pin
VX-990-0001-120M00
QF21.4-16000/03
MQF45.0-5000/19
MQF54.0-0600/03
0426CCXX20M0000_SNPBDIP
C4550A2-0272-12M8000000
CO-286W-1200MHZ
TFS800B
TFSS433L
TFSS431
TC-400-CBD-156C-16M8960000
TFSS429
TFSS435
TFSS436
566Y5724-1-40MHZ
C1460A1-0055
VCD6-101-173M438000
705Y4954
M55310/16-B24A400K0000
CO-402B-2X-373.92KHZ
1116R19M66080BX
M55310/26-B63A64M00000
M55310/16-B31A19M66080
FX-702-EDT-KMMM-H3-LN
M55310/16-B14A61K44000
1623J48M00000EN
1103D96M00000BX
1118D50M00000BX
1111R50M00000AF
1102R16M00000BF
1104R66M00000BF
1110R64M00000BA
QAB040AC
1110D64M00000BX
1104R24M75000AF
233Y2001

PCN_NTDO-19HYTI032
Affected CPN list
231-2026-5.5172MHZ
M55310/27-B11A25M000000
M55310/26-B02A1M000000
1111R16M00000AF
MQF21.4-3000/55
VCC1-G3C-28M0000000
VS-705-ECE-SAAN-625M000000
XO-400-DFF-G-36.25MHZ
MQF21.4-0700/07
1101D16M00000BX
1101D16M77722BX
1101D33M00000BX
TC-410-DAD-S6092-4.004MHZ
MQF75.0-3600/08
OC-160-AJF-107CA-10MHz
1101V32M00000BF
1116D96M00000BX
1116D16M77722BX
1104R56M00000BF
TQX7194-24M576
VS-705-ECE-KAAN-245M760000
EX-245-CAD-107FEN-38M1915150
TFS704A
TFS730A
M55310/16-B34A4M0000000
5859
1103R96M00000BX
1103V48M00000BF
1103V40M00000BF
C2570A1-0019
C2570A1-0020
1108R10M00000AF
1108D10M00000AX
TFS240M
442Y1189-2.5MHz
SGFHEA-40M0000000
172A1541-15M000000
C4998A1-0014
C5555A1-0010
C5555A1-0011
MC047X5-045
MC047X5-046
2102D80M00000WAX
C1555A1-0006
FX-702-ECE-KMMM-D6-M2

PCN_NTDO-19HYTI032
Affected CPN list
CO-446B-6X-16.39344MHZ
MC042X1-064-cold temp screened
MD-999-0001-10M00000000
PX-700-0005-33M0000000_SNPB
PX-700-0006-40M0000000_SNPB
VS-709-ECE-KAAN-P2/R5
VS-709-ECE-SAAN-P2/P5
VS-709-ECE-SAAN-P2/P4
VS-709-ECE-KAAN-P4/R6
VS-709-ECE-KAAN-P2/R3
VS-709-ECE-KAAN-PB/TC
C1460A1-0059
C1405A1-0063
TX-700-0004-10M24
TFS180H
C1250A1-0064_SNPB
TFS180G
M55310/16-B44A36M00000
JCUGCMEP-148.764MHZ
FX-702-ECE-KMMM-M2-P2
FX-702-ECT-KMMM-N2-R3
FX-702-ECE-KMMM-N3-R5
16310057-43-14M388672
600-100938-27-34M532813
CO-442A-1B-12MHZ
EX-4200-EAE-1073-20M0000000
MC091A1-099
MC091A1-080
0326CCE40M01800_SNPB
1118R16M00000AF
1118D1M048570AX
MC061A1-126E
TFS1560
CO-401A-1X-2MHZ
13012-0468-15M000000
MQF45.0-1200/13
C1460A1-0106
566Y3577-50MHZ
TFS216
PX-700-0007-50M0000000
MC639X2-005EM
M55310/16-B41A59M39200
PX-700-0008-5M00000000
QAH024AA
OX-200-0006-20M0000000

PCN_NTDO-19HYTI032
Affected CPN list
PX-5000-EAC-FKAX-50M0000000
16310057-44-14M408203
600-100938-30-34M579688
TC-210-DAF-106A-100M000000
PX-4001-DAT-DFXX-10M00000000
FX-403-ECE-S6360
FX-400-ECE-KNNN-D6-M3
VCC6-LAD-200M000000
TFS942G
1116R21M00000BF
MQF120.4-1500/HN
MQF121.9-1500/HN
EX-621-DHF-107A-10M00000000
TFS1621
PX-5701-DAY-WXXX-10M00000000
EX-209-0001-10M8570000
PX-7002-EAE-FFAX-25M0000000
EX-209-0002-10M8570000
CO-253G56-138MHZ
CO-449A-0X-142.86KHZ
MQF45.0-1500/63
MQF45.0-3000/30
CO-233-R-96MHZ
CO-233-R-96.01MHZ
C2525A1-0077
C2525A1-0078
1105R3M800000AF
VX-501-0012-61M44
VX-501-0012-61M44
1111R3M686400AF
C2570A1-0022
C2570A1-0021
600-006372-2-3M400000
600-006373-3-15M829938
1103D20M00000BX
1116C100M0000BB
1118C30M00000BB
1111R18M43200AF
C1460A1-0052
910716-30S11-12M000
C2570A1-0023
C2570A1-0024
C1405A1-0064
0429ACXB40M0000
600-100938-16-35M585938

PCN_NTDO-19HYTI032
Affected CPN list
JDUGLITN-40M0000000
C1470A1-0032
C2570A1-0026
0429ACXB40M0000_SNPB
OX-0430-AED-2582-10M0000000
OX-0430-AED-2583-10M0000000
TFS1280
FX-702-ECE-KMMM-M3-M3
5109-3.2MHz
1118V40M00000BF
1104R32M00000BF
TFS385
C1250A1-0256_SNPB
C1250A1-0258_SNPB
487Y5516-162.5MHZ
16310057-45-14M827474
OX-220-0020-10M00
TFS1210A
TFS1430A
VX-4000-EA2-FXXX-10M0000000
310110-30-12M000
TFS63C
TFS127C
VX-501-0017-122M88
1105R30M00000BF
1107D20M00000BX
PX-700-0009-80M1280000_SNPB
PX-700-0010-25M0000000_SNPB
PX-999-0001-4M0000000
TM80041CS-24MHz
OX-170-0014-10M0000000
CO-402A-OX-25MHZ
C2620A1-0025
VS-705-ECE-SAAN-693M483000
VTA2-2A0-10M0000000
C2999A1-0010
2102B80M00000WAB
2102R80M00000WAB
CB110707-33M333333
1104D66M00000BX
1104D40M00000BX
1104D24M00000AX
0428DTEX64M000000_SNPB
1103R96M00000BE
TX-191-0001-100M000000

PCN_NTDO-19HYTI032
Affected CPN list
C1460A1-0063
C1460A1-0066
600-006373-2-16M384000
600-006374-2-37M991850
600-006374-3-38M010000
1101V20M00000BF
1105D31M98157AX
TFS281
FX-702-ECT-HMMM-M2-M2
C1340A1-0015
VXM2-1C1-18M4320000
C4550A2-0275-20M0000000
283A8535P1-3M062500
0428DTEX64M000000
OX-220-0024-10M00
633Y4746
C1340A1-0016
VX-5090-EAE-GXXX-48M0000000
TFS434H
CO-724SD58L2-30MHz
TFS261C
QD10.7-2800/01
QA1115AA_141.0MHz
FX-702-ECE-HMMM-M2-P2
1111D49M09090BX
PD-700-EAE-NANN
CO-432A-OX-200MHZ
MC597X4-050W
OX-990-0006
MQF45.818-0600/02
MQF45.0-3000/31
QAB013AB
LC21.4-8.0/09
CO-402A-1X-3.6864MHZ
MC929X2-019H
VS-705-ECE-KCAN-737M280000
MQF148.29-1400/C
538665-8-106M445000
1105D31M45728BX
TFS1489
TFS1457
M55310/21-B22C20M000000
MQF21.4-3000/06
TFS433AB
MQF200.0-0800/06

PCN_NTDO-19HYTI032
Affected CPN list
JDUHCMEP-161.1328MHZ
SGFHCB-33M3330000
TFS307A
CO-446B-1X-6.144MHz
MQF70.0-1000/16
VS-709-ECE-KAAN-P2/P4
VS-709-ECE-KAAN-R3/R6
C2570A1-0027
1103V24M00000BF
1103V16M77722BF
1103V8M388608AF
C1460A1-0068
C1460A1-0067
MQF21.4-0700/10
C4540A1-0026
C4540A1-0027
600-006373-4-15M837500
C2560A1-0088_@240MHz
MC853X4-043W
1116D58M72026BX
1116D70M00000BX
1116D33M33000BX
TFS120L
TFS120M
TFS120H
TFS120K
MQF45.0-0750/12
C1460A1-0073_SNPB
1111C24M00000AX
1111C59M39200AX
1117D80M00000BX
1117D66M00000BX
MC6018X4-001W
M55310/28-B21A40M000000
CO-402B-0X-10MHZ
MQF37.4-0600/03
VX-5001-ECT-GXXX-400M000000
VCC6-RCF-125M000000
EX-385-CAF-507A-13M4217728
FX-702-EDE-KMMM-E2-M1
044861-4-12M000000
OX-400-0011-20M000
MQF21.4-10000/11
1103V48M00000BX
FX-700-EAT-SNKN-A3-JP

PCN_NTDO-19HYTI032
Affected CPN list
0426BCEX69M80000_SNPB
0426BCEX73M00650_SNPB
Quartz_13.4205MHz_spec.711/06
Quartz_13.58777MHz_spec.547/04
C1250A1-0262
C4500C1-0081-N-12M8
1116D16M00000BX
1116D7M680000BX
1116R16M00000BF
1116R7M680000BF
FX-702-ECT-SMMM-M3-M3
FX-702-ECT-SMMM-M2-M2
TFS411
233Y5958
FX-702-EDE-HMMM-K2-M2
MQF45.0-7000/01
PX-4001-EAC-DKXX-4M09600000
FX-400-ECE-KNNN-D6-V5
XO-500-DFC-205N-155.52MHZ
1105D3M800000AX
CO-484B-0X-60MHZ
PX-5001-EDE-DKAB-200M000000
3356-3.199962MHZ
TFS748
C4540A1-0029
M55310/28-B11A16M000000
CO-442A-0X-1.048576MHZ
C1405A1-0065
MQF70.0-5000/16
FX-702-ECE-KMMM-H8-L4
437Y5928-150MHZ
CRH698_diced_chip
MC985X1-004H
CO-402B-0X-28.01664MHZ
1103R20M00000BX
TFS326A
1103R20M00000BA
C5116A1-0009
404Y2207-50.996MHZ
C4550A1-0280-10M0000000
2104R40M92000KAB
2104C40M92000KAX
RBB8G0D56C-17.367MHZ
RBB8G0D56C-16.25MHZ
RBB8G0D56C-38MHZ

PCN_NTDO-19HYTI032
Affected CPN list
PX-700-0011-1M00000000_SNPB
VCC1-G3D-106M250000
VS-705-ECE-KAAN-122M880000
PX-4001-DBA-BKXX-1M00800000
VS-709-ECE-KAAN-R5/V8
C5570A1-0020
FX-702-SYNCE-156M250000
CD-700-SYNCE-25M0000000
1104D24M00000BX
1104D32M00000BX
1104D50M00000BX
1117R100M0000BA
1116D100M0000BX
1117D100M0000BX
1118C85M00000BF
FX-400-ECE-KNNN-D6-P2
OX-221-0035-10M00
QF60.0-4000/02
MQF70.0-1500/19
MQF70.0-0660/03
1104R24M00000BF
1116D12M00000AX
1116D18M43200AX
1116D20M00000AX
1116D2M000000AX
1116D32M00000AX
1116D48M00000AX
1116D4M000000AX
441-9999A-7X-20MHZ
441-9999A-7X-26MHZ
CO-421A-7X-1.0944MHZ
C2570A1-0028
C2570A1-0030
VCC6-1285-25M0000000
011126-0506-A-10M000000
PX-700-0012-312M500000
PX-999-0002-32M0000000
MQF21.45-3000/13
C5310A1-0316-S-195M0
C5310A1-0317-S-208M0
S-C5260A1-0074
PX-7000-EBC-SXXB-8M00000000
CO-402A-7B-1MHZ
1117B100M0000BX
VX-5090-EAE-GXBX-48M0000000

PCN_NTDO-19HYTI032
Affected CPN list
VX-501-0037-256M0
OX-220-0038-20M00
C5116A1-0010
C2501A1-0040
M55310/16-B31A16M60000
VC-820-EAE-KAAN-25M0000000
VC-820-EAE-KAAN-25M0000000
1110R16M00000AD
PX-4200-DA2-WXXX-12M0000000
PX-4200-DA2-WXXX-20M0000000
TFS1400A
TFS1980A
1116R70M00000BF
C4550A2-0281-10M0000000
1116R16M38400BF
OX-249-0002-100M0000
TFS1747F
TRU050-GKLNA-60M0000000
C5570A1-0019
C4408A2-0030
582R219H02-89M996500
484Y1651-21.9MHZ
VC-820-JAE-KAAN-25M0000000
VC-820-JAE-KAAN-50M0000000
TFS514
PX-7020-EAY-YXXX-32M0000000
1105D62M50000BX
1105D36M20000BX
1111D30M00000BX
C1405A1-0066
M55310/28-B11A20M00000
M55310/28-B01A8M0000000
M55310/27-B01A12M00000
1104D40M00000AX
EX-380-CAF-758B-10M0000000
2112D25M00000WBX
1105R4M096000BX
C6998A1-0076
C1250B1-0263_SNPB
C1250B1-0264_SNPB
MD-0114-BXJ-DOCX-10M0000000
MD-0113-BXJ-DAOC-10M0000000
MD-0103-BXJ-DAOC-10M0000000
PX-4001-0013-4M09600000
TFS832A

PCN_NTDO-19HYTI032
Affected CPN list
TFS1000
VX-704-0002-16M8000000
FX-700-EAE-KNKA-C4-C4
FX-702-SYNCE-125M0000000
TDB2A0D55C-40MHZ
FX-400-ECT-S6376
VCA1-A0B-2M45760000
C1405A1-0069
3429BCEB16M0000
C1460A1-0059E
C1460A1-0075
C1460A1-0076
Keramische_Kuehlkoerper
FX-400-ECT-KNNN-TG-TG
TFS63D
TFS123C
233-4668-1-70MHZ
OX-220-0040-12M96
MC580X2-004W
1118R9M216000BB
2112B25M00000WBC
VPC1-B3F-25M6000000
JDUHCJTN-74M2500000
JDUHCJTN-74M1758000
TFS333
CO-401A-1X-24MHZ
CO-431A-2B-200MHZ
1111R50M00000AX
1111D16M00000AX
VC-801-HAE-KAAN-50M0000000
2102R38M88000KAS
FX-500-LAF-SSJ-K9-K9
13012-0526-69M550000
1116B20M00000BE
1116B32M00000BE
C1250A1-0265
C1250A1-0266
TX-3200-EAE-206C-20M0000000
C4550A1-0282-10M0000000
C1405A1-0070
C1405A1-0071
C1405A1-0072
C1405A1-0073
C1405A1-0074
315-0099-020-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
VCC1-B3D-133M333000
617Y5402-622.08MHZ
MC029X1-016
TC-210-CBB-307A-1M00000000
TFS254D
OX-990-0008-10MHz
MQF90.0-3000/11
OX-200-0019-100M000000
PX-7002-EBC-FKAB-66MHZ
PX-5001-HDE-FFAB-125M000000_SNPB
TFS872
TFS1040
MD-0100-DXJ-TCXO-10M00000000
MQF45.0-0600/05
CO-484A-0X-170MHZ
CO-233VFW-MTYR-63MHZ
CO-233H-1-200MHZ
TFS1176CS01_FM
TFS1227ES01_FM
TFS1575AES01_FM
VS-705-ECE-SAAN-500M000000
MQF21.4-3000/58
1107B50M00000BX
TFS1430B
FX-702-ECT-HMMM-M2-P2
044-00009-0019-14M750000
FX-424-DFC-S6273G
VS-705-EDE-KAAN-622M080000
CO-401A-0X-8MHZ
MQF21.4-4000/03
MQF10.7-0300/09
MQF10.7-2000/07
1101D25M00000BX
OX-170-0025-10M00000000
MX-041-0001-10M00000000
MX-041-0002-10M00000000
7242AXX03M68640
7242AXX40M00000
600-008767-1-46M510417
OX-200-0020-100M000000
TFS1950B
1116R50M00000BX
1116R80M00000BX
PX-5000-EAC-KKAB-16M0000000_SNPB
FX-702-ECT-KMMM-K9-K9

PCN_NTDO-19HYTI032
Affected CPN list
VS-709-ECE-SAAN-R3/R6
MQF21.4-0900/06
MC049X5-011_SNPB
PX-7020-EA2-WXXX-3M68600000
CO-402B-2X-8MHZ
VS-705-ECE-KAAN-640M000000
VS-709-ECE-SAAN-P2/R5
C6998A1-0061 PRE-EDM UNITS
VC-806-HDE-FAAN-100M000000
CO-286W-1300MHZ
1101R25M00000BF
FX-424-DFF-S6375G
MQF130.0-2000/02
XO-500-DFF-505E-62.5MHZ
QF45.0-20000/07
CO-258F16-200k000000
MC069A1-006EM
MQF109.65-1200/02
TFS1019
PX-7020-EA2-WXXX-4M00000000
TFR1747
CO-401B-1B-29.972MHz
FX-424-DFF-S6373G
FX-424-DFF-S6374G
1107R48M00000AF
1101R33M00000BF
1101R32M00000BF
1101R66M00000BF
C1455A1-0003
Quartz_QAH010AB_10.0000MHz
TFS618
TRU050-SACCA-40M0000000
PX-4200-EAY-WXXX-3M00000000
VS-709-ECE-SAAN-P4/VC
EX-400-0002-10M000000
TFS110AA
TFS110AB
FX-500-LAF-SSJ-JT-JT
MQF20.208-3200/01
1111R2M000000AF
1111R7M680000AF
1107D48M00000AX
1101D66M00000BX
1101R32M00000BX
1101R40M00000BX

PCN_NTDO-19HYTI032
Affected CPN list
FX-700-EAE-SNKN-A3-JP
EX-245-CAF-157AES-26M0000000
583R302H01-55M996500
600-101289-2-4M096000
TFS110AC
TX-700-0028-10M0
044-00124-0001-8M760000
TFS70BL
MC724A1-131
C2570A1-0029
C2570A1-0031
C2570A1-0033
TFS640A
VV-800-EAE-KAAN-40M0000000
CO-402B-2X-32MHZ
CO-442B-2X-10.24MHz
C1460A1-0070
1105V4M194304AA
CO-718SB38VL2-10MHz
TFS215E
Quartz_100MHz-QAH100AA
Quartz_36.864MHz_602/05
1116R48M00000BX
600-008767-3-46M510417
CRH300ES01_diced_chip
C1405A1-0075
CO-441A-2X-32MHZ
CO-441A-2X-40MHZ
EX-400-0003-58M0000000
C1455A1-0004
1101V16M77722BF
1101V16M00000BF
1101V33M00000BF
PX-700-0014-125M000000_SNPB
289-7151-060-1M843200
VS-505-ECE-KAAN-1G00000000
Quartz_Crystal_64/97_3.5795MHz
EX-245-CHD-107FEN-40M0000000
044-00288-0000-85M833000
044-00292-0001-107M777700
M55310/16-B34A19M64400
MQF10.7-1680/08
MQF10.7-0630/08
TFS1091
TFS35FM01

PCN_NTDO-19HYTI032
Affected CPN list
VX-501-0058-128M0
VS-705-ECE-KAAN-250M000000
VC-820-EAE-KAAN-12M0000000
PX-4000-DAA-BKXX-1M20000000
C4550A1-0156-10M0000000
TFS215C
1103D7M0000000BX
C1250A1-0120_SNPB
MQF121.5-2500/R
CO-402A-7X-16MHZ
C4710C3-0019-10M0000000
EX-245-CAD-107FEN-38M1900000
C2525A1-0085
C2525A1-0086
MQF118.775-1500/GN
MQF124.85-1500/GN
TX-4002-DEE-1061-100M000000
VX-5090-EAE-KXXX-16M0000000
OX-2201-EAE-1080-12M800
VS-505-ECE-KAAN-669M326582
VS-505-ECE-KAAN-622M080000
VS-502-DFD-GNN-640MHZ
MQF40.7-5000/02
MQF10.7-1500/55
QF10.6966-0050/03
1115R8M388610AF
C1340A1-0018
VS-709-ECE-SAAN-P2/R3
VS-709-ECE-SAAN-P4/PB
VS-709-ECE-SAAN-R4/R6
VS-709-ECE-SAAN-R4/TG
CO-286W-800MHZ
404Y1366-40MHZ
Quartz_QAH004AB_4.0960MHz
Quartz_QAI020AB_20.9450MHz
Quartz_QAI049AA_49.6500MHz
C2555A1-0048
MC979X2-006W
VS-705-ECE-KAAN-693M483000
PX-7020-EA3-YXXX-4M00000000
1116C16M00000AX
VS-505-ECE-KAAN-320M000000
PX-7000-EAC-FKXX-40M0000000
MQF73.35-1500/02
MQF75.495-1500/C

PCN_NTDO-19HYTI032
Affected CPN list
MQF76.675-1500/C
MQF168.46-1400/C
MQF169.24-1400/C
MQF149.27-1400/C
MQF148.21-1400/C
MQF149.45-1400/C
TFS281A
LC120.0-2.0/03
LC120.0-3.0/03
TX-400-0008-2M04800000
1116D13M00000BX
EX-385-DAD-758F-10M0000000
CO-401A-0X-12.8MHZ
1101D40M00000BX
1101D50M00000BX
MC704A1-007
VX-501-0062-122M88
FX-500-EAT-KNNN-CL-H2
MC741A1-1009
647Y5081-2 155.52MHz
FX-402-ECE-KCNN-M3-M2
FX-402-ECE-KKNN-M4-M3
MC287X7-001W
MC287X7-008W
MQF45.0-1500/65
FX-402-ECE-KANN-D6-M3
1118R40M00000BF
MQF152.270-1400/T
1103B48M00000BX
MC704A1-004
C2555A1-0050
1104D56M00000BX
VS-705-ECE-KAAN-666M514300
PX-400-0001-16M0000000
Quartz_QAI075AA_75.9200MHz
Quartz_QAI107AA_107.8550MHz
MQF35.25-2200/06
MQF35.25-4000/06
MQF70.0-2200/06
MQF70.0-5000/21
1103R48M00000BE
400-7562-16MHZ
VX-501-0063-30M72
TFS1968
449Y3468-7M37280000

PCN_NTDO-19HYTI032
Affected CPN list
TX-502-0008-10M0
377Y1237-66M6000000
MC728A1-010_SNPB
C1470A1-0035
283-A-1-6M4
C2570A1-0040
C4720A1-0003-60M0000000
1115V50M00000BB
C2555A1-0049
1103R40M00000BX
1118R48M00000BA
VS-505-ECE-KAAN-156M250000
0422CCXX80M0000
EX-400-0004-10M0000000
VX-5090-EAE-KXXX-25M0000000
MQF100.0-1500/C
VS-705-ECE-SAAN-710M312500
FX-400-EDE-KNNN-A3-L4
TX-191-0004-12M8000000
C1470A1-0036
C1470A1-0037
568Y6205-4 @ 369.52 MHz
568Y6205-3 @ 371.8 MHz
M55310/16-B41A36M818000
4358273-30M72
Quartz_QAH006AA_6.0000MHz
1118D33M00000BX
C1405A1-0077
TFS115K
1116D40M00000AX
600-008767-2-47M447917
VX-501-0071-400M0
LC21.4-1.0/04
VC-820-EAE-KAAN-8M00000000
TX-0800-DBP-207B-8M19200000
MQF24.0-0600/03
FX-700-EAE-KNKN-E6-E6
C1460A1-0078
CO-402C-2B-50M0000000
1118R8M000000BF
PX-7003-HDE-KFXB-102M336000
356BE010M000000
ES-200-0001-320M000000
OX-200-0033-76M8000000
VX-5001-ECT-KAXX-128M125000

PCN_NTDO-19HYTI032
Affected CPN list
VX-5001-ECT-KAXX-121M875000
M55310/16-B31A4M8000000
VS-705-ECE-SAAN-647M239364
MQF73.125-1500/06
VS-705-ECE-SAAN-660M184152
LC160.0-50.0/06
M55310/16-B41C50M000000
OX-2226-EAN-1080-20M00
1115R16M00000BF
2102D48M00000VAX
2102D66M00000VAX
PX-5000-EAC-FKXX-16M0000000
PX-5000-EAC-FKXX-39M2832000
1105R31M45728BF
1105R40M00000BF
1118R1M048570AF
1118R16M00000BF
VS-705-ECE-KAAN-693M750000
MQF100.0-0400/06
VCC1-G3D-106M250000_SNPB
VCC1-B3D-133M333300_SNPB
VC-801-EAE-FAAN-50M0000000_SNPB
PX-4001-DBC-FKXX-20M0000000
PX-4001-DBC-FKXX-60M0000000
VTC1-C2AE-19M2000000
TX-550-0001-20M0000000
C5570A1-0024
401-9999A-7X-11.0592MHZ
CO-442B-2B-16.67MHZ
MC597X4-048W
VX-501-0075-156M25000
CRH741_diced_chip
CO-441A-1B-20MHZ
C5570A1-0023
VS-709-ECE-KAAN-VC/VP
74201584-001-25M000000
TFS1080C
TFS1080D
VS-705-ECE-KAAN-698M812334
VC-709-PCIE2-100M000000
VC-820-EAE-KAAN-16M0000000
16310057-21-14M599609
VS-509-ECE-KAAN-P2/R3
VS-509-ECE-KAAN-P2/P5
VS-509-ECE-KAAN-P4/R6

PCN_NTDO-19HYTI032
Affected CPN list
1105R60M00000BF
315-0099-120-9M792000
582R218H01-82M777777
582R218H02-86M388888
EX-209-CAK-758FEN-40M0000000
C1470A1-0042
810522-30-6M0
810522-30-16M0
810522-30-9M0
TFS1227B
TFS1278A
TFS1575Z
810522-30-15M0
810522-30-17M0
PX-5000-EAC-DKAX-80M0000000
1117R66M00000BF
C2525A1-0088
M55310/30-B21A40M00000
JDMGCMEP-77.76MHZ
VPB1-A1B-32M0000000
VPA1-A1A-12M00000000
VPA1-A1A-24M00000000
C1470A1-0039
C1470A1-0040
MQF29.255-1500/02
MQF38.855-1500/02
VV-800-EAE-SAAN-14M3181808
1103R13M12500BA
1103R13M12500BX
MQF71.85-2500/12
582R022H01-10M0000000
VS-705-EDE-KAAN-698M812334
VX-5090-EAE-KXBX-25M0000000
C2525A1-0089
M55310/30-B01A12M00000
C2525A1-0087
TFS850B
TFS850C
C5260A1-0066-S2-96M0
C5260A1-0066-S2-96M0
CO-718SA19WV-10MHz
805Y4089
PX-7003-HDE-FFAX-312M500000
PX-7003-HDE-FFAX-320M000000
M55310/26-B33A4M000000

PCN_NTDO-19HYTI032
Affected CPN list
C4550A2-0290-10M0000000
MC070-013
PX-7020-EA2-WXXX-460K800000
PX-400-0002-1H00000000
MQF21.4-0560/04
PX-7020-JA2-WXXX-30M0000000
TFS140W
TX-191-0007-156M250000
CO-402E-5X-20MHZ
1115D100M0000BX
1115R100M0000BA
OC-260-CAD-408CA-10MHz
OX-200-0039-10M0000000
VS-709-ECE-KAAN-P2/P5
CO-253E56-138MHZ
OX-200-0040-10M0000000
TFS192M
C1460A1-0079
1103R60M00000BF
MC794A5-001
600-100938-31-34M482809
1116R16M00000AF
PX-5000-EAC-FKXX-25M0000000
MQF70.0-5000/22
C1455A1-0005
PX-4000-DBC-FKXB-24M0000000
M55310/30-B11A25M00000
4140-019
MC537X2-002W
1103R100M00000BX
PX-7000-JAC-KSXX-24M0000000_SNPB
C1455A1-0006
TFS729
600-009260-2-4M096000
A016515-0001-25M000000
MD-0113-BXE-DAOC-10M000000
1118R24M00000BX
1118R16M77722BX
TFR993
VS-505-ECE-KAAN-155M520000
1109R60M00000BF
1109D60M00000BX
PX-500-0008-20M0000000_SNPB
PX-500-0009-28M0000000
VX-500-0009-49M1520000

PCN_NTDO-19HYTI032
Affected CPN list
VTC1-1166-19M2000000
FX-702-EDE-SMMM-NY-VX
C2555A1-0038
C2555A1-0039
C2555A1-0040
C2555A1-0041
1116R10M00000AF
1116R13M00000BF
PX-7020-EA2-WXXX-32K7680000
PX-7020-EA2-WXXX-20M0000000
C2490A1-0007
OX-200-0045-100M000000
1104C24M00000BF
1104C32M00000BF
1104C40M00000BF
1104C48M00000BF
VTD3-J32D-10M0000000
1104C56M00000BF
M55310/27-B31A64M000000
M55310/30-B31A66M000000
MX-041-0007-10M0000000
TFS2595A
TFS123D
VS-709-ECE-KAAN-P4/VC
81X-777P042-135M937500
81X-777P043-132M500000
81X-777P044-137M500000
1116D8M000000BX
VT-501-DAG-106B-10M0000000
MC929X2-012H
VS-705-ECE-KAAN-624M693800
3968-11.70816MHz
VC-820-EAE-KAAN-75M0000000
TX-1910-ECJ-4660-163M840000
EX-621-CGF-107F-30M0000000
PX-5701-0003-4M00000000
PX-5701-0004-32K7680000
MC906X5-023
600-101290-20-14M367837
TX-4004-EAE-2061-125M000000
600-101290-12-16M384000
VS-705-ECE-KAAN-720M000000
C2501A1-0039
MC639X2-002WR
38328-1-2M445120

PCN_NTDO-19HYTI032
Affected CPN list
38328-2-2M451360
VCC6-LAD-66M0000000
8005
VC-820-JAW-FAAN-25M0000000
EX-209-CAF-107FEN-16M0000000
1103D48M00000BX
1103D64M00000BX
TFS1540
TFS1643
PX-7002-EAE-KXXX-100M000000
1115B16M00000BX
SD02-SCREENING-CX00031_350g
TFS400R
VC-501-DFF-GFA-200M000000
VX-4000-DA2-FXXX-24M5760000
484Y5591-500MHZ
PX-4200-EAZ-JXFX-12M0000000
TFS1344
600-101291-22-34M767188
VX-701-0014-38M0
MC092A1-003_SNPB
OX-400-0023-20M00
FX-402-EDE-KANN-D6-M2
VX-4000-EAZ-FXXX-24M5760000
1118R24M00000BA
1118R16M77722BA
C2525A1-0094
OX-2206-EAE-5080-40M00
VX-501-0095-491M52
VS-709-ECE-KAAN-P3/TC
VV-800-EAE-KAAN-74M17458000
CO-403B-5X-64M0000000
QF4.3-0210/06
2101D20M45600VAX
QF45.0-0300/06
CO-484A-1B-303MHZ
C2570A1-0044
MQF21.4-1200/07
TFS850D
PX-999-0003-4M91520000
C1460A1-0088
VS-705-ECE-KCAN-800M000000
MQF129.5-1500/GN
LC140.5-10.0/06
373Y3623-60MHZ

PCN_NTDO-19HYTI032
Affected CPN list
1103D50M00000BX
C1470A1-0043
C1470A1-0044
C1470A1-0045
GJN999850P83-16M0
1115V33M33333AB
HETT400143P10-9M0
PX-7020-EA2-WXXX-3M68640000
TFS150AR
VT-802-EAE-2560-19M2000000
PX-5000-EAC-FKXX-8M00000000
TX-400-0014-86M4000000
TX-400-0013-96M0000000
1105E16M00000AF
1116R60M00000BF
TFS845B
600-101290-21-14M486328
TFS160T
TFS430F
1117D40M00000BX
FX-702-EDE-KMMM-HK-M8
C1405A1-0081
C1405A1-0082
C1405A1-0083
C2490A1-0031
1104R20M00000BX
1116R1M000000BF
VCC6-RCF-50M0000000
TFS350K
VC-806-EDE-FAAN-100M000000
PX-700-0028-106M250000
PX-700-0026-100M000000
PX-700-0027-125M000000
CO-441A-0X-2MHZ
MQF73.35-2500/02
PX-7003-HDT-SXAX-200M000000
C1460A1-0091
1105D12M00000AX
1105D16M00000AX
OX-2002-EAJ-2581-20M0000000
1117R40M00000BF
1116D500K0000AX
1116R500K0000AF
1103R100M00000BF
PX-4001-DBT-KFXX-16k0000000

PCN_NTDO-19HYTI032
Affected CPN list
TQ3330S-3M6864
TFS850A
TFS820A
OX-4011-EAE-1080-20M00
C1460A1-0096
FX-702-EDE-KMMM-J9-L4
C1460A1-0097
725016A1084-3-75M000000
2102D10M00000KAX
JDUGLMUP-160MHZ
1118R40M00000BD
C1340A1-0020
VS-705-ECE-SAAN-690M569196
VS-705-ECE-SAAN-704M380580
CO-484V-LX-70MHZ
MQF70.0-3200/06
OX-4052-DAE-5070-111M111111
1103R48M00000BF
1103R48M00000BX
LC150.0-10.0/06
LC160.0-10.0/06
LC169.0-10.0/06
LC154.75-37.9/07
C2570A1-0045
C4540A1-0035
OX-170-0042-10M0000000
2511-2-9.969MHz
Quartz_QAH010AA_10.021875MHz
C1460A1-0086
C1460A1-0087
EX-209-CGD-107AEN-38M6560000
TFS1019A
TFS1091A
TFS1555B
TFR1748A
TFS2062
VXM7-1D1-25M0000000
C1555A1-0013
PX-500-0011-64M0000000
EX-400-0008-20M000000
PX-7020-DA2-WXXX-4M91520000
C5570A1-0026
C5570A1-0025
MC042X1-105_SNPB
TFS1320

PCN_NTDO-19HYTI032
Affected CPN list
6041-10M0000000
C5116A1-0011
PX-5000-EAE-FSAX-40M9600000
VCC6-1300-100M000000
C1999A1-0007
PX-7020-JA3-YXXX-7M37200000
MQF70.0-4000/13
TFS134D
TFS160U
C5300A1-0003_SNPB
CO-448A-2B-5MHZ
CO-448A-2B-5MHZ
PX-5000-EAC-FSAX-20M0000000
PX-3400-DAC-DKXX-512H000000
TFS1968A
PX-3400-DAC-DKXB-512H000000_SNPB
TFS2457
VCC1-B3R-100M000000
VCC1-B3R-25M0000000
0424ATX25M6000000
CO-645V-E-125MHz
OX-170-0043-12M8000000
OX-170-0044-15M3600000
VS-709-EDE-TAAN-P4/VC
MQF10.0-0320/07
MX-041-0012-10M0000000
TFS1575AA
1111D24M00000AX
VCC1-B3R-40M0000000
1117D16M00000AX
1117D16M00000BX
1117R16M00000AA
1117R16M00000BA
VCC6-RCF-100M000000_SNPB
M55310/19-B11A32M00000
1103R40M00000BA
C1555A1-0012
566Y3365-2-32MHz
FX-702-EDE-KMMM-KH-M8
OX-220-0072-16M00
1102R10M00000AF
C1460A1-0092
C1460A1-0093
C1460A1-0094
C1460A1-0095

PCN_NTDO-19HYTI032
Affected CPN list
1103R32M00000BF
1103D32M00000BX
OX-2221-EAJ-1080-38M88
TFS150AX
OX-2022-EAE-1080-20M0000000
C2400A3-0120
1116R20M00000BX
TX-502-0022-6M400000
OX-403-0001-20M00
OX-220-0075-10M00
TFS822
C5555A1-0018
MQF21.4-3000/52
MX-0410-BEJ-4001-10M0000000
JDBGLMUB-155.52MHZ
EX-245-CAD-107FSS-38M1900000
OX-4022-EAE-1080-20M00
C2555A1-0056
JCUHCMEP-148.764MHZ
TFS170T
VC-501-ECE-KXCN-100M000000
VC-501-ECE-KXCN-200M000000
VC-501-EAJ-KXCN-100M000000
VX-4000-0005-32M7680000
MQF70.0-0500/09
4140-008
TFS1158
TFS130D
MQF21.4-3000/62
VC-709-ECW-KAAN-25M0000000
1103D18M75000BX
VC-501-ECT-KXCP-300M000000
MQF130.05-2100/01
MQF110.2-2000/10V1
EX-4000-EAE-1073-20M0000000
1108D24M00000AX
PX-5701-0006-4M00000000
OX-0450-BEJ-5091-10M0000000
VC-820-EAE-KAAN-10M0000000
MQF21.4-2500/07
VCC1-G3R-25M0000000
1105R33M00000BF
647Y5081-2 166.6285MHz
PX-4000-DAT-KFXB-3M00000000
PX-4200-EA2-WXXX-7M50000000

PCN_NTDO-19HYTI032
Affected CPN list
TRU050-GALGB-38M8800000
TFS174L
C1460A1-0100
TFS416A
MQF45.0-1500/67
C1460A1-0101
OX-4033-EAE-1080-20M00
PX-7000-EAC-DSXB-10M0000000
CO-434V-BX-160MHz
PX-4001-DBA-BKXX-6M14400000
MC639X2-008EM
TFS1643A
1118D25M00000BX
1116D66M00000BX
PX-700-0031-1M84320000_SNPB
VS-705-ECE-KAAN-748M070900
TFS87F
0428DCEX12M00000
VXA4-300-3M68640000
VXA4-300-4M00000000
VXA4-300-4M19430400
VXA4-300-4M91520000
VXA4-300-8M00000000
VXA4-300-9M83040000
VXA4-300-11M0592000
VXA4-300-12M0000000
VXA4-300-14M7456000
VXA4-300-16M0000000
VXA4-300-18M4320000
VXA4-300-20M0000000
TFS850E
M55310/28-B24A40M96000
M55310/28-B11A15M360000
TFS850F
OX-4051-DAE-3072-100M000000
VL-821-JAE-KAAN-30M0000000
C1460A1-0102
PX-4200-EA2-WXXX-4M00000000
PX-4200-EA2-WXXX-100M000000
MQF76.8-0800/01
VCC6-RAD-121M109000
C1405A1-0080
MD-011-0014-10M00000000
QF20.0-0050/06
QF60.0-0100/04

PCN_NTDO-19HYTI032
Affected CPN list
600-009584-1-4M096000
600-009572-1-15M354444
VX-5001-ECE-GXXX-491M520000
2102D24M00000VAX
2102D20M00000VAX
MQF45.0-10000/02
EX-245-CAD-107FSS-38M1915150
TFS125P
TFS125R
VC-706-ECE-FAAN-159M375000
OX-200-0073-10M0000000
MX-0410-DAT-2001-10M0000000
0425DXX80M0000
MQF73.35-1500/06
VC-501-ECE-KXCN-250M000000
PX-500-0012-20M0000000_SNPB
2102B50M00000YAB
TFS2595C
FX-104-DFC-S6230G
FX-104-DFC-S6231G
484Y2225-1-88.75MHZ
484Y2225-1-361.25MHZ
VC-806-ECE-FAAN-50M0000000
OX-170-0049-100M000000
0428ATXB32M00000
C1470A1-0046
C1470A1-0048
CO-447B-2B-29.4912MHZ
600-009573-1-36M850667
C1460A1-0105
PX-7001-ECT-KSCX-100M000000
PX-7000-EAC-DSXB-20M0000000
MQF10.0-0320/09
TDX1227
TX-5500-EAE-106B-81M9200000
PX-7020-EA2-UXXX-40M0000000
C1405A1-0086
C1405A1-0087
C1405A1-0088
C1405A1-0089
C1405A1-0090
TFS1227C
C2555A1-0060
VX-4000-DA2-FXXX-24M5686000
1116D4M194304BX

PCN_NTDO-19HYTI032
Affected CPN list
1103D10M00000BX
M55310/19-B03A1M000000
TFS63F
FX-700-EAE-PNKA-A9-D6
CD-700-EAE-SANA-12M8000000
442Y5938-4.096MHz
566Y5930-21.4MHz
566Y5930-18.4MHz
C1460A1-0107
C5555A1-0025
TFS127D
TFS63G
PX-7020-EAY-WXXX-32K7680000
OX-400-0033-20M00
OX-0420-BEE-3083-10M0000000
352Y4987-720MHz
TFS1220H-BIN
TFS482B
C1555A1-0018
C1555A1-0019
1103C20M00000BX
6175-4M194304
TX-700-0048-20M0
OX-4022-EAE-1080-10M00
OX-4022-EAE-1080-10M00
TFS180L
C2555A1-0061
2102D48M00000AAZ
C5555A1-0028
PX-7020-EA5-UXXX-32K7680000
PX-7020-EAY-UXXX-1M00000000
PX-7020-EAY-UXXX-32K7680000
VCC1-B3F-36M8640000
1104R20M00000BF
16S31A4M000000
1116C33M33300BX
1116R33M33300BF
C1555A1-0014
C1555A1-0015
C5555A1-0020
C5555A1-0021
C5555A1-0022
C5555A1-0023
OX-200-0079-10M0000000
PX-700-0036-156M250000

PCN_NTDO-19HYTI032
Affected CPN list
1105D50M00000BX
VCC1-B3R-72M0000000
VC-801-EAE-FABN-25M0000000
484Y2226-1-228.00MHz
VT-803-EAE-5070-50M0000000
TFS770H
1102R50M00000BF
TFR2400
TX-3200-EAA-156A-10M0000000
MQF70.2-1100/02V4
TFS1584
TFS1590A
TFS125S
PX-500-0013-48M0000000
VT-802-EAE-5060-40M0000000
C1999A1-0008
OX-200-0084-20M0000000
C2555A1-0053
C4550-F207-SV050-RFS-A2-0-96M500
1102D50M00000BX
C1460A1-0109
C1340A1-0024
CO-408C-1X-10M0000
TFS70BR
1105D16M00000BX
VS-705-ECE-KAAN-480M000000
312A3331P1-8M000000
FX-402-ECE-SBNN-C4-K9
1109B4M000000AX
TFS1538
VS-705-ECE-KCAN-983M040000
1115R4M096000AF
VV-701-EAE-KKAB-10M0000000
PX-489-0001-48M00000
PX-489-0002-64M00000
TFS1905
PX-7020-EA3-YAXX-14M7456000
C1460A1-0110
C1460A1-0111
PX-5000-EAC-FKAX-50M0000000_SNPB
VC-709-HDE-KAAN-100M000000
VC-709-EDE-KAAN-125M000000
PX-369-0004-30M00000
PX-369-0005-100M0000
TFS200N

PCN_NTDO-19HYTI032
Affected CPN list
VCC6-VAP-200M000000
OX-0431-AEE-3083-10M0000000
MC092A1-002 SNPB
C1460A1-0108
TFS939
SM-S433L-G-Standard
SM-S436-G-Standard
SM-S435-G-Standard
SM-S432-G-Standard
SM-S431-G-Standard
SM-S429-G-Standard
1103D45M00000BX
EX-209-CGF-107FEN-10M0000000
VC-801-EAE-KABN-14M3180000
VC-801-EAE-KABN-100M0000000
PX-5000-EAE-KXAB-96M0000000
1105D10M00000BX
1105D25M00000BX
1109D6M000000AX
MC347X5-038
PX-369-0006-125M0000
VX-209-0001-80M00000
TX-209-0001-80M00000
CO-401A-2D-32MHZ
FX-700-EAE-KNKA-C4-E2
PX-489-0003-20M00000
VX-705-ECE-S6408-122M880000
MQF40.0-0600/03
MCO1610B-42M0
TFS499B
VS-705-ECE-KAAN-838M860800
MQF118.3-1500/GN
TFS1540A
600-100938-6-34M804688
1103R10M00000BF
PX-4001-DBT-KFXX-16M3840000
TFS698
TFS1191
TFS1542A
EX-209-0003-10M0000000
PX-369-0009-32M00000
VC-806-0001-156M250000
PX-7020-DA2-WXXX-20M0000000
TFS178
EX-4001-DAE-1070-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
EX-209-0005-37M5000000
EX-209-0006-37M5000000
MC623X2-026E
OX-2022-EAJ-1080-20M0000000
487Y5971
TFS869L
PX-7020-0040-24M0000000
1115D10M00000BX
PX-7020-EAY-YXXX-20M0000000
C2525A1-0095
OX-1702-EAE-1081-26M0000000
CO-484C-1X-10MHz
MD-023-0002-10M0000000
VCB2-B3D-50M0000000
MX-041-0017-10M0000000
1101R50M00000AF
PX-7020-EA5-WXXX-32K7680000
VX-5090-DAE-GXXX-16M0000000
MQF100.0-2400/09
MQF21.4-2000/33
TFS70BT
VX-189-0001-914M285714
VX-189-0002-914M285714
OX-2031-DEE-8241-10M0000000
255-8494
BV5107-9701.004-12M0
3BDC750000R0001-12M0064
TX-5500-DFJ-507A-40M0000000
TX-249-0009-104M448000
PX-489-0004-48M00000
1104V48M00000BX
PX-209-0001-500M000000
1101D80M00000BX
1101R80M00000BF
PX-5000-EAC-DKXX-10M0000000
PX-7003-HDC-PXXB-80M0000000_SNPB
C2555A1-0052
PS-709-ECU-SANN-P4/VC
C2525A1-0099
TFR873
C2998A1-0002
TFS1064
TX-209-0002-80M00000
VX-209-0004-80M00000
EX-209-CAF-107FEN-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
OX-200-0097-10M0000000
VT-803-EAE-287A-25M0000000
CO-402B-2B-1.44MHZ
TFM315P
TX-999-0001-14M3181800
PX-489-0005-7M0000000
724Y4748-400MHz
MX-041-0018-10M0000000
VXA4-300-6M00000000
MQF20.208-3200/06
972368-1-12M0000000
EX-380-CAD-ST3F-77M7600000
MQF191.0-2000/04
VC-715-DFF-GFA-47M8500000
CO-487A-OXR-370MHZ
PX-999-0004-4M91520000
1118X25M00000BA
1105D27M84000BX
1105D22M66000BX
PX-7020-0042-16M0000000
PX-7001-HDC-PXXX-128M0000000
PX-7001-HDC-PXXX-125M0000000
MQF43.0-2500/04
MQF52.55-2500/04
MQF75.0-2500/04
1118D20M00000BX
1116D48M00000BX
PX-489-0006-20M000000
PX-489-0007-6M0000000
C1340A1-0021
C1340A1-0022
TFS174M
301-1030-002-12M0000000
1104D96M00000AX
TX-249-0010-50M00000000
1103C100M0000BB
TFS836G
TFS1732A
TFS1880D
EX-209-CGF-157FEN-40M00000000
EX-209-CAF-107AEN-16M3840000
EX-209-0008-40M00000000
OX-2031-DAE-8240-10M00000000
MQF73.35-1500/07
VC-709-ECE-FAAN-48M00000000

PCN_NTDO-19HYTI032
Affected CPN list
TFS1575ADS01_FM
OX-2201-EAE-1081-10M00
205422102-10M475
TFS35GS01_FM
205422103-10M925
TFS35GS01_LVT_Subgroup_1
OX-220-0096-30M72
TFS1575AC
TFS1575AD
PX-5701-0007-3M68640000
TFS35G
PX-7020-EA2-SXXX-32K7680000
011126-0503-A-10M000000
CRH520_diced_chip
81X-776P020-126M000000
81X-777P029-139M333333
81X-778P010-146M000000
81X-777P028-132M666667
81X-775P019-119M333333
TFS2490
TFSS428
TFSS429A
TFSS430A
TFSS431A
TFSS433R
TFSS434D
TFSS435A
TFSS437
TFSS438A
TFSS438B
OX-5011-EAE-2080-20M00
TFD60H
TX-249-0014-50M0000000
289-7128-090-5M529600
TFS90G
TX-5500-EAE-106A-10M0000000
OX-5011-EAE-2080-12M8
TFS1047
C1470A1-0049
OX-170-0068-10M00000000
PX-700-0044-20M0000000_SNPB
TFS1575DS01_EQM
C1405A1-0076
C1405A1-0091
FX-702-ECT-HMMM-E2-M1

PCN_NTDO-19HYTI032
Affected CPN list
TFS1920A
FX-702-ECT-HMMM-D6-M2
VX-4000-0007-24M5785000
VX-4000-0008-24M5686000
MQF10.0-2000/08
PX-7020-0046-20M0000000
VX-501-0109-100M0
TX-999-0002-14M3181800
TX-249-0015-10M00000
EX-4202-EEJ-7584-10M0000000
TFS36K
6338-51.2MHz
OX-990-0031-120M00
OX-990-0031-120M00
VS-709-ECE-KAAN-V8/R5
MQF71.64-5000/07
1103D51M98937BX
1118R50M00000BF
TFS782A
EX-400-0012-10M0000000
MQF110.2-2000/10V2
442Y1189-4MHZ
PX-369-0021-75M00000
TX-500-0050-100M0
TX-500-0050-100M0
TFR804
TFS1526
VCC6-1307-33M3330000_SNPB
TX-8010-EAE-2870-12M800
TX-8010-EAE-2870-12M800
C1405A1-0093
MQF50.0-8000/07
Quartz_343/01_94.0210MHz
Quartz_343.1/06_87.5800MHz
CO-402A-OX-20MHZ
PX-700-0050-125M000000
EX-4000-EAE-1073-10M0000000
1118R24M57600BF
1118R10M00000BF
OX-400-0041-25M00
1115R100M0000BF
TX-249-0016-20M0000000
VX-501-0161-1200M1
TX-249-0019-100M000000
MQF52.0-0600/03

PCN_NTDO-19HYTI032
Affected CPN list
TFS1220K
OX-4050-DEE-2072-100M000000
TX-5500-EAE-106A-20M0000000
C5116A1-0012
1115R33M33333AF
5116D40M00000BX
623TJ48M00000EN
EX-380-CAF-ST3A-20M0000000
TFS70BHS01_FM
TFS70BHS01_QM_Endurance_Subgroup
TFS256A
VS-505-ECE-KAAN-200M000000
VS-505-ECE-KAAN-240M000000
VS-505-ECE-SAAN-669M326600
VS-705-ECE-KAAN-531M250000
TFS890A
PX-5701-EA2-UAXX-32M0000000
TFS35GS01_LVT_Subgroup_2
TFS35GS01_LVT_Subgroup_3
TFS84S01_EQM
TFS1575AES01_QM_Env/Mech_SGA
TFS1575AES01_QM_Env/Mech_SGB
TFS1575AES01_QM_Endurance_SG
PX-508-0005-120M00
TFS1575AES01_QM_AssCap_Sold_SG
TFS1176CS01_QM_Environ/Mech_SG_A
TFS1176CS01_QM_Environ/Mech_SG_B
TFS1176CS01_QM_Endurance_SG
TFS1176CS01_QM_AssCap_Sold_SG
TFS1227ES01_QM_Env/Mech_SGA
TFS1227ES01_QM_Env/Mech_SGB
TFS1227ES01_QM_Endurance_SG
TFS1227ES01_QM_AssCap_Sold_SG
13012-0391-16M000000
VS-709-ECE-SAAN-W6/W7
VS-709-ECE-SAAN-W6/W8
044-00072-0000-52M600000
CO-401A-2B-10MHZ
TFS499C
SM_S428_12G_Standard_BM2
SM_S429A_12G_Standard_BM2
SM_S430A_12G_Standard_BM2
SM_S431A_12G_Standard_BM2
SM_S433R_12G_Standard_BM2
SM_S434D_12G_Standard_BM2

PCN_NTDO-19HYTI032
Affected CPN list
SM_S435A_12G_Standard_BM2
SM_S437_12G_Standard_BM2
SM_S438A_12G_Standard_BM2
SM_S438B_12G_Standard_BM2
M55310/16-B34A9M830400
PX-7000-EAE-KXAB-40M0000000_SNPB
PX-489-0009-4M000000
TFS70BHS01_LAT_Electrical_SG
TFS240W
TFS1390
1103R50M00000BF
VX-701-0029-100M0
VC-820-EAE-SAAN-4M00000000
FX-702-EDE-KMMM-H8-L4
TFS460F
VCC1-B3R-125M000000
PX-7020-EAY-WXXX-32M0000000
TFS1200A
TX-801-0007-24M576
TFS1220L
CRH403_diced_chip
TX-249-0022-24M5000000
PX-7020-JA1-VXXX-7M37280000
OX-4053-DEE-2070-100M000000
VCC1-B2C-66M0000000
TFS35AS04_EQM
VS-709-EDE-KAAN-P4/VC
TFS70AXS01_Package_Eval
TFS70BX
OX-5011-EAE-2080-10M00
TFS156D
TFS890
MC794A5-182
VS-509-ECE-SAAN-P2/P4
VS-509-ECE-SAAN-R3/R4
1104D75M00000BX
0429ACXB12M0000_SNPB
1118R10M00000BX
1118R24M57600BX
1116E66M00000BF
1116B66M00000BX
VX-369-0001-16M0000000
C1460A1-0114
C1460A1-0115
1204R100M00000BF

PCN_NTDO-19HYTI032
Affected CPN list
1204C100M0000BX
QBS9.7-0600/06
1220R125M0000BF
1220D125M0000BX
TX-5500-EAE-106B-40M0000000
TFS1621B
1116X19M66080BA
1107R20M00000BF
PX-5701-E131-32K7680000
0429ACXB12M0000
M55310/30-B24A40M00000
PX-369-0024-16M3840000
QF2.76635-0275/07
QF2.7648-0600/07
QF2.7648-1600/07
2104D100M0000KAX
0425ACEX16M00000
M55310/21-B11A16M38400
1116R96M00000BF11
1116R96M00000BF21
1116R4M194304BF11
TX-550-0002-40M0000000
PX-7020-0053-32K7680000
OX-2040-BEE-2085-10M0000000
TFS1687
PX-5701-0009-16M0000000
OX-2040-BEJ-2082-10M0000000
PX-7000-EAC-PXXB-32M0000000
311204253-100M000
TX-189-0003-382M160000
TX-189-0004-383M080000
PX-7020-JA5-WXXX-4M09600000
1116R1M152000BX
1103R51M98937BF
2102R25M16580WAS
CRH495_diced_chip
CRH480D_diced_chip
TX-249-0024-97M6500000
TX-249-0025-70M2343750
OX-4050-DEE-5082-100M000000
TFS115D
VS-709-ECE-SAAN-VC/VP
TFS1228A
1116R4M194304BF21
C1460A1-0116

PCN_NTDO-19HYTI032
Affected CPN list
CO-402V-LX-9.1968MHZ
MQF45.0-1600/02
PX-7020-0054-3M68640000
MQF45.0-0750/31
MQF45.0-2500/17
MQF45.0-2500/18
TFS135G
VX-701-0015-40M0
PX-7020-EA5-VAXX-20M0000000
PX-7020-EA5-VAXX-32K7680000
OX-2050-BEJ-2075-100M000000
OX-2050-BEJ-2075-100M000000
OX-2050-BEJ-1075-100M000000
OX-2050-BEJ-1075-100M000000
VC-801-EAE-FABN-27M0000000_SNPB
VC-801-EAE-FABN-25M0000000_SNPB
VC-801-EAE-FABN-28M6363600_SNPB
VC-801-EAE-FABN-65M0000000_SNPB
VC-801-EAE-FABN-100M000000_SNPB
OX-2050-BEE-2072-100M000000
XR-P111-1CE-EEAX-27M0000000
PX-7020-DA5-WAXX-40M0000000
PX-7020-DA5-WAXX-4M00000000
PX-7020-DA5-VAXX-40M0000000
PX-7020-DA5-VAXX-4M00000000
PX-7020-EA6-YXXX-40M9600000
1102R16M38400AF11
1102R16M38400AF21
1102R16M38400BF11
1102R25M00000BX01
1102R25M00000BF11
1102R25M00000BF21
1108D12M00000AX01
1108R12M00000AF11
1111R48M00000AX01
1111R48M00000AF11
1111R48M00000AF21
1116R24M00000AF11
1116R40M96000BF11
1116R48M00000BF11
1116R48M00000BF21
1116R58M72026BF11
1116R70M00000BF11
1116D80M00000BX01
1116R80M00000BX01

PCN_NTDO-19HYTI032
Affected CPN list
1116R80M00000BF11
OX-200-0111-20M0000000
EX-4002-EEE-1075-10M0000000
TFS1965
OX-2221-EAE-1080-25M00
OX-5011-EAE-2080-25M00
VX-501-0175-122M88
VS-709-EDE-SAAN-P4/VC
PX-500-0022-33M0000000
TX-8010-EAE-2870-10M0
TX-8010-EAE-2870-20M0
TX-8010-EAE-2870-25M0
TX-8010-EAE-2870-25M0
TFS1220M
1103D24M00000BX
1102D25M00000BX01
TFS134E
FX-702-EDE-SMMM-L4-L4
TX-209-0003-80M00000
PX-369-0025-125M0000
VX-209-0009-80M00000
VX-501-0176-320M0
1116D1M000000BX
PX-509-0002-300K000000
044-00292-0000-107M777700
OX-4033-EAE-1080-12M80
1103R50M00000BX
PX-7020-EAZ-WXXX-40M0000000
1103R40M00000BF
1102E80M00000BF
850-2529-070-111M716700
850-2505-010-9M830400
OX-2040-BEJ-1083-10M000000
1118R8M192000BF
1118R14M74560BF
PX-7020-EA2-VXXX-10M0000000
VC-801-EAE-FABN-100M000000
VC-801-EAE-FABN-28M6363600
VC-801-EAE-FABN-65M0000000
1117B16M00000BX
1116X9M830400AX
1116R9M830400AF
1116D600K0000AX
PX-7020-DA2-VXXX-2M45760000
MQF10.7-3000/35

PCN_NTDO-19HYTI032
Affected CPN list
VS-705-ECE-KCAN-794M727753
VC-801-EAE-FABN-27M0000000
PX-500-0023-33M0000000
PX-349-0002-32M0000000
PX-349-0003-48M0000000
PX-349-0004-1M27000000
PX-349-0005-25M0000000
1118R38M40000BF
PX-3690-EAC-SSXC-110M000000
538665-4-100M113000
TX-503-0002-22M1184
MC091A1-068E
OX-220-0106-10M0
PX-5001-ECE-EFBB-48M0000000
PX-5701-EA2-SXXX-512K000000
5116D50M00000BX
FX-500-EAE-KNNN-A3-E6
MQF21.4-10000/12
MD-023-0003-10M0000000
2104D85M00000YAX
1104D20M00000BX
1104D25M00000BX
C1460A1-0112
PX-5701-0010-20M0000000
PX-420-0013-66M4300000
PX-420-0014-75M0000000
2113D240M0000YCX
EX-209-0010-10M8570000
MQF21.4-4000/21
VCC6-QAP-212M500000
1118R20M00000BF
1204B125M00000BX
VC-801-JAC-KAAN-37M0000000
OX-4050-EAT-2582-100M000000
MQF152.970-1400/T
MQF153.910-1400/T
TFS2535D
1109R24M00000BF
1103R19M98848BX
972368-0011-8M000000
PX-4200-DA6-YXXX-4M00000000
PX-7020-0055-40M9600000
1116R600K0000AF
MQF17.75-2000/03
TFS807

PCN_NTDO-19HYTI032
Affected CPN list
TFS856
TFS772A
PX-7020-EA6-YXXX-7M37200000
EX-4000-EAA-1073-10M000000
VK-N7.1K_SCREW_CORE_F100b
VK-N5.1K_THRUHOLE_5-pole
VK-IND_CER_120nH_10pct._1008
VK-N5.1K_SCREW_CORE_F100b
VK-N5.1K_SCREENING_CAN_TINNED
VK-N7.1K_THRUHOLE_2-pole
VK-N7.1K_Spule_Abschirmbecher
VK-7V1K_THRUHOLE_5-pole
1103R19M98848BF
1101R49M15200BF
VK-PMSS_43.2x14.2x1.1_05P_GM29
VK-PMSS_34.5x25.6x1.3_04P_GM11.2
VK-PMSS_36.7x16.6x1.4_06P_GM1_SF
VK-CMOS_11.5x11.0x8.5_GV2.1
VK-CMOS_14.8x14.8x11.8_GV4
VK-CMSS_24.3x13.4x9.9_GM3
VK-CMSS_44.1x15.0x11.9_GM29
VK-CMSS_35.6x26.8x18.0_GM11.2
VK-CMSS_57.8x16.9x13.7_GM7.1
VK-CMSS_37.9x18x12.7_GM17_SF
VK-PCB_GS3-01
VK-PCB_2432-02
VK-PCB_GS20-01
PX-7020-EA6-YAXX-5M00000000
PX-5701-EA2-SXXX-20M0000000
PX-5701-EA2-SXXX-24M0000000
TFS1300A
PX-7021-0057-10M00000000
OX-201-0014-12M8
1101R10M00000AX
1101R8M000000BX
1101R33M17760BX
1103R2M097100BF
1101R10M00000AF
1101R14M74560BF
1101R33M17760BF
1101R8M000000BF
TX-5500-EAE-106A-50M0000000
044-00221-0001-121M111100
TX-309-0006-38M1900000
VK-N5.1K_THRUHOLE_2-pole

PCN_NTDO-19HYTI032
Affected CPN list
PX-7020-EA2-WXXX-512K000000
PX-7020-EA2-WXXX-7M37280000
TFS733
TX-550-0003-13M0000000
TX-550-0004-19M4400000
PX-7020-EA5-WXXX-16M0000000
PX-369-0030-24M0000000
VK-PMSS56.5x15.4x3.1_06P_GM7.1SN
VS-705-ECE-KAAN-240M000000
MC741A1-161
TX-8010-EAE-2871-10M000
C555A1-0019
PX-4200-0015-7M19500000
PX-4200-0016-7M15000000
TFS788
1117D24M00000BX
1102D80M00000BX
TFS87FM01
MQF70.0-3000/17
CO-254B27RW-60MHZ
TX-801-0016-19M200
TX-801-0016-19M200
OX-2040-BEE-2083-10M000000
VV-701-1045-25M0000000
PX-7020-EA2-WXXX-8M00000000
PX-5701-JA3-YXXX-4M00000000
VX-705-ECE-KXAN-100M000000
TX-5500-EAE-106B-19M2000000
OX-4053-DEE-5082-100M000000
CO-434B-1B-500MHZ
VCC1-1537-114M285000
TFS809A
TFS70YM01
1101D100M00000BX
PX-409-0011-16M00000000
PX-409-0012-27M8400000
CO-233FW-L2 at 57.985188MHZ
TFS70AWM01
TFS70AUM01
TFS460GM01
TFS460FM01
TFS1390M01
TFS115AM01
TFS70ATM01
PX-7020-EAZ-UXXX-32K7680000

PCN_NTDO-19HYTI032
Affected CPN list
1103C100M0000BC
2113B240M0000YCC
TFS368A
CO-441A-1X-88.500MHZ
OX-170-0083-10M0000000
TDX772A
PX-7003-HDE-KKXX-80M0000000
0425DTEX32M0000_SNPB
1116D85M00000BX
1111D40M00000AX
OX-405-0003-100M0000000
HM-4201-RTCM1
HM-4201-RTCM2
C2570A1-0046
TX-249-0026-128M281250
FX-700-1001-E6-E6
OX-2050-BEE-2075-100M0000000
VT-822-EAE-2560-25M0000000
1103C100M0000BX
PX-7000-DAC-SSXB-1M00000000
1304D200M0000BX
1304D156M2500BX
1319D250M0000BX
C1300A1-0227
C1300A1-0229
MD-173-0001-5M00000000
1103B100M0000BC
EX-209-CAF-107FSS-12M0000000
OX-170-0084
VCC6-LAP-156M250000
VCC6-LAP-200M000000
044-00107-0000-12M800000
MO-9000AE-9E-XXX-000.FP0000
PX-369-0032-75M00000
MO-9000AE-7E-XXX-000.FP0000
1304R200M0000BF
VS-705-ECE-KAAN-1G00000000
VS-709-ECE-UAAN-P4/VC
PX-369-0033-24M0000000
0425DTEX20M0000_SNPB
0425DTEX02M0000_SNPB
MO-9000AE-6E-XXX-000.FP0000
VCC1-B3P-80M0000000
TX-5500-EAE-106B-74M1000000
TX-249-0027-101M893750

PCN_NTDO-19HYTI032
Affected CPN list
PX-3690-EAC-SSSK-125M000000
MO-9200AE-C3F-XXX000.FP0000
MO-9200AE-C1F-XXX000.FP0000
MO-9200AE-D1F-XXX000.FP0000
MV-9300AE-6F-XXXX-000.FP0000
MV-9400AE-C3F-XXXX000.FP0000
MV-9400AE-D3F-XXXX000.FP0000
MO-9000AE-9F-XXX-000.FP0000
MO-9000AE-7F-XXX-000.FP0000
MO-9000AE-6F-XXX-000.FP0000
MO-9000AE-4F-XXX-000.FP0000
MO-9000AE-2F-XXX-000.FP0000
442Y1189-1MHZ
EX-209-0013-16M3840000
EX-209-0014-16M3840000
TFS131
PX-7020-JAY-UAXX-3M68600000
PX-7020-HAY-UAXX-7M37280000
VK-N5.1K_SCREW_CORE_F10b
OX-204-0005-10M0000000
010854-0577-D-10M000000
TRU050-GBECA-44M7360000
PX-7020-DAZ-UXXX-8M00000000
VS-705-EDE-SAAN-500M000000
TFS125T
TFS1280M01
600-101290-25-14M843099
511126-0508-B-10M000000
1204D125M0000BX
1204R200M0000BF
MQF21.4-0900/10
TX-5500-EAE-507A-10M0000000
PX-7020-JAY-SAXX-3M68600000
PX-7020-HAY-SAXX-7M37280000
VT-800-EFE-1060-10M0000000
M55310/30-B11A16M00000
CD-700-EAE-SBNN-18M4320000
PX-4200-DAZ-SXFB-4M00000000
TFS725B
M55310/16-B21A307K2000
PX-4000-DAT-FKXB-22M0000000
PX-7020-HA2-VXXX-4M00000000
PX-489-0010-20M0000000
PX-489-0011-33M3333300
1103D100M0000BX

PCN_NTDO-19HYTI032
Affected CPN list
OX-400-0047-40M00
PX-369-0035-110M000000
TFS169F
MV-9300AE-3F-XXXX-000.FP0000
MV-9300AE-1F-XXXX-000.FP0000
MD-403-0001-30M72
PX-369-0036-24M0000000
M55310/16-B44A64M00000
TFS1255
TFS723
PX-7020-EA3-YXXX-3M68640000
PX-7020-0061-8M00000000
1103D33M33333BX
1117R24M00000BF
VS-709-ECE-KAAN-V8/VC
OX-3050-BEE-2075-100M000000
OX-170-0086-20M0000000
PX-4000-DAT-FKXB-22M0689700
OX-405-0005-100M000000
MQF21.6285-5000/04
FX-703-ECT-KMMM-M3-M4
1204D106M2500BX
TC-400-DBF-156A-115M200000
1F95133-1-3M579545
113-02-0035-2M513920
VK-PMSS_24.4x13.4x1.3_04P_GM3_SN
OX-4050-DAE-2070-112M000000
MO-9000AE-7K-EE-50M0000000
TX-209-0004-64M0000000
VC-820-EAE-KAAN-24M0000000
VC-820-EAE-KAAN-24M0000000
VC-806-ECE-FAAN-25M0000000
TX-249-0028-35M2187500
TX-249-0029-37M0390625
TX-249-0030-37M0390625
VC-801-EAC-KAAN-100M000000
850-2514-020-73M393300
850-2514-010-73M413300
CO-233FW-200MHZ
1204D200M0000BX
1116D37M50000BX
TX-189-0006-40M0000000
VT-803-EAE-106B-10M0000000
TFSS433S
VX-501-0135-153M6

PCN_NTDO-19HYTI032
Affected CPN list
PX-5701-EA1-SXXX-32K7680000
PX-369-0039-32M0000000
600-101290-3-8M320000
600-101290-1-9M728000
600-101290-2-12M160000
MQF50.0-1500/09
VC-820-EAE-KAAN-20M0000000
600-010366-1-100M000000
1104R100M0000BF
1116R6M500000BF
1116R66M66666BF
1319R250M0000BF
1103D30M00000AX
PX-369-0028-156M250000
MQF21.4-4000/20
OX-221-0074-30M72
TX-249-0031-104M448000
TX-249-0032-104M448000
1108R24M00000AF
1105R25M00000BF
TX-704-0013-20M0
VC-806-0003-125M000000
VC-806-0004-100M000000
VC-806-0006-108M000000
233Y4225-2-192MHz
TX-5500-EAE-106B-100M000000
PX-5701-E150-16M0000000
PX-5701-E150-8M00000000
PX-7000-EAC-DKCX-60M0000000
1118R66M66666BF
1102D26M00000BX01
2102C8M192000KBX
2102C40M00000KBX
MX-060-0001-10M0000000
MC622X2-004EM
OX-2040-BEE-2082-10M0000000
PX-4000-DAT-KSXX-1M00000000
MO-9000AE-6F-ES-25M0000000
VCC6-1316-156M250000
PX-5701-DAZ-UXXX-8M00000000
PX-7000-EAE-KKAB-40M0000000
PX-7020-0063-8M00000000
PX-5701-0011-32K7680000
MQF120.325-1500/GN
MQF121.75-1500/GN

PCN_NTDO-19HYTI032
Affected CPN list
VC-801-EAC-KAAN-27M0000000
VC-806-0005-212M500000
PX-7020-0064-16M0000000
MC066A1-024
VS-709-ECE-KAAN-VC/V8
TFS1255A
VTA1-5011-60M0000000
PX-7020-EAY-SXXX-25M0000000
PX-507-0003-10M0000000
QF45.0-35000/06
407Y2541-3.6864MHZ
407Y2542-16MHZ
407Y2543-32MHZ
VC-806-0007-125M000000
PX-7020-E120-12M0000000
600-010366-EM-100M000000
TFS1881
M55310/16-B21A1M440000
M55310/16-B41A56M00000
1108R20M00000AF11
1115D10M00000AX
TX-309-0005-38M1900000
MQF70.0-1000/18
566Y4810
566Y4811
TX-503-0009-25M000
CO-401B-6X-20MHZ
1116D16M00000AX
2101D80M00000WAX
1105D33M00000BX
1105D100M00000BX
1105D80M00000BX
TFS770K
TFS860D
TFS92F
VS-401-0047-1986M819383
VC-840-1004-40M0000000
1108R20M00000AF21
CS-427-DFF-S6307
CS-427-DFF-S6308
PX-509-0005-64M0000000
PX-509-0006-100M000000
1116R85M00000BF
MQF45.0-0750/23
VXA4-300-8M38860800

PCN_NTDO-19HYTI032
Affected CPN list
850-2533-070-84M000000
850-2533-060-90M420800
PX-7001-EDC-SXAX-156M250000
289-7222-160-16M700000
PX-7000-EAE-DKAX-24M0000000
PX-7000-HAE-DKAX-25M0000000
TX-707-0001-20M000
TX-4003-EEE-2560-60M0000000
MD-999-0024-10M0000000
OX-170-0096-10M0000000
VX-501-0208-100M0
VT-803-FFE-507B-28M8000000
PX-7001-HCC-PXAB-250M000000
VT-803-FAE-1060-25M0000000
VS-709-ECE-KAAN-R2/V8
1116D20M01900BX
1102R26M00000BF21
1102R26M00000BF11
1104R48M00000BF
1116B66M00000BE
1116B48M00000BE
1116B25M00000BE
FX-402-0001
FX-102-0002
FX-101-0001
FX-102-0003
HT-MM900AC-4K-EE-40M0000000
VT-803-EAE-1060-27M0000000
1107R100M00000BF
1107R100M00000BX
1115R10M00000BF
VC-709-EDE-KAAN-125M000000_SNPB
TFS92G
TFS434K
TFS887
TX-5500-EFE-106A-50M0000000
OX-220-0113-24M576
TX-5500-DFJ-106B-100M000000
PX-500-0009-28M0000000_SNPB
VX-500-0009-49M1520000_SNPB
OX-300-0024
1101R100M00000BF
PX-489-0012-30M00000
M55310/19-B02B2M457600
PX-7020-DA2-WXXX-3M68600000

PCN_NTDO-19HYTI032
Affected CPN list
TFS140BC
M55310/19-B01A10M00000
M55310/19-B21A50M00000
FX-500-LAF-SSJ-JF-JF
3429ACEB33M0000_NPC
3429ACXB25M0000NPC_SNPB
EX-4002-DEE-2572-50M0000000
PX-369-0042-80M0000000
PX-369-0043-80M0000000
TX-707-0003-40M0000000
850-2530-010-11M850000
PS-709-ECT-SAAN-P4/VC
TX-550-0005-50M0000000
1116D64M00000BX
MQF75.0-3600/09
1111R4M096000AF11
1105R24M00000AF21
1105R24M00000AF11
1102R96M00000AF11
MC929X2-047H
MC929X2-047E
PX-400-0005-66M0000000
VS-505-ECE-KAAN-1G24800000
PX-7020-HA2-VXXX-32K7680000
1116C8M000000BX
1116R24M00000BA
1118B33M55443BX
TFS128B
TFS1220R-BIN
TFS1220P
PX-7020-EA5-VXXX-32M7680000
PX-400-0006-3M07200000
PX-400-0007-32M0000000
VS-705-ECE-KABN-1G24800000
TX-5030-EAJ-3081-10M0000
MX-1700-DAJ-7001-10M0000000
PX-369-0046-36M7240000
OX-2050-BEE-2072-80M0000000
PX-7020-EA5-VXXX-32K7680000
FX-400-0003
MQF148.31-1400/C
MQF149.23-1400/C
MQF50.0-4000/01
1220D156M2500BX
1220D131M5800BX

PCN_NTDO-19HYTI032
Affected CPN list
1118D32M89500BX
1118D12M00000BX
PS-709-ECX-SANA-P4/VC
PX-7020-E190-9M21600000
OX-0421-BEE-3083-10M0000000
TX-309-0013-40M0000000
TX-309-0012-16M7772160
EX-209-CAF-157ASS-40M0000000
TX-503-0011-10M0
TX-503-0011-10M0
MQF29.8-3000/01
TX-5500-GAE-106B-10M0000000
TX-550-0006-10M0000000
PX-489-0013-12M2880000
TFS2146
OX-170-0100-10M0000000
TX-801-0023-10M0
VC-709-HDE-FAAN-125M000000
TFS1905A
M55310/16-B34A10M00000
1116R35M00000BF
EX-209-CAF-157AEN-40M0000000
PX-5701-EA2-WAXX-12M0000000
1107D8M000000AX
PX-7020-EAY-SXXX-32K7680000
PX-7020-EAY-VXXX-20M0000000
FX-500-EAE-SNNN-C6-E2
VX-705-ECE-KXAN-160M000000
VS-709-HCE-SAAN-P2/R5
OX-4000-EAE-1080-32M768
QF45.0-0060/06
TX-501-0003-30M00
TX-501-0004-40M96
PX-7020-JAY-WXXX-20M0000000
PX-5701-0012-7M37280000
M55310/30-B31A80M00000
QF10.7-15000/06
850-2530-030-11M850000
TX-5500-EFJ-466A-50M0000000
TX-5500-EFE-466A-50M0000000
850-2538-010-20M575000
1107R25M00000AX
TFS80N
311204765-104M291667
311204766-104M708333

PCN_NTDO-19HYTI032
Affected CPN list
PX-369-0049-48M0000000
1118R4M000000BF
HETT400143P20-20M0
CRH750C_diced_chip
MQF121.725-1500/GN
MQF121.850-1500/GN
TFS180N
MQF124.975-1500/GN
MX-0420-DET-1001-10M0000000
MQF72.0-2500/02-01
1115R10M00000AF
1103D12M28800BX
PX-369-0050-125M000000
PX-369-0051-200M000000
PX-369-0052-156M250000
PX-209-0006-250M000000
MQF90.0-5000/06
TFS149D
81X-777P008-130M750000
EX-420-0003-19M2000000
OX-170-0103-10M0000000
TFS110AD
TFS108
TFS115L
PX-5702-EA2-WAXX-32K7680000
TFS1238
PX-5701-E132-7M37280000
566Y4811-1
M55310/16-B31A4M250000
0753BX32M0000000
TFS1581
TFS1225A
TFS1225B
PX-369-0053-100M000000
VC-820-JAE-KAAN-24M0000000
TX-309-0011-16M7772160
OX-2050-BEE-2074-100M000000
VS-705-EDE-KAAC-698M8123348
VT-820-EFE-1060-38M8800000
PX-369-0054-25M0000000
MQF75.955-1500/C
TFS400T
MX-041-0035-10M0000000
PX-5702-0011-32K7680000
TFS180LM01

PCN_NTDO-19HYTI032
Affected CPN list
PX-7001-HDC-FKAB-20M0000000
MD-203-0006-10M000
123-00044-000-10M000000
13012-0424-36M600000
M55310/27-B24A32M00000
PX-5002-DAE-SXAX-4M00000000
600-007777-12-16M384000
MO-9200AE-D3K-EE100M000000
434Y5175-137.088MHz
TFS1245A
TFS1601A
TFS1220N
EX-209-0015-30M0000000
TX-249-0035-100M000000
VS-709-HCE-SAAN-P4/VC
1118D24M00000BX
1118D48M00000BX
1101D30M00000AX
1101D32M00000BX
1116R40M00000BX
1116R30M00000BX
1116R33M00000BX
1116R60M00000BX
725016A1084-4-59M999440
725016A1084-5-60M000560
PX-7000-EAC-KXAB-24M0000000
PX-369-0055-100M000000
PX-7020-EAZ-WXXX-50M0000000
VT-840-0024-19M2000000
TX-249-0036-33M1462100
1108R12M00000AF21
FX-500-EAT-KNNN-CC-CC
TFS300K
OX-170-0108-10M0000000
C1250A1-0189_SNPB
TFS175M
TFS1229
TFS1229A
PX-5701-EA2-SAXX-12M0000000
TX-5500-GFJ-507A-10M0000000
FX-702-EDE-HMMA-K2-M2
PX-5002-EAE-FXXB-64M0000000
M55310/16-B21B1M228800
LC140.5-10.0/02
LC150.0-10.0/02

PCN_NTDO-19HYTI032
Affected CPN list
LC160.0-10.0/02
LC169.0-10.0/02
M55310/16-B31A15M72864
TX-5500-EFE-507A-24M1920000
1116R1M152000BF
PX-7020-EA5-WXXX-4M00000000
MQF40.048-0800/06
MQF40.048-2500/09
PX-5002-EAE-SXAB-40M0000000
TX-209-0007-49M9968000
TX-209-0008-49M9968000
TFS246P
VS-505-ECE-SAAN-400M000000
PX-489-0014-50M0000000
EvalBoard_for_VT-501
C2525A1-0017EM
MV-9400AE-D1F-XXXX000.FP0000
TFSS433T
TX-5500-DAE-106B-25M0000000
VC-709-119-40M0000000
TX-249-0037-35M2187500
HT-MM900AC-7F-EE-50M0000000
1116R9M830400AX
TX-309-0014-100M000000
TX-5500-EAE-466A-10M0000000
TX-5500-EAE-466A-50M0000000
PX-7020-EAY-VXXX-1M10000000
PX-7020-EAY-VXXX-1M05000000
TFS1575AG
Funkspiess_ME_9077213-gruppiert
PX-369-0059-24M0000000
PX-369-0056-40M0000000
PX-369-0057-40M0000000
1118D64M00000BX
M55310/16-B34A11M05920
TFS150AP
SM-S433S
TFS150AN
VV-701-EAE-SNAB-20M0000000
VX-705-ECE-KXAN-153M600000
TFS624
PX-369-0064-32M0000000
QF25.34-20000/06
QF26.0-20000/06
VC-806-ECE-KAAN-161M1328125

PCN_NTDO-19HYTI032
Affected CPN list
2112D40M96000KCX
HT-MM900AC-7K-EE-25M0000000
MQF152.110-1400/T
TFS174N
1104R25M00000BF
1104R88M10000BF
1104R88M10000BX
M55310/30-B04A10M00000
VC-806-0009-250M000000
VC-806-0010-150M000000
1220R132M0000BX
PX-7020-EA5-WAXX-7M37280000
PX-7000-EAC-DKXB-33M0000000
VC-801-EAE-EABN-2M04800000
Quartz_QAB026AD_26.0000MHz
FX-702-EDE-KMXM-C4-LC
451540950368-108M458333
451540950465-108M875000
OX-221-0079-10M0000000
OX-221-0079-10M0000000
PX-7000-EAC-KKXB-16M0000000
PX-7000-EAC-KKXB-24M0000000
725016A1084-1-30M0000000
725016A1084-2-78M750000
2102C40M00000KBB
2102C8M192000KBB
TFR600
TFS100L
1102R16M38400BF
MQF45.0-0700/12
MQF45.0-0700/08
VT-803-FAH-2060-40M0000000
TX-249-0038-16M3840000
1102D16M38400BX
TFS2062A
SAMPLE_REPORT
TX-8010-EAE-2871-23M0400
TX-5030-EAE-5080-24M576
PX-5701-0013-4M00000000
1101V30M00000BF
TFS1621E
M55310/09-B01A2M000000
PX-369-0066-160M000000
1204D184M1400BX
TFS312B

PCN_NTDO-19HYTI032
Affected CPN list
PX-369-0067-8M00000000
0335DCE22M00000_SNPB
0335DCE10M00000_SNPB
PX-5702-0014-32K7680000
0335DCE17M40000_SNPB
321-01000-0002-50M0000000
321-1015-001E-50M0000000
VV-701-EAE-PNAE-45M0000000
PX-5701-EA1-JXXX-32K7680000
TFS1220S
1107R16M00000BF
1118R30M00000BF
MQF127.5-2400/FN
PX-7020-DA2-WXXX-32K7680000
TFS69B
OX-2000-DAJ-1081-10M00000000
1116D25M00000BX
MO-9200AE-D1F-EE100M000000
VCC4-B3F-10M0000000_SCRN_SNPB
MC728A1-044
TFS499BM01
M55310/16-B24A3M686400
MQF45.0-10000/07
1118D60M00000BX
1118D48M00000AX
1103D12M00000BX
TFS770L
PX-5000-EAE-FXXB-80M0000000
PX-5000-EAE-FXXB-64M0000000
1204R184M1400BA
VK-N7.1K_SCREW_CORE_F10b
MQF118.1-1500/GN
TFS428A
VV-701-EAE-PNEE-25M0000000
VV-701-EAE-PNEE-45M0000000
VV-701-EAE-PNEE-32M7680000
VV-701-EAE-PNEE-16M3840000
VV-701-EAE-PNEE-40M0000000
VV-701-EAE-PNEE-30M0000000
PX-509-0007-8M00000000
PX-509-0008-8M00000000
1118R10M36800BF
10038692-022_F-50M0000000
10038692-022_F-100M0000000
TX-801-0035-12M8000

PCN_NTDO-19HYTI032
Affected CPN list
PX-5701-EA2-WAXX-48M0000000
OX-4000-EAE-1082-40M000
TFS1225C
TFS150AZ
MO-9200AE-D5F-XXX000.FP0000
MO-9200AE-C5F-XXX000.FP0000
HT-MM900AF-7K-EE-24M0000000
1116R4M194304BF
PX-7000-EAC-PXXB-64M0000000
EX-209-0016-30M0000000
TFS1650B
OX-170-0110-10M0000000
VC-840-JAE-FAAN-14M3181800
1116D72M00000BX
OX-220-0097C-26M000
TX-5500-DFJ-507A-10M0000000
MQF125.875-1500/GN
VS-705-ECE-KABN-672M162712
1101R90M88000BF
1101D90M88000BX
TX-8010-EFE-2070-10M0
TX-8010-EFE-2070-10M0
10038692-022 X-100M000000
VC-806-HDE-FAAN-50M4000000
VC-709-ECE-FAAN-125M000000
VX-701-0043-128M0000
TFS2000A
10038692-022 F-75M000000
PX-369-0070-20M0000000
TX-309-0017-100M000000
TX-309-0016-100M000000
TX-209-0010-39M3750000
TX-209-0011-39M3750000
PX-7001-HDT-KXAX-160M315600
PX-5702-EA6-YXXX-16M3840000
MQF72.0-5000/02
MQF35.25-1200/02
QF35.25-15000/02
MQF21.4-1200/13
MQF21.4-1200/15
2113B50M00000YCC
TFS925
TFS924E
TFS924H
TFS924G

PCN_NTDO-19HYTI032
Affected CPN list
TFS921
TFS919
TFS924F
TFS923B
TFM175P
VK-CMRS_7.7x5.6x3.0_GH9
VK-CMRS_7.4x7.4x2.4_GH8
VK-CMRS_7.7x5.6x2.2_UM5
PX-4000-DAC-KKXB-5M00000000
HT-MM900AC-7K-EE-24M0000000
OX-1700-DAE-2581-10M0000000
1116V50M00000BF
TFS320B
PX-369-0071-25M0000000
PX-369-0072-48M0000000
S20-5M000000
VX-501-0104-122M88
PX-4000-DBT-KXXX-30M0000000
EX-385-DAF-S7150-20M0000000
MQF10.0-0300/06
PX-4210-DAC-SXCX-25M0000000
PX-4210-DAC-SXCX-40M0000000
PX-369-0073-125M000000
PX-7020-E120-20M0000000
HT-MM900AC-9F-XXX-000.FP0000
HT-MM900AC-6F-XXX-000.FP0000
HT-MM900AC-4F-XXX-000.FP0000
HT-MM900AC-2F-XXX-000.FP0000
OX-4050-EAJ-3580-104M857600
1103V20M00000BF
EX-4001-EAJ-5073-13M0000000
PX-369-0074-32M0000000
Evaluation_Board_GS2
Evaluation_Board_GS17
Evaluation_Board_GS10
OX-200-0136-40M0000000
0429CCXB20M0000
TRU050-SKLHB-60M0000000
CO-442A-2B-12MHz
TFS140BH
TFR1475
OX-204-0006-26M0000000
PX-7020-EA2-WXXX-40M0000000
1116R8M000000AF
TFS246R

PCN_NTDO-19HYTI032
Affected CPN list
PX-7003-EDE-KKXB-166M666666
MO-9150AE-6F-ES-125M000000
HT-MM900AC-4F-EE-50M0000000
TDX770M
VCC6-QCP-100M000000
MQF156.425-1500/J
13012-0459-2M457460
1103D60M00000BX
TFS240X
TFS240Y
TFS1220T
VV-701-EAE-PNEE-50M0000000
1109R4M000000AA
MQF42.2-0800/06
OX-990-0047-125M00
PX-489-0015-8M00000000
TFS1650C
PX-360-0002-5M00000000_SNPB
PX-360-0003-6M00000000_SNPB
PX-360-0004-25M0000000_SNPB
VX-189-0014-500M000000
MX-041-0036-10M0000000
OX-1710-EAE-8001-10M0000000
TFS1681B
TFS1717B
TFS1226B
TFS1187A
TFS106A
TFS106B
TFS207A
TFS207B
TX-5500-EAE-106A-40M0000000
CRH805_diced_chip
CRH873_diced_chip
CRH881_diced_chip
TX-309-0018-33M5544320
TX-309-0019-33M5544320
M55310/26-B42A24M00000
1118D38M40000BX
OX-171-0001-10M0000000
TFS266B
PX-7000-EAC-PXXB-30M0000000
VS-709-ECE-KAAN-WJ/WR
1319D500M0000BX
OX-204-0008-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
TFS1747K
EX-219-DAF-157ASS-50M0000000
OX-0432-BET-5091-10M0000000
1204D156M2500BX
PX-369-0075-156M25
1204C156M2500BB
PX-369-0076-156M25
PX-369-0077-156M25
0426CCEX24M56000
PX-489-0016-90M0000000
TX-503-0019-25M0
TFS123G
TFS127E
TFS63H
PX-7020-E190-9M60000000
TX-1910-DEE-1060-310M000000
TFS180MM01
TFS434L
VS-702-1005-805M664062
MQF124.525-1500/GN
MQF70.0-2200/07
MQF70.0-7500/02
TFS70BU
TFS678B
TFS678A
TFS639
TFS639A
2102R40M00000KBS
EX-4210-EAE-3083-10M0000000
PX-7000-JAE-KXXX-25M0000000
VXA1-1B3-4M32000000
VXB1-1F4-5M00000000
TFS609
TFS674
TFS578
TFS512A
HT-MM900AF-7K-EE-50M0000000
TFS869M
311205034-2M949000
MQF50.0-1500/12
1104R25M99468BF
1104R12M00000BF
1104R84M11138BF
1104R30M00000BF
MQF120.175-1500/GN

PCN_NTDO-19HYTI032
Affected CPN list
MQF121.950-1500/GN
OX-990-0048-120M00
FX-400-EDE-KNNN-E2-L8
MQF173.84-1400/C
MQF85.295-1500/C
MQF85.755-1500/C
MQF86.475-1500/C
MO-9200AE-D1K-HE25M0000000
HT-MM900AC-7F-JE-50M0000000
LC40.7-50000/02-01
MQF70.0-1250/02
TFS246S
ANT-PIF-0002
10038692-022 I-106M666667
PX-369-0080-3M68640000
PX-369-0081-16M0000000
PX-369-0082-24M0000000
M55310/16-B34A6M0000000
TX-249-0041-39M2418620
FX-702-ECT-KMMM-K9-M1
0429ACXB66M0000
1118D30M00000BX
MX-060-0002-10M0000000
PX-700-0061-53M1250000
CO2080-2
MQF25.34-3000/06
MQF26.0-3000/06
VS-705-ECE-KAAN-200M000000_M01
VS-705-ECE-KAAN-250M000000_M01
VS-705-ECE-KAAN-400M000000_M01
TFS500C
2112R40M96000KCS
TFS1504
TFS1651
VS-501-0046-1000M0
OX-200-0141-20M0000000
OX-2211-EAE-3090-10M000
TX-7070-EAE-106D-10M0000000
OX-2050-BEJ-2070-70M0000000
TFS1650D
TFS1250
TFS1792
PX-369-0085-36M7240000
PX-369-0086-50M0000000
PX-369-0087-80M0000000

PCN_NTDO-19HYTI032
Affected CPN list
TFS140BG
PX-990-0011-120M000
VK-PMSS_58.3x23.4x1.6_02P_GA2
VK-CMSS_60.8x26.7x26.1_GA3.1
VK-Buchse-SMA
PX-7003-EDE-KXXX-166M666666
M55310/19-B13A25M00000
M55310/19-B23A60M00000
M55310/21-B11A6M000000
VL-821-JAE-KAAN-30M0000000_SNPB_SCR
289-7128-020-7M372800
1103D75M00000BX
TFS175NS01_FM
TFM175PS01_FM
TFM175PS01_Group_B
TFM175PS01_Package_Eval
TFS177ES01_FM
TFM177DS01_FM
TFM177DS01_Group_B
TFS179CS01_FM
TFM179BS01_FM
TFM179BS01_Group_B
TFM179BS01_Group_C_SG_1
TFM179BS01_Group_C_SG_2
TFM179BS01_Group_C_SG_3
TFM179BS01_Group_C_SG_4
TX-7070-EAE-106A-50M0000000
TFS63K
011567-0502-10M0000000
1116R100M0000BA
1118R30M0000BA
CO-286WT-3-1005MHZ-RoHS
TX-249-0042-50M0000000
PX-4000-DAC-KSXB-32K7680000
PX-7000-DAC-SSXB-500K000000
MO-9200AE-D5K-HE20M0000000
FX-500-EAE-KNNA-A9-E4
TX-801-0041-20M0
TFS962
VK-PMRS_7.5x2.8x1.0_03P_UM1-1
VK-PMRS_7.5x2.4x1.0_03P_UM1-slim
VK-PMRS_7.3x2.6x1.0_03P_UM5
VK-PMRS_7.3x2.6x1.0_02P_UM1
TFS123K
MO-9000AE-6F-ES-16M0000000

PCN_NTDO-19HYTI032
Affected CPN list
MO-9000AE-6F-ES-80M0000000
MO-9000AE-6F-JS-80M0000000
2102D50M00000WAX
2102B50M00000WAC
M55310/16-B24B4M915200
EX-4211-EAE-3083-10M0000000
TFS249C
850-2508-020-24M576000
OX-202-0002-20M0000000
MO-9200AE-D1K-HE160M000000
10350-3099-41M455000
OX-403-0007-20M000
OX-403-0008-20M000
PX-509-0013-40M0000000
PX-7020-DA5-VXXX-8M19200000
PX-7020-JA2-WXXX-4M00000000
011577-0502-40M0000000
MX-060-0003-10M00000000
C2570A1-0047
MQF40.048-4800/07
PX-369-0088-100M00
HT-MM900AC-9F-EE-60M0000000
PX-7004-EAE-KXAB-25M0000000
PX-7000-EAE-KXAX-33M0000000
PX-5713-EAC-FKXB-14M7456000
PX-5713-EAC-FKXB-16M0000000
PX-5713-EAC-FKXB-25M0000000
PX-5713-EAC-FKXB-32M0000000
PX-5713-EAC-FKXB-50M0000000
1103R30M00000BD
1118R60M00000BD
1118R48M00000AD
1118R12M00000BD
1118R48M00000BD
MD-261-0002-10M00000000
TFS212
TFS1582A
PX-409-0016-32M0000000
MV-9300AE-3F-EES20M0000000
1115R100M0000BC
PX-489-0018-66M0000000
TFS1220V
TX-209-0012-10M00000000
TFS1575ADS03_FM
TFS35GS03_FM

PCN_NTDO-19HYTI032
Affected CPN list
MQF21.4-4000/22
MQF21.4-4000/23
1103R75M00000BD
PX-360-0005-200K000000
MQF110.2-1500/02V1
MQF110.2-1500/02V2
MQF124.4-1500/HN
M55310/21-B11A5M000000
VCC6-1318-200M000000
MQF180.0-1400/C
PX-7000-EAE-FKXB-125M000000
TX-7070-EAE-106C-50M0000000
CO-402C-2B-20MHZ
EX-4010-EAJ-3083-10M0000000
401Y0684-16.5MHZ
PX-7001-ECE-KKXX-800M000000
PX-409-0019-83M1600000
MX-5030-EAE-5080-19M200000
TFS270E
010854-0518-10M230000
MO-9150AE-6K-HE-125M000000
M55310/30-B01A14M74560
M55310/16-B44A25M000000
EX-219-CHF-107AEN-20M0000000
VK-CRYSTAL_CLIP_C52_10_CUSN_025
FX-702-ECE-KMMM-JF-JF
M55310/16-B24A2M457600
PX-7020-0066-7M37280000
1101D8M000000BX
1101D10M00000AX
1103D96M00000BG
1103D66M00000BG
MO-9200AE-D3K-EE106M250000
TX-7070-EFE-106D-50M0000000
TFS2655B
HT-MM900AC-7F-EE-40M0000000
1104R96M00000AF11
1118D32M00000BX
TFS1737
10038581-022_J-97M117647
10038581-022_J-98M166923
TFS1508
OX-171-0003-10M0000000
TX-707-0007-40M0000000
OX-1710-DEE-8001-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
10038692-022 H-99M025974
10038692-022 H-98M924051
10038692-022 H-98M827160
10038692-022 H-97M159091
10038692-022 H-98M369565
10038692-022 H-95M869792
10038692-022 H-96M410000
10038692-022 H-97M660000
10038692-022_H-98M886905
10038692-022 H-99M929412
10038692-022 H-99M787356
10038692-022 H-99M651685
10038692-022 H-99M521978
10038692-022_H-99M018293
1304D120M0000BX
TFS1080F
TFS1774
HT-MM900AC-9F-EE-17M6000000
5321D156M2500BX
MQF75.0-7000/02
PX-509-0015-90M0000000
TFS315S
TX-309-0020-60M0000000
TX-7070-EAE-106C-10M0000000
OX-170-0116-20M0000000
TX-309-0021-60M0000000
OX-170-0117-10M0000000
VX-805-0010-122M880000
MX-5030-EAE-3080-10M0000
MX-5030-EAE-3080-10M0000
600-010645-3-8M320000
MQF124.35-2500/R
MQF21.4-4000/24
PX-7004-JAC-FKXX-100M000000
1103D60M000000BG
TX-7070-EAE-206C-10M0000000
1103R80M000000BF
TFS847B
TFS897G
TX-7070-EAE-106C-20M0000000
2104D60M000000YAX
TFS180SS01_FM
TFS180SS01_Group_B
TFS180SS01_Group_C_SG2
MQF35.25-2500/04

PCN_NTDO-19HYTI032
Affected CPN list
20502205000-14M580
PX-369-0091-125M00
PX-369-0092-125M00
PX-369-0093-125M00
TFS1575AK
M55310/16-B44A20M000000
TX-7070-EAE-106D-50M0000000
PX-7000-EAC-DKCX-33M0000000
M55310/16-B34A6M5793000
EX-4000-EAJ-1073-40M0000000
TFS1539
PX-501-0039-320M0000
MQF121.875-1500/GN
PX-5701-EAZ-JAXX-11M0592000
VX-5090-EAE-GXSX-24M5454545
TFS1581A
TX-707-0008-50M0000000
1118R32M00000BF
TX-7070-EAE-106B-40M0000000
EX-4210-DEE-3082-10M0000000
EX-4002-DEE-1572-10M0000000
PX-4000-E210-16M3840000
OX-170-0120-20M0000000
TFS1584A
VX-705-1014-155M520000
TX-269-0001-200M000
C6999A1-0005
EX-4210-DAE-3083-20M0000000
1404D125M0000BX
TFS315T
VC-709-HDE-KAAN-32M0000000
MQF70.2-1100/02V1
MQF21.4-7000/01
EX-4210-DAP-3083-20M0000000
CO2080-1
MQF8.403512-0625/05
VT-840-0033-19M2000000
TX-7070-EAE-106D-25M0000000
OX-170-0122-10M0000000
TX-801-0042-10M0000000
EX-4210-DEE-7581-100M0000000
TX-5500-EFT-106A-40M0000000
MO-9100AE-4K-EE-40M0000000
OX-170-0108R-10M0000000
VS-709-ECE-SAAN-WJ/WK

PCN_NTDO-19HYTI032
Affected CPN list
TX-7070-EFE-206A-50M0000000
MX-5030-EAE-5081-16M384
TX-707-0009-40M0000000
TX-707-0010-40M0000000
VC-709-0038-125M000000
VC-709-0037-156M250000
TX-7070-EFE-206A-10M0000000
PX-7020-EAZ-JXXX-32K7680000
401Y0684-21MHZ
MQF50.0-0700/08
MD-2610-EXE-OCXO-10M0000000
TFS230C
MD-2610-EXJ-HPTC-10M0000000
TX-5500-EFE-106A-100M000000
TX-7070-EAE-106D-40M0000000
MO-9000AE-6F-HS-25M0000000
VX-805-0012-153M600000
PX-409-0024-2M94912000
PX-409-0025-12M0000000
1116R30M00000BF11
1116R40M96000BF
1103R96M00000BF11
1220D125M8290BX
MX-042-0004-10M0000000
1103R66M00000BA
1104D66M66667BX
FX-500-EAT-KNNN-CC-F8
PX-7020-EAY-UXXX-10M0000000
MQF70.0-0600/11
VC-820-HAE-KAAN-12M0000000
FX-702-ECE-KMMM-WX-WX
PX-7020-JAY-SALX-32K7680000
FX-400-0005
TX-189-0009-367M200000
TX-189-0010-370M800000
TX-320-0004-20M0000000
OX-170-0126-10M0000000
MQF27.0-2400/02
OX-5011-EAE-1080-20M000
Quartz_QAI012AB_12.800000MHz
1104D72M00000BX
PX-489-0019-7M000000
TX-7070-DAE-106D-25M0000000
VT-820-FFE-106B-19M2000000
C2570A1-0047E

PCN_NTDO-19HYTI032
Affected CPN list
TX-550-0007-57M8500000
600-010366-2-100M000000
MX-5030-EAE-3081-10M00
OX-300-0029-10M0000000
EX-4011-0001-10M0000000
1116D30M00000BX
MQF101.0-4000/01
MQF149.19-1400/C
4140-004
TX-7070-EAE-106A-10M0000000
TX-8010-EAE-2871-25M0
PX-7020-EA3-YXXX-12M0000000
VT-803-FFE-287B-38M4000000
MO-9000AE-6K-ES-100M000000
EX-4002-DEE-1071-10M0000000
PX-4000-DAE-DFXX-3M68640000
PX-7020-EAY-SXLX-32K7680000
TX-7070-EAE-106A-40M0000000
MQF45.0-5000/25
TX-7070-EAE-106C-40M0000000
TFS2155
PX-369-0102-80M0000000
VC-706-HDE-KABN-125M000000
VC-801-HAE-KAAN-25M0000000
VT-822-EAE-2560-27M0000000
M55310/16-B41A25M427000
PX-369-0103-8M00000000
PX-369-0104-12M0000000
PX-369-0105-30M0000000
PX-369-0108-60M0000000
PX-369-0109-80M0000000
1105D12M00000BG
1105D25M00000BG
1105D66M00000BG
447Y5034-33.554432MHZ_SNPB
4140-020
MD-1730-DAJ-6001-10M0000000
TX-707-0011-10M0000000
TFS199ME01
1420D125M00000BX
1420D125M8290BX
1420R125M00000BF
M55310/09-B21A50M000000
TX-209-0013-50M0000000
OX-200-0125-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
011126-0509-10M000000
PX-369-0110-24M0000000
PX-369-0112-24M0000000
PX-500-0031-16M0000000
PX-7020-E190-20M0000000
PX-369-0114-40M0000000
PX-4001-DBC-KKXX-16M0000000
TFS280U
WSR-F1-01
TFS917
TFS924K
TFS869N
2104C40M92000KAZ
MD-403-0002-30M72
Quartz_QAI013AB_13.402340MHz
972368-0019-15M0000000
VC-826-EDE-FAAN-114M426000
PX-7020-DA3-YXXX-4M91520000
408Y2765-1
EX-4210-EAE-7580-100M0000000
VT-706-0001-19M2000000
TX-7070-EAE-106A-25M0000000
TX-7070-EFE-106A-25M0000000
MX-503-0005-10M0
OX-1710-DAE-1091-10M0000000
TFS155D
MQF76.8-0800/06
VCC1-B3R-20M0000000
OX-0432-BEJ-1081-10M0000000
PX-7020-EA5-WAXX-16M0000000
TX-707-0012-40M0000000
2104D80M00000VAX
OX-041-0044-10M0000000
PX-5702-EAY-UXXX-2M04800000
1103R40M96000BF11
1103R66M00000BF11
1103D40M96000BX
1104D100M0000BX
TFS1990BS01_FM
TFS1990BS01_QM_Env/Mech_SGA
TFS1990BS01_QM_Env/Mech_SGB
TFS1990BS01_QM_Endurance_SG
TFS1990BS01_QM_AssCap_SG
TFS1990BS01_QM_Solderability_SG
0429ACEB33M0000

PCN_NTDO-19HYTI032
Affected CPN list
OX-174-0005-10M0000000
TFS70BRS01_FM
TFS70BRS01_QM_Env/Mech_SGA
TFS70BRS01_QM_Env/Mech_SGB
TFS70BRS01_QM_Endurance_SG
TFS70BRS01_QM_AssCap_SG
TFS70BRS01_QM_Solderability_SG
TFS280V
TFS63L
HT-MM900AC-7F-EE-33M3333333
EX-4210-DEJ-2084-10M0000000
FX-102-0005
1103R45M00000BF
PX-369-0116-125M0000000
TX-7070-EFE-106A-16M3690000
TX-7070-EFE-106A-16M3680000
1118R48M00000BX
1118R48M00000AX
1204R125M00000BF
TFS806A
TX-249-0045-100M0000000
FX-700-EAE-SNKN-A3-F7
M55310/19-B01A15M000000
VS-705-ECE-SAAN-670M838000
PX-4200-0018-24M5830000
2104R33M554432VBS11
2104R33M554432VBS21
0426CCXX02M29376_SNPB
PX-400-0027-23M9400000
TQX6800_B-9M0316
OX-1711-EAT-4001-15M0000000
EX-219-DAK-508FEN-10M0000000
PX-4000-DBT-KXXX-16M5517240
3429ACEB33M0000 NPC_SNPB
VCC1-H3R-25M0000000
TX-7070-EFE-106D-16M3680000
1116R66M00000BF
MD-023-0004-10M000000
MQF156.950-1500/J
MQF156.900-1500/J
MQF156.800-1500/J
EX-4210-DAJ-2083-20M0000000
011699-0503-10M0000000
SP-I-011-EM-10M0000000-NON SWEPT
1103R96M00000BD

PCN_NTDO-19HYTI032
Affected CPN list
FX-500-KAC-GNJ-C4-C4_IPV_IC
FX-500-KAC-GNJ-C4-C4_IPV_IC
VX-501-0231-200M0
311205374-6M000000
OX-405-0013-100M000000
MO-9000AE-6K-EE-2M04800000
TFS2035
TFS2250
TFS1930A
PX-4001-DBT-KKXX-24K0000000
MX-503-0007-20M0
MX-503-0007-20M0
PX-7020-EA3-YXXX-32M0000000
PX-489-0020-75M6833300
PMRS_7.4x2.6x1.0_02P_UM1-3
PMRS_7.4x2.6x1.0_02P_UM1-4
MC741A1-995
2104B80M00000YAB
1103D25M00000BX
1103D58M72026BX
TX-7070-EFE-106A-26M0000000
TRU050-GALGA-40M0000000
FX-500-LAF-GNJ-C4-JF_IPV_Qual
FX-500-LAF-GNJ-C4-JF_IPV_Qual
FX-500-LAF-GNJ-C4-JR_IPV_Qual
FX-500-LAF-GNJ-C4-JR_IPV_Qual
VT-803-EFW-2870-50M0000000
EX-4010-EEJ-2085-10M0000000
MD-1731-DAT-4001-10M0000000
OX-043-0024-100M000000
TX-320-0005-25M0000000
PX-4200-EAZ-VXXX-40M0000000
PX-7020-JA2-VAXX-6M00000000
LC0-31.0/06
044-00311-0000-128M750000
Evaluation_Board_GS23
VCC1-G3C-120M000000
311205424-100M000000
TX-7070-EAE-106D-48M0000000
STFHEA-20M0000000
MQF50.0-3000/09
289-4435-010-6M001536
289-4435-030-6M292992
TX-7070-DFE-106D-40M0000000_SNPB
MD-011-0020-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
EX-4211-EAP-1083-10M0000000
TFS433AF
VC-820-HAE-FAAN-93M7500000
MQF168.38-1400/C
VXM7-1261-54M0000000
PX-5701-D130-29M4912000
HT-MM900AC-7K-JE-25M0000000
MD-2610-EXJ-OCXO-10M0000000
EX-4210-EAE-5080-32M0000000
VS-501-0061-1734M375
10038581-022 B-100M853618
10038581-022 A-96M056980
10038581-022 B-100M711111
VS-705-ECE-SAAN-150M0000000
VT-803-EAE-507A-50M0000000
VT-803-EAE-2870-29M79200000
QF20.0-0040/06
QF5.0-0600/08
M55310/09-B11A12M0000000
OX-2040-DEJ-2082-10M0000000
TFS1530S01_FM
TFS1532S01_FM
TFS1532S01_QM_Env/Mech_SGA
TFS1532S01_QM_Env/Mech_SGB
TFS1532S01_QM_Endurance_SG
TFS1532S01_QM_AssCap_SG
TFS1532S01_QM_Solderability_SG
2112D10M00000RCX
2112B10M00000RCB
MQF131.725-1500/GN
600-011380-1-16M384000
VK-THREE_BOND_3301F_200g_Can
1204B200M0000BX
TX-249-0047-65M5360000
1118B10M00000BX
TFS1575ADS01_LVT_Subgroup_1
TFS1575ADS01_LVT_Subgroup_2
TFS1575ADS01_LVT_Subgroup_3
PX-5002-DAC-ZXAB-50M0000000
13012-0445-9M828000
TFS60M01
PX-369-0118-156M25
TX-8010-EAE-1060-10M0
TX-7070-EAE-106A-20M0000000
PX-189-0002-1G00000000

PCN_NTDO-19HYTI032
Affected CPN list
EX-4210-EAJ-5083-50M0000000
MX-041-0039-10M0000000
MQF45.0-1500/73
VV-701-EAE-PNEE-16M3840000-A
VV-701-EAE-PNEE-40M0000000-A
PX-369-0121-125M00
311205488-50M000000
311205489-100M000000
311205490-150M000000
MO-9100AE-8F-EE-40M0000000
311205491-10M000000
TFR867
TFR950
TFR981
TFR633
VX-420-0001-80M0000000
1404R156M2500BF
EX-4210-EEE-3085-10M0000000
TFR1068
PX-4003-DBE-KXXX-8M00000000
TFR1034
PX-4003-DBE-KXXX-4M91520000
TX-249-0049-83M3375000
FX-500-LAF-NSJ-E2-E2
VS-705-HCE-KAAN-500M000000
OX-220-0100-A-20M000
OX-200-0150-10M0000000
FX-500-EAT-KNNN-CL-H2_SNPB
PX-509-0017-24M0000000
PX-509-0018-66M6666600
TX-7070-EFJ-106A-16M3680000
OX-4051-DAE-3072-98M666667
TX-249-0050-106M062500
QF9.5625-3000/06
QF9.6022-6000/06
1118B1M600000BG
TFS128C
010854-0546-10M949297
MQF149.9725-2400/01
MQF149.9725-2400/02
TX-7070-EFE-106C-20M0000000
VX-706-0002-122M88
1103R96M00000BF21
1103R60M00000BF11
MQF10.0-1500/06

PCN_NTDO-19HYTI032
Affected CPN list
PX-5701-E151-12M0000000
010854-0501-10M0000000
TFS1800C
TFS2105
TFS2265
TFS2425
FX-500-EAE-KNNN-C4-JF
FX-500-EAE-KNNN-C4-JF
FX-500-EAE-KNNN-C4-JR
FX-500-EAE-KNNN-C4-JR
FX-500-DAT-KNNN-C4-C4
FX-500-DAT-KNNN-C4-C4
OX-2211-EAE-3090-20M000
OX-2211-EAE-3090-24M576
XR-P111-1F9-KBAA-16M0000000
CO-446D-2B-12MHZ
PX-7020-EAZ-JXXX-16M0000000
PX-4002-DAC-DKXB-12M0000000
PX-5701-E150-24M0000000
HT-MM900AC-2E-XXX-000.FP0000
HT-MM900AC-4E-XXX-000.FP0000
VX-501-0239-491M52
CRH660_diced_chip
1118R50M00000BA
1204R125M0000BA
2102R10M00000BAK
1107D16M00000BX
PX-369-0126-125M0000000
OX-043-0027-10M0000000
MD-011-0014-10M0000000-EK
Quartz_QAH006AB_6.144000MHz
Quartz_QAH014AB_14.745600MHz
Quartz_QAH015AB_15.000000MHz
Quartz_QAH020AB_20.000000MHz
TFS1575AL
M55310/09-B05A4M0000000
PX-7020-EA5-WXLX-7M37200000
TFS62
1116E80M00000AF
Evaluation_Board_GS12
HT-MM900AC-7F-EE-24M0000000
VX-509-0002-9M99969500
VX-509-0003-9M99969500
1117R16M00000AF
OX-220-0099-A-10M000

PCN_NTDO-19HYTI032
Affected CPN list
OX-4011-EAE-0580-10M000
PX-7020-EAZ-JALX-32K7680000
VX-504-0003-100M0
VX-706-0003-250M0
TDX1210
81X-774P012-103M165598
81X-774P013-104M875000
81X-776P013-129M769897
81X-775P013-110M333333
81X-777P035-138M500000
81X-778P011-140M166667
TFS160R
TFS160P
TFS10C
TFS10B
MX-0410-DEE-8001-10M0000000
VS-369-0002-433M000000
VS-369-0003-622M000000
VX-501-0240-256M0
TFS1370A
TFS640AM01
QF5.0-0020/04
QF5.0-0040/04
QF5.0-0100/04
QF5.0-0300/04
QF5.0-0600/04
OX-403-0008-A-20M000
TFS199MS01_FM
TFS199MS01_QM_Environ/Mech_SG_A
TFS199MS01_QM_Environ/Mech_SG_B
TFS199MS01_QM_Endurance_SG
TFS199MS01_QM_AssCap_SG
TFS199MS01_QM_Solderability_SG
AXX35-31-PN-100M000000
VX-5071-EAE-KAXX-29M0000000
PX-7020-JA3-WXXX-3M68640000
0429ACEB40M0000_SNPB
1105R24M00000AX
010853-0510-5M000000
81X-777P011-133M188701
81X-777P013-136M607504
81X-777P014-138M316906
OX-3050-BEE-2070-100M000000
011126-0510-10M000000
TX-707-0013-50M0000000

PCN_NTDO-19HYTI032
Affected CPN list
TFS184C
PX-7020-EA5-VXXX-8M19200000
400-7562-10MHZ
PX-4220-0001-20M0000000
1103V100M0000BX
TX-5500-EFE-206A-100M000000
M55310/16-B31A16M66000
M55310/16-B31A13M90000
81X-774P011-101M456197
81X-774P014-106M584402
81X-774P015-108M293804
81X-776P011-126M351094
81X-776P012-128M060496
81X-777P010-131M479299
81X-777P012-134M898103
VXM8-1050-30M0000000
JCUFLMEP-40M0000000
TX-8010-EAF-2060-10M368
FX-702-ECT-SMMM-P3-L8
1103R64M00000BF
TX-249-0051-128M203125
TX-249-0052-128M218750
PX-7020-EAZ-JXLX-32K7680000
1103D16M00000BX
TFS2105A
TX-249-0053-1M02400000
VS-705-ECE-KAAN-614M000000
PX-509-0019-100M000000
PX-509-0020-100M000000
PX-7020-EA6-VXXX-20M0000000
401-9999A-2X-11.0592MHZ
TX-7070-DFE-106A-25M0000000
TX-7070-DFE-106A-40M0000000
MQF118.0000-1500/GNZ
MQF118.1000-1500/GNZ
MQF118.9000-1500/GNZ
MQF119.5000-1500/GNZ
MQF119.6500-1500/GNZ
MQF120.0000-1500/GNZ
MQF120.2000-1500/GNZ
MQF120.7750-1500/GNZ
MQF121.5000-1500/GNZ
MQF121.8250-1500/GNZ
MQF123.7000-1500/GNZ
MQF124.1500-1500/GNZ

PCN_NTDO-19HYTI032
Affected CPN list
MQF124.6000-1500/GNZ
MQF125.1000-1500/GNZ
MQF125.5750-1500/GNZ
MQF126.6000-1500/GNZ
MQF126.6750-1500/GNZ
MQF126.8750-1500/GNZ
MQF126.9750-1500/GNZ
MQF127.9500-1500/GNZ
MQF128.0500-1500/GNZ
MQF128.5250-1500/GNZ
MQF129.1000-1500/GNZ
MQF129.9000-1500/GNZ
MQF130.1500-1500/GNZ
MQF130.4500-1500/GNZ
MQF130.6000-1500/GNZ
MQF131.2250-1500/GNZ
MQF132.2500-1500/GNZ
MQF132.8250-1500/GNZ
MQF133.1250-1500/GNZ
MQF133.1667-1500/GNZ
MQF134.1000-1500/GNZ
MQF134.7000-1500/GNZ
MQF135.0250-1500/GNZ
MQF135.6833-1500/GNZ
MQF136.3250-1500/GNZ
CONNECTOR_FOR_HSR-01-2M
2102E32M00000WAS
PX-369-0134-200M000000
850-2533-030-76M436577
PX-369-0128-156M25
PX-369-0129-156M25
PX-369-0131-128M00
PX-369-0132-128M00
VX-7080-EAZ-FXXX-32M7680000
PX-369-0136-156M250000
PX-369-0137-200M000000
Monolithic_Crystal_Filter
SAW-Filter
BBV021570A010CDGS_21k56X-5-2
PX-369-0138-100M000000
PX-369-0139-125M000000
VXM7-9001-48M0000000
PX-7000-EAC-ZXXX-12M0000000
1116E2M000000BF
1116E100M0000BF

PCN_NTDO-19HYTI032
Affected CPN list
PX-7020-EAZ-JALX-11M2000000
M55310/30-B14A20M00000
PX-400-0029-12M0000000
PX-400-0030-2M45760000
TX-209-0017-70M0000000
SP-I-013-EM-10M000000-NON SWEPT
TFS241F
EX-4000-EAE-1073-40M0000000
OX-2211-EAE-1080-20M000
OX-221-0099-10M000
TFR1701-1
TFR1701-2
TFR1701-3
TFR1701-4
TX-7070-EFE-106C-16M0000000
CRH342_diced_chip
PX-7001-HDC-FKXX-125M000000
PX-7001-HDC-FKXX-200M000000
OX-200-0155-50M0000000
VC-708-1021_SCRN_SNPB
TX-5500-EAT-106B-73M7280000
SP-I-011-EM-10M000000
SP-I-013-EM-10M000000
SP-I-022-EM-10M000000
SP-I-022-10M000000
TFS320C
TFS320CM01
TFS1920AM01
TFS897H
M55310/16-B01A15H00000
010854-0547-10M230000
1103D66M00000BX
1304R200M0000BA
1304R155M0000BA
TFS1225D
TFS1581B
TFS1542D
PX-7001-ECT-KXXX-160M000000
PX-7002-EAE-KXAB-80M0000000
1118R33M00000BX
1118R40M00000BX
2102R48M00000KAS
MQF21.4-4000/04-01
MQF23.0-4500/04-01
VX-501-0242-122M88

PCN_NTDO-19HYTI032
Affected CPN list
OX-2211-EAE-3091-10M000
VCC6-LCF-78M1250000
MQF10.7-1000/08
TFS149E
048-0015-00-7M150000
048-0016-00-7M195000
TX-209-0018-64M0000000
373Y5150-29.560MHZ
VS-5080-DFE-205X-2400M0
VS-5080-DFE-205X-2400M0
C4720A1-0006-50M0000000
MQF21.4-2500/13
TX-7070-EAE-206A-20M0000000
VC-826-ECE-FAAN-128M000000
OX-171-0009-10M0000000
MQF45.0-1500/74
1110R3M686400AF
EX-219-CJF-157FEN-69M9692780
EX-219-CJF-157FEN-70M0067588
CO-484C-2B-70MHz
PX-5002-EAB-KXXX-50M0000000
PX-5072-EAB-KXXX-50M0000000
TFS1480A
TX-5500-DAE-507A-70M0000000
1103R58M72026BF
1420R125M0000BF11
1420R125M8290BF11
1420R125M8290BF21
1103R25M00000BF11
1103R25M00000BF21
PX-7020-EA2-WXLX-8M00000000
PX-7020-EA2-WXLX-4M00000000
TX-5030-EAE-3080-12M8
TFS468T
VX-501-0245-160M0
TX-7070-EAE-106B-9M60000000
EX-219-0004-20M0000000
1116R60M00000BE
FX-400-ECE-KNNN-D6-F7
TFS1210C
FX-400-ECE-KNNN-M3-H5
1105R75M00000BF
1105R48M00000BF
1105R15M00000AF
1105B75M00000BG

PCN_NTDO-19HYTI032
Affected CPN list
1105B48M00000BG
1105B15M00000AG
MQF21.4-1500/87
MQF21.4-1260/05
PX-509-0022-2M00000000
PX-5717-EAB-KXXX-50M0000000
TFS186C
PX-5001-HDE-FFAB-125M000000
TFR1200
1116E80M00000BF
1108D10M00000BX
1108R10M00000BF
VXM7-1D1-25M0000000_SNPB
OX-221-9100-20M000
OX-221-9101-24M576
OX-221-9102-49M152
VX-5090-DAE-KXXX-77M0400000
010854-0517-10M0000000
TFS300L
PX-509-0023-80M0000000
MQF109.53-1000/04
QF109.5315-0260/04
QF109.5315-0300/04
VX-805-0017-122M880000
OX-2080-DEE-8001-10M0000000
TFS2012E01
PX-7020-EA3-YAXX-12M0000000
OX-221-0105-20M000
1204D100M00000BX
1117R4M915200AF
M55310/16-B31A7M5000000
VS-709-ECE-KAAN-WJ/WK
MQF70.0-2000/23
PX-706-0001-300M0
MQF21.4-1500/01
81X-853P002-99M601496
81X-774P022-101M738248
81X-774P023-103M875000
81X-774P024-106M011752
81X-774P025-108M148504
81X-777P020-131M854701
81X-777P021-133M991453
81X-777P022-136M128205
81X-777P023-138M264957
81X-778P004-140M401709

PCN_NTDO-19HYTI032
Affected CPN list
81X-778P005-142M538461
81X-778P006-144M675214
81X-778P007-146M811966
TX-5500-EFJ-206A-10M0000000
TX-209-0019-64M0000000
TX-209-0020-64M0000000
TX-209-0021-70M0000000
0429ACXB20M0000
0429ACXB25M0000
0429ACXB64M0000
PX-509-0024-40M0000000
PX-509-0025-37M5000000
PX-489-0022-16M000000
TX-309-0023-80M0000000
PX-706-0002-250M0
PX-706-0002-250M0
VCC6-LAF-122M880000
OX-0432-BEJ-1083-10M0000000
PX-4001-EAC-ZXXB-12M0000000
PX-4001-EAC-ZXXB-27M0000000
PX-4001-DBC-ZXXB-20M0000000
PX-7000-DAC-SXXB-16M0000000
TX-707-0014-50M0000000
PX-709-0010-33M0000000
VS-709-HDE-KAAN-P4/VC
VS-709-HCE-KAAN-WJ/WK
VX-706-0005-100M0
VS-701-0001-1265M625
EX-219-DHD-758FEN-10M2400000
TX-209-0022-64M1406250
MQF118.000-2000/U
PX-7020-EA5-VAXX-8M00000000
PX-7004-HAE-DKAX-25M0000000
OX-174-0007-10M0000000
PX-7020-E190-14M7456000
0426CCEX20M00000
PX-7004-EAE-DKAX-24M0000000
TX-5500-EAE-106A-80M0000000
VX-501-0251-122M88
VX-501-0253-125M0
311205825-50M000000
VS-800-EGE-EANN-1G56897921
VX-504-0005-100M0
PX-369-0148-125M000000
1105D41M58000BX

PCN_NTDO-19HYTI032
Affected CPN list
TFR1024
VX-189-0015-500M000000
VX-189-0016-500M000000
1157D33M00000BX
5116B100M0000WF_ENG
PX-7021-EA5-WXXX-32K7680000
EX-380-CAF-107A-10M0000000_BOX
EX-380-DAF-107A-20M0000000_BOX
EX-380-DAF-107A-10M0000000_BOX
EX-385-DAF-107A-10M0000000_BOX
EX-400-0002-10M000000-BOX
EX-400-0005-60M000000_BOX
QF70.0-20000/09
PX-509-0026-16M0000000
TX-7070-EFE-106A-39M7265000
VC-709-0046-156M250000
TX-707-0015-40M0000000_SNPB
PX-7024-EAZ-JXLX-32K7680000
PX-7024-EA3-YAXX-14M7456000
PX-7024-0069-8M00000000
TQY2426B-120M000000
OX-4050-DET-2072-100M000000
OX-170-0108T-10M0000000
MQF21.4-3400/07
MQF21.6-4400/03
EX-4211-EEE-7582-100M000000
MX-060-0004-32M0000000
0426CCEX11M05920_SNPB
1420R147M4560BF
1420D147M4560BX
C1555A1-0021
C1555A1-0020
PX-7020-EA3-YXXX-7M37200000
1157R50M00000BF
1157R30M00000BF
1157D50M00000BX
CO-484A-2XR-125MHZ
EX-219-DAK-508-FSS-10M0000000
1118R40M00000BB
EX-219-0005-10M2400000
EX-219-0006-10M2400000
VX-4000-0011-24M5785000
011699-0504-10M000000
TX-5500-EAE-106A-60M0000000
TX-189-0012-100M000000

PCN_NTDO-19HYTI032
Affected CPN list
TX-189-0013-100M000000
VX-501-0257-122M88
EX-4210-DAE-5083-10M0000000
SB5AA
SB5AB
SB5AC
SB5AD
SB5AE
SB5AF
SB5AG
SB5AH
SB5AI
SB5AJ
SB5AK
SB5AL
SB5AM
SB5AN
SB5AO
SB5AP
SB5AQ
SB5AR
SB5AS
SB5AT
SB5AU
SB5AV
SB5AW
SB5AX
SB5AY
SB5AZ
SB5BA
SB5BB
SB5BC
SB5BD
SB5BE
SB5BF
SB5BG
SB5BH
SB5BI
SB5BJ
SB5BK
SB5BL
SB5BM
SB5BN
SB3AA
SB3AB

PCN_NTDO-19HYTI032
Affected CPN list
SB3AC
SB3AD
SB3AE
SB3AF
SB3AG
SB3AH
SB3AI
SB3AJ
SB3AK
SB3AL
SB3AM
SB3AN
SB3AO
SB3AP
SB3AQ
SB3AR
SB3AS
SB3AT
TRU050-TCLGA-16M3840000
SB3AU
SB3AV
SB3AW
SB3AX
SB3AY
SB3AZ
SB3BA
SB3BB
SB3BC
SB3BD
SB3BE
SB3BF
SB3BG
SB3BH
SB3BI
SB3BJ
SB3BK
SB3BL
SB3BM
SB3BN
SB3BO
2104D100M0000DAX
SB3BP
SB3BQ
SB3BR
SB3BS

PCN_NTDO-19HYTI032
Affected CPN list
SB3BT
SB3BU
SB3BV
SB3BW
SB3BX
SB3BY
SB3BZ
SB3CA
SB3CB
SB3CC
SB3CD
SB3CE
SB3CF
SB3CG
SB3CH
SB3CI
SB3CJ
SB3CK
TX-5500-EEE-106A-80M0000000
SB3CL
SB3CM
SB3CN
SB3CO
SB3CP
SB3CQ
SB3CR
SB3CS
TX-707-0016-40M0000000
SB3CT
SB3CU
SB3CV
SB3CW
SB3CX
MQF10.7-0580/02
MQF75.0-6200/06
TFS940E
TX-550-0008-100M000000
TFS190X
EX-4210-EAE-3083-10M0000000 BOX
DX-041-0001-10M0000000
DX-041-0002-10M0000000
PX-706-0003-200M0
OX-043-0028-10M0000000
FX-500-EAE-SSNA-C4-C4
MO-9200AE-D3E-EE25M0000000

PCN_NTDO-19HYTI032
Affected CPN list
2104B80M00000KAS
1116R50M00000BF11
1116R50M00000BF21
SB3CY
SB3CZ
SB3DA
OX-200-0157-10M0000000
EX-4210-EAE-3080-10M0000000
PD-7001-EAE-NANN
PX-369-0151-25M0000000
PX-509-0027-12M0000000
PX-509-0028-20M0000000
PX-509-0029-25M0000000
PX-509-0030-33M0000000
PX-509-0031-100M0000000
TFR784
TX-7070-EFE-106C-40M0000000
HT-MM900AF-7K-EE-30M0000000
ES-200-0002-320M0000000
VX-5073-EAE-GXXX-125M0000000
TFS92H
2104D40M00000YAX
2104D100M0000YAX
1116R23M04000BF
2112B40M00000VCB
TX-400-0031-166M222222
MQF100.896-3000/02
EX-4210-EAE-5080-26M0000000
EX-4210-EEE-5082-26M0000000
OX-171-0011-10M0000000
VC-820-0026-100M0000000
MQF21.4-4000/27
EX-4210-DEJ-5081-10M0000000
1102R20M00000AF
1116C16M00000BX
TFS434P
205-000034-10M0000000
EX-4210-EEE-3087-10M0000000
MQF70.0-2500/04
MQF70.0-0600/13
VS-709-HCE-KAAN-WJ/X2
VT-822-EAE-2560-49M1520000
TX-7070-DFE-106D-40M0000000
PMRS_7.3x2.6x1.0_3L3P_UM1
PX-7000-EAC-KZAX-20M0000000

PCN_NTDO-19HYTI032
Affected CPN list
CD-700-EAE-KBNN-64M0000000
TX-707-0017-120M000000
TX-707-0018-150M000000
M55310/09-B25B40M000000
M55310/09-B15B12M000000
TFS920B
TFS398NS01_FM
TFS192AS01_FM
TFS1255AS01_FM
TX-801-0052-12M8
OX-407-0003-50M0000000
OX-2211-EAE-3091-20M000
10038692-022_E-41M113244
M55310/26-B02A32K76800
Test_SB1AM
Test_SB1AU
VC-709-0043-156M250000
PX-369-0153-40M0000000
PX-369-0155-33M0000000
QF2.7648-1600/08
MQF70.0-2500/19
TX-5500-DAJ-106A-10M0000000
VC-820-0030-25M0000000
1208B156M2500BC
TFS350M
TFS70CB
TFS70CC
TFS70CD
PX-4001-DBT-KFXX-4M00000000
TFS678C
TFS638
TFS638A
1116R36M00000BX
1102R24M00000AF11
1102R24M00000AF21
FX-102-0006
TFS310A
TX-209-0023-32M0000000
OX-170-0108N-10M0000000
1102R19M37500AF
VX-504-0006-100M0
1111R10M00000AF
1111R15M00000AF
1111R1M843200AF
1204R156M2500BF

PCN_NTDO-19HYTI032
Affected CPN list
TFS1542E
VCC1-1558-1M04857000
VK-THREE_BOND_3303M_50g_Can
1157D16M38400AX
TFS70AWS01_FM
TFS70AWS01_QM_Env/Mech_SGA
TFS70AWS01_QM_Env/Mech_SGB
TFS70AWS01_QM_Endurance_SG
TFS70AWS01_QM_AssCap_SG
TFS70AWS01_QM_Solderability_SG
TFS70AWS01_DPA
TFS496A
PX-7021-EAZ-VXXX-100M000000
TX-5500-DEE-206B-100M000000
TFS398NS01_QCI_Unit
TFS192AS01_QCI_Unit
TFS1255AS01_QCI_Unit
PX-7000-EAE-DFXX-40M0000000
1104E24M00000BF
1104E24M00000AF
TX-5500-EFJ-507A-80M0000000
2104R80M00000VAS
PX-369-0157-120M000000
TX-707-0019-16M3680000
FX-500-EAE-KNNA-D2-F6
1157B100M0000BC
TX-400-0033-21M0000000
TX-5500-EAE-206A-10M0000000
MQF75.0-2400/02
QF45.0-15000/06
TFS63N
1115C10M00000BX
1115C10M00000BE
1157R32M76800AA
EX-219-TJK-508FEN-10M0000000
EX-219-TJK-508FSS-10M0000000
EX-219-0007-30M0000000
TFS732
1157D32M76800AX
QF100.0-0400/06
TFS1176FE01
TFS1575APE01
PX-7004-EAE-DFXX-40M0000000
1116B32M00000BB
1116B48M00000BB

PCN_NTDO-19HYTI032
Affected CPN list
OX-221-9115-10M000
CO-718-0001-10M0000000
CO-718-0002-10M0000000
5319R156M2500BF
5321E112M0000BF
5321E160M0000BF
HT-MM900AC-9F-EE-12M0000000
VCC1-H3P-46M3200000
5319D156M2500BX
PX-209-0011-622M080000
PX-209-0012-622M080000
TFS501A
VX-209-0014-644M531300
TFS557
VX-209-0015-693M483000
TX-707-0020-10M0000000
TX-5500-EAE-206A-12M5000000
TFS350N
M55310/19-B11C19M66080
M55310/19-B11C40M00000
VCC6-VCP-125M000000
PX-5711-EAC-ZXXX-22M7200000
PX-5711-EAC-ZXXX-10M2400000
PX-369-0158-12M0000000
TX-5500-EAE-206A-50M0000000
MX-5030-EAE-3080-20M0
SM-S428-12H
SM-S429A-12H
SM-S430A-12H
SM-S431A-12H
SM-S433R-12H
SM-S434D-12H
SM-S435A-12H
SM-S437-12H
SM-S438A-12H
SM-S438B-12H
VC-709-121-66M6670000
VC-820-EAE-FAAN-1M84300000
CRH308_diced_chip
TFS1540A-1
TX-801-0053-32M0
TFS1540A-2
1157R33M00000BF
1157R33M00000BX
1157R30M00000BX

PCN_NTDO-19HYTI032
Affected CPN list
TFS1220H-1
TFS1220H-2
TFS1220R-1
TFS1220R-2
TFS1220R-3
TFS1220R-4
MD-1740-DXE-DAOC-10M0000000
VC-709-121-148M351600
OX-171-0012-10M0000000
VX-701-0044-160M0
5221D125M0000BX
1204B200M0000BG
1117R36M86400BF
OX-401-9015-98M304
OX-200-0160-10M0000000
PX-4001-DBT-KXXB-8M0000000
2104D40M92000KAX
MD-1710-DEE-DAOC-10M0000000
MD-1710-DEE-DAOC-10M0000000
MO-9000AE-7E-EE-33M3333000
TFR1000D
PX-501-0047-213M33
1157D30M00000BX
1103D7M370000BX
PX-5712-HAC-DKXB-125M000000
TFS1445
PX-4003-DAE-SSXX-11M2896000
EX-4001-DAA-1070-25M0000000
EX-4210-DEE-3087-20M0000000
1304R120M0000BF
1280D61M38000BX
PX-369-0159-200M00
PX-369-0160-200M00
EX-4210-EAE-3083-12M8000000
EX-4002-DEE-1072-40M0000000
OX-2211-DAE-3091-10M000
PX-369-0161-156M250000
OX-041-0045-10M0000000
OX-171-0013-10M0000000
1104R66M60000BF
1104B50M00000BC
1104B66M60000BC
1104B100M0000BC
1104B50M00000BX
1104B66M60000BX

PCN_NTDO-19HYTI032
Affected CPN list
1104B100M0000BX
TQY2609-10M000000
5319D693M4830BF_ENG
1208D200M0000BF_ENG
1216D200M0000BF_ENG
315-0099-080-10M240000
315-0099-100-10M240000
TX-707-0021-20M0000000
MQF21.4-2400/13
MQF21.4-2500/16
2104B80M00000KAX
MQF21.4-1500/24
1157D100M0000BX
PX-7000-EAC-ZKXB-12M0000000
PX-7000-EAC-ZKXB-16M0000000
PX-7000-EAC-ZKXB-27M0000000
PX-7000-EAC-ZKXB-32M0000000
PX-7000-EAC-ZKXB-40M0000000
PX-7000-EAC-ZKXB-50M0000000
PX-7000-EAC-ZKXB-56M0000000
PX-7000-EAC-ZKXB-70M0000000
5319B156M2500BX
5321D160M0000BX
TFS1312
TFS1600A
TX-5500-DEE-106A-100M000000
PX-489-0023-66M0000000
PX-501-0048-320M0
TX-5500-EAE-106A-26M0000000
TFS175P
TFS150BA
TFS1552B
VT-840-EFE-5070-26M0000000
TFS1584B
TFS1578
1157V10M00000BX
1157V25M00000BX
1157V50M00000BX
QF10.7-0050/11
OX-3050-BEJ-1072-100M000000
CO-402B-2X-18.432MHZ
MQF26.0663-3000/02
1103R16M00000BF11
EX-219-TJD-107FEN-107M205000
1116R600K0000BA

PCN_NTDO-19HYTI032
Affected CPN list
1116R600K0000BX
MQF45.0-5000/28
MQF136.975-1500/GN
OX-171-0014-10M0000000
TX-5500-DAE-106A-10M0000000
2102R20M00000YAS
1204B100M0000BX
1157B10M00000BX
MD-171-0003
PX-7001-HDF-FKAB-125M000000
2102D20M00000YAX
PX-369-0162-2M40000000
VXB2-1KE-10-25M0000000
EX-4210-EAE-5083-50M0000000
MX-503-0001-20M0
MX-503-0021-10M0
VS-800-EGE-EANN-1G60000000
1208B156M2500BE
MQF45.0-1300/03
OX-081-0001-10M2400000
VT-820-1122-25M0006250
A-1009-Y-1-95M975500
A-1009-Y-2-96M005000
TX-209-0028-64M0000000
VX-501-0238-10M0
TX-7070-EAE-106A-16M7772160
TX-5500-EFE-106B-80M0000000
1117R8M000000AD
PX-489-0024-50M0000000
PX-489-0025-20M0000000
MQF10.0-0300/04-01
MQF10.7-1500/55-01
VC-820-0010-114M285000
TX-7070-EFE-106C-16M3680000
TX-400-0035-50M0000000
CO-402V-KX-12.159MHZ
CO-402B-2B-50MHZ
D016515-0001-25M000000
EX-4210-DEE-1076-100M000000
OX-171-0015-10M0000000
EX-4210-DEE-3084-20M0000000
5319D120M0000BX
1157B100M0000BE
1116C25M00000BX
1116C32M76800BX

PCN_NTDO-19HYTI032
Affected CPN list
1116C20M00000BX
1116C80M00000BX
VS-709-ECE-SAAN-WJ/X2
TFS63S
5319R230M0000BF
EX-219-0009-89M7270125
TX-249-0054-122M062500
1103D33M55443BX
1103R33M55443BF11
TX-5500-DAE-106B-16M0000000
PX-4210-DAC-SXAX-25M0000000
PX-4210-DAC-SXAX-40M0000000
1116R27M00000BF
PX-700-0062-24M0000000
PX-4000-DBC-DSXX-3M68640000
PX-4000-DBC-DSXX-40M0000000
EX-4002-DEE-1071-10M0000000_BOX
TFS242B
1103V100M0000BC
PX-489-0026-24M0000000
PX-489-0027-36M0000000
1103D37M50000BX
MX-6000-EAE-3081-10M0
OX-204-0016-10M0000000
TFS307C
EX-219-TJD-107FEN-100M000000
PX-7004-EAE-KXAB-66M6600000
PX-7005-HDC-FKAB-312M500000
TFS63R
QF2.7648-0600/08
QF2.76635-0250/08
TFS92K
TFR1000C
PX-369-0166-120M000000
PX-409-0027-100M000000
VK-LMWS_6.2x4.4_Y0253
865138-0001-6M000000
MCF45.0-20/S1
1103R48M00000BF11
CO-441A-7X-14M74560
CO-441A-7X-20M00000
CO-441A-7X-32M00000
1157R66M00000BX
1157R66M00000BF
1103D29M49120BX

PCN_NTDO-19HYTI032
Affected CPN list
VK-PCSA_3.8x3.8_08P_BV30.1.B4-0
VS-800-EGE-EANN-2G50000000
VS-800-EGE-EANN-2G00000000
EX-4211-DEE-3082-10M0000000
CD-700-EAE-KBNN-26M8800000
VT-800-EFE-106A-10M0000000
OX-170-0133-10M0000000
1103C48M00000BX
OX-221-0119-10M000
VK-PMRS_7.3x2.6x1.0_3L2P_UM5
VS-800-EGE-AANN-2G50000000
VS-800-EGE-EANN-2G94912000
MQF40.455-0600/02
TFS500D
TFS1210D
VCC1-B3R-33M3330000
QF70.0-7000/06
0429ACXB16M0000_SNPB
PX-7000-EAC-ZXXX-25M0000000
XT3180-01-REVD-60M001700
PX-5713-EAC-ZXXX-80M0000000
TFS367
ES-200-0001-99-320M000000
1103D58M98240BX
1104R96M00000AF21
301-1064-003-10M560000
301-1064-004-8M000000
301-1064-005-30M503000
301-1064-006-30M200000
13012-0525
MD-1710-DAE-DAOC-10M0000000
MD-1710-DAE-DAOC-10M0000000
TRU050-GBLFB-51M8400000
MQF45.0-5000/31
MQF75.0-3000/09
TFS1315S01_FM
TFS1188S01_FM
TFS2225S01_FM
TFS2030S01_FM
TFS455HS01_FM
TFS586AS01_FM
TFS1430BS01_FM
TFS385S01_FM
TFS1091AS01_FM
TFS1390S01_FM

PCN_NTDO-19HYTI032
Affected CPN list
TFS1575ACS02_FM
TFS1643S01_FM
TFS707BS01_FM
TFS986BS01_FM
TFS1068CS01_FM
TFS1900DS01_FM
TFS1965BS01_FM
TFS2095S01_FM
TFS2140DS01_FM
TFS820AS01_FM
TFS1510AS01_FM
TFS653AS01_FM
TFS922CS01_FM
TFS653A
TFS1188S01_QM_Environ/Mech_SG_A
TFS1188S01_QM_Environ/Mech_SG_B
TFS1188S01_QM_Endurance_SG
TFS1188S01_QM_AssCap_Sold_SG
TFS1430BS01_QM_Environ/Mech_SG_A
TFS1430BS01_QM_Environ/Mech_SG_B
TFS1430BS01_QM_Endurance_SG
TFS1430BS01_QM_AssCap_Sold_SG
TFS385S01_QM_Environ/Mech_SG_A
TFS385S01_QM_Environ/Mech_SG_B
TFS385S01_QM_Endurance_SG
TFS385S01_QM_AssCap_Sold_SG
TFS1091AS01_QM_Environ/Mech_SG_A
TFS1091AS01_QM_Environ/Mech_SG_B
TFS1091AS01_QM_Endurance_SG
TFS1091AS01_QM_AssCap_Sold_SG
TFS922CS01_QM_Environ/Mech_SG_A
TFS922CS01_QM_Environ/Mech_SG_B
TFS922CS01_QM_Endurance_SG
TFS922CS01_QM_AssCap_Sold_SG
MQF72.0-2500/02
13012-0516-21M600000
M55310/28-B01A11M05920
1103R20M00000BF11
PX-489-0029-40M0000000
TFS115M
TX-5500-EAE-507B-10M0000000
TX-7070-EAE-206A-50M0000000
EX-4210-EEE-5085-40M0000000
TFS1795A
Sealed_Packages

PCN_NTDO-19HYTI032
Affected CPN list
XR-P111-1DE-CBAA-27M000000
MC741A1-1004
MQF91.65-0900/01
MQF91.65-2000/02
VK-Ceriumoxyd-polisher_CERI_900Q
PX-7021-EA6-VXXX-20M0000000
PX-709-0012-1M600
TX-7070-EFE-106C-48M0000000
TFS325F
TFS325G
TX-5500-EFE-106B-100M000000
SP-I-023-10M230000
5116D80M00000LX
5219D100M0000BX
TFS1457A
MX-041-0041-10M0000000
TX-7070-EAE-106C-32M7680000
PX-5712-0001-25M0000000
PX-5712-0002-50M0000000
PX-7021-0001-65M5360000
EX-4210-0003-10M0000000
EX-4210-0004-10M0000000
PS-508-0003-1748M366885
TX-249-0055-128M3203125
TX-249-0061-128M125000
1109R4M000000BB
1103R25M00000BF
1103C10M00000BX
1116R64M00000BF
2102R64M00000KAX
1157R10M00000BA
MX-0410-BEJ-1091-10M0000000
EX-4210-EAE-5083-50M0000000 BOX
VCC1-B3D-50M0000000_MH
TFS100M
OX-1714-EAE-8000-10M0000000
OX-1714-EAE-2090-20M0000000
PX-369-0170-66M0000000
VX-5010-EAE-3050-20M48
TDX1220W
81X-775P012-111M666666
EX-385-0001-20M0000000
HT-MM900AC-6E-XXX-000.FP0000
HT-MM900AC-7E-XXX-000.FP0000
HT-MM900AC-9E-XXX-000.FP0000

PCN_NTDO-19HYTI032
Affected CPN list
TX-209-0027-64M0000000
TX-209-0026-64M0000000
EX-4210-0005-10M0000000
VX-5073-ECE-GXXX-240M000000
CO-484A-2XR-120MHZ
TX-249-0056-35M0234375
VS-800-EGE-EANN-2G45760000
582R113H01-20M000000
TX-5500-EFE-106B-61M4400000
TFS608A
M55310/30-B11B22M33000
EX-4010-0001-11M6800000
1120R40M00000AF
C5310A1-0202-92M16
C5310A1-0248-400M0
VX-501-0151-300M000
5319R200M0000BF
MD-1710-DEJ-DAOC-10M0000000
VX-501-0085-36M864
448Y2428-40MHZ
VCC6-RCF-125M000000_SNPB
13012-0539-30M603000
TFS240AB
TX-209-0029-40M9600000
OX-249-0024-64M0000000
VCC1-B3P-100M000000
VCC6-RAP-106M250000
VX-501-0142-100M0
VX-501-0146-80M0
1105D78M12500BX
1119D50M00000BX
1119R50M00000BF
OX-204-0006
OX-204-0012
HT-MM900AC-SE-XXX-000.FP0000
PX-369-0128-156M25-PS173
PX-508-0007-120M0000
1101D24M00000BX
VC-709-0050-212M500000
TFS869P
C2525A1-0093
1107D1M400000BX
PX-369-0174-2M40000000
PX-509-0033-66M0000000
TFS315RM01

PCN_NTDO-19HYTI032
Affected CPN list
1319B500M0000BF
M55310/30-B11A16M00000_SNPB
M55310/16-B41A21M29767
TX-7070-EFE-106C-16M3686400
VK-BLS-B16-D180
EX-219-TJD-157FEN-81M8340000
1157R38M88000AA
1157D38M88000AX
C1460A1-0063P
TFS246U
1157R16M00000BA
TX-7080-EAE-106A-160M000000
MQF21.4-4000/28
VX-501-0222-63M0
VX-501-0224-65M0
VX-501-0237-120M0
VX-501-0252-100M0
VX-501-0255-80M0
TX-249-0062-128M1328125
V42311-Z60-A68-51
PX-709-0015-16M0000000
1404D48M00000BX
1120R20M00000BF
1103R37M50000BF
PX-509-0034-24M0000000
PX-509-0035-32M7680000
PX-509-0036-40M0000000
PX-509-0037-80M0000000
EX-380-0001-10M0000000
VCC6-1335-125M000000
OX-208-0005-10M0000000
VX-501-0270-1000M0
EX-4210-0007-10M0000000
TX-704-0023-20M0
M55310/16-B21A400K0000
OX-6011-EAE-1080-10M000
TFS1643D
TFS150BB
MQF90.0-4400/02
MX-600-0007-40M0
VX-5050-EAF-4550-50M0
VK-LMWS_7.7x3.0x7.5_GEC-B01-003
TFS1995
81X-775P002-110M921300
81X-853P001-90M000000

PCN_NTDO-19HYTI032
Affected CPN list
FX-500-LAC-GNK-H2-H2_SNPB
1157V70M00000BX
VX-501-0265-245M76
TFS1601B
HT-MM901AC-9E-XXX-000.FP0000
HT-MM901AC-7E-XXX-000.FP0000
HT-MM901AC-6E-XXX-000.FP0000
HT-MM901AC-4E-XXX-000.FP0000
HT-MM901AC-2E-XXX-000.FP0000
1157D40M00000BX
1157D20M00000BX
MD-010-0011-10M0000000
CD-700-EAE-SKNA-12M8000000
1116D15M36000BX
OX-2040-BEE-2086-10M0000000
TFS1621H
M55310/16-B41A24M39125
OX-401-9016-20M000
3427ACEX12M0000_SNPB
TX-209-0030-64M0000000
TX-309-0026-40M0000000
1103C50M00000BX
TFS922D
OX-4051-DAE-2072-100M0000000
010854-0587-20M0000000
TFS1552C
OX-2080-DAE-8000-10M0000000
TX-5500-EAE-206A-100M0000000
EX-380-0001-10M0000000_BOX
EX-4211-DEE-3084-10M0000000
TX-189-0014-100M0000000
TX-189-0015-100M0000000
EX-4210-EAE-3083-40M0000000
TX-5500-EAE-106A-100M0000000
TFS120T
MQF21.4-4000/29
CO-402A-1X-4.0000MHZ
TX-3210-EEE-106A-50M0000000
PX-7020-E520-48M0000000
2112D100M0000TAX
1103R80M00000BF11
1103R58M98240BF11
2104D33M554432VBX
1103R4M194304BF
EX-4210-DEE-7581-100M0000000_BOX

PCN_NTDO-19HYTI032
Affected CPN list
TX-189-0016-136M000000
PX-7021-0003-50M0000000
MO-9200AE-D3E-XXX000.FP0000
1105D60M00000BX
TFS1176E
TFS1227G
TFS1542G
1240D156M2500BX
TX-707-0022-40M0000000
FM-S433W-GG_9001303306
FM-S433X-GG_9001303307
TFS207F
TFS207G
OX-249-0027-80M0000000
1157R64M00000BC
VC-801-EAE-FAAN-50M0000000
TX-550-0009-100M000000
VS-369-0012-300M277760
MX-5030-EAE-3080-25M0
MO-9200AE-D5E-XXX000.FP0000
MO-9250AE-C1E-XXX000.FP0000
MO-9250AE-C3E-XXX000.FP0000
MO-9250AE-C5E-XXX000.FP0000
MO-9250AE-D1E-XXX000.FP0000
MO-9250AE-D3E-XXX000.FP0000
MO-9250AE-D5E-XXX000.FP0000
SB4AK
SB4AL
SB4AM
SB4AN
SB4AO
SB4AP
SB4AQ
SB4AR
SB4AS
SB4AT
SB4AU
SB4AV
SB4AW
SB4AX
SB4AY
SB4AZ
SB4BA
SB4BB
SB4BC

PCN_NTDO-19HYTI032
Affected CPN list
SB4BD
SB4BE
SB4BF
SB4BG
SB4BH
SB4BI
SB4BJ
SB4BK
SB4BL
SB4BM
SB4BN
SB4BO
SB4BP
1119B100M0000BX
1116V40M00000BA
1157R16M00000BF
1157D16M00000BX
VX-505-0002-491M52
TFS120U
TX-7070-EAE-106C-46M7200000
TX-7070-EAJ-206A-50M0000000
TX-7070-EAJ-206A-52M0000000
1116R46M08000BF
CO-408A-7B-6MHZ
OX-200-0163-10M0000000
PX-369-0176-125M000000
PX-369-0177-156M250000
PX-369-0178-200M000000
PX-990-0012-120M000000
TFS324
MO-9000AJ-7F-JE-100M000000
967009-002-40M000000
EX-219-0010-30M0000000
MQF121.500-1500/GN
MQF124.700-1500/GN
MQF118.500-1500/GN
MQF119.000-1500/GN
MQF119.700-1500/GN
MQF121.200-1500/GN
MQF124.000-1500/GN
MQF127.100-1500/GN
MQF128.200-1500/GN
MQF130.600-1500/GN
MQF132.400-1500/GN
MQF121.700-1500/GN

PCN_NTDO-19HYTI032
Affected CPN list
1157D24M00000BX
1157D80M00000BX
OX-4011-EAE-0580-20M000
EX-219-0014-100M000000
EX-4210-DEJ-1074-36M0000000
PX-5702-DAZ-JXXX-12M0000000
VX-7081-EAY-FXXX-16M0000000
VX-7081-EAY-FXXX-4M00000000
M55310/27-B01A4M000000
1105D52M50000BX
1105D70M00000BX
1116R72M00000BF
OX-208-0003-10M0000000
1119D80M00000BX
C2260A1-0186-10M0
TFS1638
TFS1662
TFS866C
M55310/26-B32B16M77216
PX-7004-EAC-ZKXB-40M0000000
PX-7004-EAC-ZKXB-24M0000000
PX-7004-EAC-ZKXB-48M0000000
PX-7004-JAC-ZKXB-25M0000000
TFS412C
XR-P111-1EE-KAAA-8M000000
OX-4053-EAE-5080-108M000000
MQF45.0-10000/03
BAV021620A010CDFS
TFS433AL
PX-369-0181-200M000000
PX-369-0182-100M000000
TX-550-0010-76M8000000
PX-4200-EA5-SXXX-8M19200000
TX-3210-EAE-106A-50M0000000
PX-5701-EA6-VAXX-7M37280000
PX-7020-EA6-VAXX-7M37280000
PX-489-0035-156M250000
PX-489-0036-125M000000
1116E16M00000BF
EX-4211-DEE-3086-10M0000000
M55310/16-B34A6M144000
TX-707-0024-20M0000000
TX-550-0011-20M0000000
2202R10M00000BAK
VX-5040-EAE-3050-125M0

PCN_NTDO-19HYTI032
Affected CPN list
VK-PMRS_8.0dx13.2_3L3P_HC-49/U
VK-CMRS_10.7x10.7x4.3_HC-49/U
EX-4210-DEE-1076-73M7280000
QF23.1-12500/07
QF23.3-12500/07
VS-800-EEU-EANN-2G50000000
1204D143M7500BX
1204R143M7500BF
VX-504-0012-122M88
C5310A1-0320-S-200M0
VT-800-DFJ-1060-25M0000000
PX-700-0064-100M000000_SNPB
PX-700-0065-100M000000_SNPB
PX-4214-DBE-DFXX-25M0000000
2212D67M18750MBX
1220D200M0000BX
1320D156M2500BX
PX-509-0038-50M0000000
1157D25M00000BX
TFS1950F
1101D10M00000BX
1204R128M0000BG
2212D80M00000KBX
1116D96M00000BX-PB
TX-249-0065-129M296875
TFS1080K
C1460A1-0117
VX-501-0276-245M76
VX-501-0275-491M52
VX-501-0274-256M0
EX-4210-EEE-5082-10M0000000
TFS427
PX-7001-HCB-PKAX-312M500000
PX-7001-HCB-PKAX-125M000000
PX-7001-HCB-PKAX-100M000000
TX-7070-EFE-106C-30M0000000
5321E156M2500BD
VC-826-EDE-FAAN-128M000000
ES-200-0003-320M000000
ES-200-0004-320M000000
ES-200-0099-320M000000
600-101289-3-3M168768
600-006373-5-15M679861
600-101291-30-37M631667
OX-204-0017-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
TX-7070-EFE-106C-25M0000000
OX-200-0164-10M0000000
TX-707-0025-40M0000000
OX-221-0123-10M000
XR-R111-1EF-FFAA-13M200000
PX-4210-DBT-SSAB-20M0000000
TFS1080L
1116C75M00000BX
1103R4M000000BF
1103R14M74560BF
1103R24M57600BF
TX-189-0017-136M000000
PX-4210-DAC-SXXB-20M0000000
PX-5002-EAE-SXXB-20M0000000
PX-5002-EAE-SXXB-66M0000000
QF16.5550-0300/03
QF12.3860-0300/03
QF8.7045-0300/03
QF8.5890-0300/03
QF8.3140-0300/03
QF6.4460-0300/03
QF6.4180-0300/03
QF6.2510-0300/03
QF4.2920-0300/03
QF4.2325-0300/03
QF4.1540-0300/03
EX-4210-EAJ-2083-16M3840000
OX-407-0004-50M0000000
5116D100M0000WX
1157R12M00000AF
PX-7020-EAZ-JXUX-32K7680000
VS-800-EGE-EANN-2G87500000
MQF156.350-1500/J
MQF156.225-1500/J
TX-249-0066-80M0000000
PX-7021-EAZ-JXUX-32K7680000
TX-249-0068-24M0000000
0429ACXB14M3180_SNPB
MX-041-0042-10M0000000
M55310/30-B31A66M600000
1620D156M2500BX
1620D200M0000BX
PX-369-0188-40M0000000
PX-369-0189-50M0000000
TX-189-0018-100M000000

PCN_NTDO-19HYTI032
Affected CPN list
MO-9200AE-D5E-HE100M000000
1204D160M0000BX
VT-501-EAK-1060-10M0000000
EX-4010-DEE-7586-100M000000
TX-5500-DAE-507B-100M000000
TX-209-0031-100M000000
PX-7004-EAE-KKAX-10M0000000
PX-369-0192-22M1184000
VS-800-EEU-EANN-1G00000000
VS-800-EGU-EANN-1G00000000
PX-7000-EAC-ZXXX-50M0000000
011126-0511-10M000000
1157R100M0000BF
TX-5500-DAE-507A-120M000000
PX-7026-E630-100M000000
PX-7026-E630-125M000000
EX-4210-EAE-7580-52M0000000
C1310A1-0072-200M0
QF70.0-8000/09
PX-7000-EAA-KXXX-63M9360000
MQF10.0-0500/06
OX-990-0072-28M53515625
OX-990-0076-30M00000000
TFS748B
SVO100-44-77M76
TFS634
1208D104M0000BX
TFS1600C
TFS1800D
TFS2000D
TFS451B
TFS468U
VS-800-EGU-AANN-1G60000000
MO-9150AE-6E-HS-133M000000
M55310/16-B31A17M03814
MO-9100AE-6E-HS-80M0000000
M55310/16-B21A3M686200
TX-7080-EAE-106A-150M000000
1103R29M49120BF
PX-409-0028-41M5800000
PX-409-0029-52M5000000
PX-409-0030-60M0000000
PX-409-0031-70M0000000
PX-409-0032-78M1250000
PX-409-0033-65M3460000

PCN_NTDO-19HYTI032
Affected CPN list
VX-209-0018-120M000000
TX-5500-EEE-106A-100M000000
VX-701-0045-80M0
81X-774P008-104M674200
MQF130.05-4000/01
MQF70.05-4000/01
XT1865B-REVB-20M0
PX-5712-0003-32M0000000
1220D100M0000BX
MQF45.0-1500/29
TFS938
TFS938A
TFS938B
TFS939A
TFS940F
TFS941A
TFS941B
TFS942H
TFS385B
TX-7070-EFE-106D-20M0000000
1157V40M00000BX
1208R104M0000BF
PX-509-0041-6M50000000
TX-5500-EAE-106B-10M0000000
PX-369-0193-50M0000000
PX-369-0194-50M0000000
OX-249-0028-40M0000000
OX-249-0029-40M0000000
OX-221-9125-12M800
M55310/16-B34A15M000000_SNPB
TFS178AS01_FM
TFS178AS01_QM_Environ/Mech_SG_A
TFS178AS01_QM_Environ/Mech_SG_B
TFS178AS01_QM_Endurance_SG
TFS178AS01_QM_AssCap_SG
TFS178AS01_QM_Solderability_SG
TFS63U
MQF130.05-5000/01
PX-709-0017-16M00
FX-400-0007
1116E14M74560BF
13458089-21M600000
600-012358-2-4M096000
V50500-A1-B293-53
C5310A1-0203

PCN_NTDO-19HYTI032
Affected CPN list
1157R50M00000BX
PX-369-0199-29M4912000
VX-501-0110-160M0
TX-5500-DEE-507A-100M000000
EX-4210-DAJ-5083-50M0000000
TX-707-0026-20M4608000
EX-219-0017-98M0000000
EX-219-0018-98M0000000
PX-7001-EDC-KXXX-500M000000
TX-7080-EAE-106D-100M000000
MX-600-0011-25M0
81X-777P003-133M437500
PX-7021-DA5-SXXX-32K7680000
PX-369-0201-50M0000000
PX-369-0202-40M0000000
1105D1M048570AX
2102D33M55443YBX
TX-209-0032-24M0000000
TX-209-0033-24M0000000
1103R7M370000BF
QF140.0-0400/02
QF70.0-10000/14
TX-707-0027-40M0000000
TX-7070-EAE-206C-10M2300000
TFS2000E
VX-501-0279-1000M0
TFS457B
TFS452F
TFS442
TFS437B
TFS432B
TFS447
TFS1176H
TFS1575AR
TFS978B
TX-209-0036-32M7680000
TX-209-0037-32M7680000
TX-189-0019-26M1979170
TX-189-0020-26M1979170
PX-369-0203-7M37280000
FX-500-EAE-KNNA-AR-BB
PX-700-0066-40M0000000
TX-5500-DAE-106A-100M000000
PX-4210-DAE-FKXX-1M22450000
TFS123N

PCN_NTDO-19HYTI032
Affected CPN list
1101R1M400000BF
1101R24M00000BF
PX-489-0038-48M0000000
1403R48M00000BF
VX-7060-ECE-3051-240M0
PX-5002-EBB-KKXX-50M0000000
OX-170-0135-10M0000000
C1310A1-0038-160M0
TDX1220X
TX-309-0027-80M0000000
5219D156M2500BX
PX-706-0011-128M0
VS-800-EGE-EANN-2G04288000
2105D1M000000MAX
TFS234
TX-707-0028-48M0000000
TX-5500-EEE-106B-10M0000000
TX-7070-EAE-206A-10M0000000
2112D40M96000KBX
VX-501-0282-50M0
TFS490B
PX-7002-EAE-FFAB-50M0000000
PX-369-0204-40M0000000
PX-369-0205-22M1184000
PX-369-0206-125M000000
PX-369-0207-156M250000
PX-369-0208-200M000000
TX-5500-DEE-106B-100M000000
TX-7070-EFE-106C-50M0000000
1220R50M00000BF
TFS1023
PX-5002-EAC-SXAB-20M0000000
PX-5002-EAC-SXAB-40M0000000
M55310/27-B01A5M000000
1304C156M2500BX
1157C68M00000BG
PX-7001-HD7-KKXB-100M000000
EX-219-CJF-107ASS-10M0000000
OX-2211-EAE-3090-25M000
1196721-01FM-54M950000
1196721-03FM-59M900000
1196721-04FM-60M000000
1196721-07FM-60M642857
1196721-13FM-62M450000
1196721-22FM-64M125000

PCN_NTDO-19HYTI032
Affected CPN list
1196721-23FM-64M214286
1196721-17FM-63M461538
1196721-20FM-63M750000
1404R32M00000BF
1101R80M00000BX
TFS324S01_FM
TFS324S01_QM_Environ/Mech_SG_A
TFS324S01_QM_Environ/Mech_SG_B
TFS324S01_QM_Endurance_SG
TFS324S01_QM_AssCap_SG
TFS324S01_QM_Solderability_SG
PX-509-0042-75M0000000
TFS382A
TX-5500-EEJ-106A-100M000000
TFS110Z
1208D156M2500BX
TX-5500-GAE-106A-100M000000
TX-550-0012-10M0000000
TX-550-0013-20M0000000
TFS402B
TFS407A
TFS417
TFS422A
VS-504-0007-S
TX-5500-EEE-106B-50M0000000
OX-249-CAF-107FEN-100M000000
PX-5002-EAE-KKAB-10M0000000
PX-489-0041-25M0000000
2102R48M00000KAX
1240R156M2500BF
TFS1795B
1157D66M00000BX
1157R16M38400AF
TX-707-0029-16M3680000
TFS100NM01
1504F40M00000BF
TX-707-0030-20M0000000
TX-707-0031-20M0000000
TX-707-0032-40M0000000
TX-707-0033-40M0000000
TFS1815
PX-7021-E610-100M000000
TX-5500-DAE-507B-10M0000000
2105R1M000000VAS
2205D80M00000WAX

PCN_NTDO-19HYTI032
Affected CPN list
TFS722A
TFS2007
C3430A1-0081-S2-430M08
1504B40M00000BF
1103R16M00000BF21
PX-7021-E610-25M0000000
M55310/16-B11B16K38400
2205R80M00000WAS
MQF10.0-0300/07
PX-5701-EA1-SXXX-3M68640000
TX-7070-EAJ-106B-48M0000000
VT-800-EFJ-106B-10M0000000
OX-221-0129-49M152
OX-221-0130-57M1425
MX-5030-EAE-3080-24M0
MX-5030-EAE-3080-24M576
2105D25M00000YAX
PX-489-0042-24M0000000
PX-489-0043-24M0000000
PX-369-0210-8M00000000
TFS1210F
2102D24M00000WBX - see long desc
VXA4-300-58M9824000
VXA4-300-29M4912000
HT-MM900AC-7F-ES-40M0000000
EX-4000-EAE-1070-10M0000000
OX-171-0018-30M7200000
TFR800F
TX-707-0034-40M0000000
TX-5500-GAJ-106B-96M0000000
TX-5500-EAE-206A-66M0000000
TX-7070-EAE-106D-20M0000000
OX-6011-EAE-2080-20M000
OX-6011-EAE-2080-25M000
PX-7020-EA2-WXLX-3M68640000
PX-369-0211-50M0000000
PX-7004-EAC-ZKXB-25M0000000
OX-1741-DAJ-5095-10M0000000
1220R100M00000BF
1220R66M00000BF
TFS434S
TFS1000F
VX-5001-ECT-GXXX-600M000000
011577-0503-40M0000000
1204D140M00000BX

PCN_NTDO-19HYTI032
Affected CPN list
TFS1795M01
0429ACXB01M50000
TFR1440
TX-707-0035-20M0000000
Xtal_20.034_Mhz_HC37
VS-800-EGE-EANN-2G36544000
TX-550-0014-25M0000000
TX-550-0015-40M0000000
OX-220-0153-10M000
1157D32M00000BX
1110R100M0000BF
1110R56M05600BF
1103D19M20000BX
1103R19M20000BF
EX-219-DAD-758FEN-10M0000000
PX-369-0213-8M00000000
TX-7070-EAE-206B-50M0000000
MD-173-0010-10M0000000
TX-7080-EAE-106C-120M000000
TX-7080-EAE-106A-155M520000
Xtal_50.95_MHz_HC35
OX-1715-DAE-2090-20M0000000
TFS1812
VS-800-EEU-EANN-969M0
VS-800-EEU-EANN-1G2000
PX-400-0032-1M00000000
VS-800-EGE-EANN-2G88080000
PX-7021-EAZ-WXXX-3M00000000
PX-7021-EAZ-WXXX-7M50000000
PX-7021-EAZ-WXXX-20M0000000
PX-7021-EAZ-WXXX-24M0000000
1116R40M00000AB
OX-5021-EAE-1080-24M576
OX-1741-DEE-1081-10M0000000
PX-7021-JAZ-WXXX-7M50000000
M55310/26-B03A32K76800
OX-228-0004-20M000
1404D64M00000BX
1404D32M00000BX
1404D100M00000BX
TFS332B
1308D200M00000BX
1104D8M0000000BX
5321D560M4000BX
TFS899

PCN_NTDO-19HYTI032
Affected CPN list
TFS938C
PX-369-0214-64M0000000
PX-369-0215-64M0000000
PX-369-0216-25M0000000
311206626-100M000000
1109R4M000000BF
1157R32M00000BF
TFS895C
TFS850H
TFS160W
FX-500-EAE-KNNN-A3-E6_SNPB
1103B60M00000BG
1157B48M00000BG
1157B48M00000AG
TX-707-0036-40M0000000
1103E25M00000BD
OX-601-0007-20M000
VX-501-0283-204M8
VX-501-0284-312M5
M55310/19-B01A10M00000_SNPB
MX-0600-DET-2001-10M0000000
PX-709-0021-16M0000000
VCC1-B2C-80M0000000
M55310/26-C33A16M00000
M55310/26-C33A16M00000
TFS1575DS02_FM
TFS1575DS02_QM_Env/Mech_SGA
TFS1575DS02_QM_Env/Mech_SGB
TFS1575DS02_QM_Endurance_SG
TFS1575DS02_QM_AssCap_SG
TFS1575DS02_QM_Solderability_SG
VS-800-EGE-EANN-2G88000000
PX-7021-E610-16M0000000
TFS1068D
1105D30M00000BX
TFS1500D
TFS1500E
1157R9M216000AF
1115D33M00000BX
PX-369-0219-33M0000000
M55310/19-B21A50M00000_SNPB
1103R16M00000AF
OX-1711-DAE-8001-10M0000000
PX-7005-HDE-FKAB-312M500000
1116R60M00000BD

PCN_NTDO-19HYTI032
Affected CPN list
1116R100M0000BD
PX-369-0221-33M0000000
VS-800-EGE-EANN-983M040000
SM-S433T-EL
SM-S433T-EL
OX-6011-EAE-2080-24M576
PX-7001-EDE-DKAB-100M000000
TFS540B
OX-204-0020-10M0000000
TFS123P
TFS520H
OX-220-0155-30M72
1157R40M00000BF
PX-489-0046-65M5360000
OX-5011-EAJ-1081-20M000
2105B16M38400WAB
2105R16M38400WAB
1419D30M00000BX
OX-220-0157-10M000
VT-803-EFH-207A-25M0000000
OX-249-0032-16M3840000
OX-5021-EAE-2080-20M000
VX-501-0285-400M0
VX-501-0286-840M0
1204C200M00000BX
2111D40M96000TBX
QF54.0-0600/03
1104R64M00000BF
1104B64M00000BG
VCC6-QAD-32M0000000
TX-189-0021-156M250000
TX-189-0022-156M250000
TX-189-0023-156M250000
6504B1G099000BB
TFS844A
00871-0903-0001
PX-509-0043-15M3600000
TX-209-0039-40M9600000
TX-7070-DFE-106D-16M3680000
MO-9100AJ-6E-JE-33M3333333
1119B65M53600BX
2205D50M00000TAX
1187R50M00000BF
1187D50M00000BX
EX-219-DJF-107AEN-10M0000000

PCN_NTDO-19HYTI032
Affected CPN list
PX-369-0223-8M00000000
MQF50.0-0600/02
PX-369-0224-24M0000000
PX-369-0225-41M9430400
2202D33M55443YBX
PX-369-0226-48M0000000
PX-7004-EAA-KXXX-63M9360000
OX-221-9133-24M576
OX-4011-EAE-0580-24M576
OX-6011-EAE-1080-20M000
OX-6011-EAE-1080-24M576
OX-5021-EAE-1080-20M000
PX-7004-EAC-ZKXB-50M0000000
VC-820-0040-19M4400000
TFS2106_EM_single
EX-219-0024-99M5192308
EX-219-0025-99M5192308-PS186
VXA4-100-58M9824000
VXA4-100-29M4912000
1105B62M50000BG
1504F66M00000BD
TFS605
M55310/16-B01A100H0000
VX-7060-ECE-3051-204M8
TX-707-0039-25M0000000
TX-707-0040-40M0000000
TX-707-0041-50M0000000
OX-990-0077-100M000000
TX-249-0073-10M000000
TFS2203_EM_single
TFS2287_EM_single
TX-707-0037-20M0000000
TX-707-0038-40M0000000
MQF168.16-1400/C
VXM7-1366-48M0000000
2205D77M76000KAX
VS-800-EGE-EANN-2G00591881
HT-MM900AC-4F-JE-25M0000000
0751BB11M059200_SNPB
OX-5021-EAE-2080-25M000
OX-2040-DEE-2084-10M0000000
TFS353A
2212D40M96000KBX
2101B23M50000KAX
1419R30M00000BG

PCN_NTDO-19HYTI032
Affected CPN list
1157B32M00000BB
M55310/19-B01A1M0000000_SNPB
1157R40M00000BD
M55310/19-B01A3M0625000_SNPB
EX-219-CAF-157ASS-40M0000000
PX-7001-HD7-KKXB-125M000000
TX-189-0024-100M000000
TFD63W
2133D125M0000TAX
TX-3210-EFE-106B-38M4000000
TX-3210-EAE-106B-38M4000000
TX-319-0005-25M0000000
2215D50M00000TAX
VT-803-FAE-287B-38M4000000
1103B33M33333BG
TFS310B
TFS310C
1157R6M000000AF
PX-369-0229-8M00000000
PX-700-0067-63M9360000
VS-800-EGE-EANN-1G00000000
EX-4211-EAE-7580-100M000000
1120B8M192000BB
5219R156M2500BX
TX-7080-EAE-106A-100M000000
1157D48M00000AX
OX-6011-EAE-1080-25M000
MD-228-0018-10M000
OX-2081-DEE-1091-10M0000000
TFS434R
MQF59.97-0600/06
PX-7021-EA2-WALX-3M68640000
TFS60K
VS-800-EGE-EANN-1G0016000
2215B50M00000WAC
HT-MM900AC-4F-EE-40M0000000
1308R100M0000BB_to_adj_xtal_ang
TFS1220Y
PX-7004-EAC-KKXB-25M0000000
FX-702-ECE-KMMM-H8-L4-M01
FX-702-EDE-KMMM-J9-L4-M01
1157D61M38000BX
1157R61M38000BA
PX-5002-DAC-KXAB-50M0000000
1157R66M66666BF

PCN_NTDO-19HYTI032
Affected CPN list
1105D2M097152AX
5116R64M51200LB
OX-249-0035-50M0000000
VS-800-EGE-EANN-3G20000000
VX-5040-EAE-3050-122M88
TFS921A
MD-015-0001-10M0000000
MD-015-0002-10M0000000
VS-504-0006-S
2205D50M00000KAX
MD-0123-BXE-15E7-10M0000000
MD-0123-BXE-40E7-10M0000000
MD-0133-BXE-15E7-10M0000000
MD-0133-BXE-40E7-10M0000000
MD-1750-DAE-15E7-10M0000000
MD-1750-DAE-40E7-10M0000000
MD-1750-DEE-15E7-10M0000000
MD-1750-DEE-40E7-10M0000000
MD-1760-DAE-15E7-10M0000000
MD-1760-DAE-40E7-10M0000000
MD-1760-DEE-15E7-10M0000000
MD-1760-DEE-40E7-10M0000000
PX-369-0234-33M0000000
PX-369-0235-64M0000000
1620F156M2500BD
1620F200M0000BD
FX-400-EAE-KNNN-C4-C4
VS-501-0007A-1701M32
VX-5050-EAC-4550-28M0000000
1196721-14FM-62M500000
1196721-34FM-57M812500
1196721-35FM-58M342857
1196721-36FM-60M556786
1196721-37FM-61M336000
1196721-38FM-61M957083
1196721-39FM-63M062500
1196721-40FM-63M636364
PX-5701-EAY-VAXX-10M0000000
PX-7021-EAZ-JXXX-3M58400000
Xtal 10MHz SC 3rd HC37
TFS550B
PX-7021-DA2-WXXX-3M68640000
2104R80M00000KAS
2205R77M76000KAS
CM112918-4M215000

PCN_NTDO-19HYTI032
Affected CPN list
OX-171-0020-10M0000000
OX-171-0021-10M0000000
TX-707-0042-25M0000000
TX-707-0043-40M0000000
2101R23M50000KAS
1321R211M6800BB
PX-4000-EAE-KXXX-100M0000000
VS-401-0003-S5-1747M62305
1117B16M00000AG
1117B80M00000BG
TFR600E
2133R125M0000TAS
HT-MM900AE-4K-EE-4M80000000
VC-709-HDE-FAAN-156M250000
VC-709-HDE-FAAN-24M5400000
VC-709-HDE-FAAN-66M6670000
VCC6-1307-33M3330000
VTC1-J1BE-16M0000000
VXM7-1355-25M0000000
MD-1730-DEE-8001-10M0000000
OX-220-0159-20M000
1103E25M00000BX
1120D24M00000BX
MQF21.4-1500/60
1120R24M00000BF
TX-209-0040-100M0000000
TX-249-0074-50M0000000
TX-249-0075-50M2350000
TX-249-0076-51M2700000
TX-249-0077-50M7200000
VK-PCB_GS20-02
VC-709-EDE-FAAN-66M6670000
VC-709-EDE-FAAN-20M0000000
5321D491M0400BX
TFS1690
5321D500M0000BX
TFS2007A
TFS2132
TFS455K
TFS387
OX-174-0010-10M0000000
1187D25M00000BX
OX-2281-EAE-5000-10M000
VX-189-0017-250M0000000
VX-189-0018-250M0000000

PCN_NTDO-19HYTI032
Affected CPN list
M55310/28-C21B40M00000_SNPB
PX-489-0048-4M00000000
TDX718
TX-5500-DEE-507B-100M000000
FX-424-DFF-S6376G
OX-403-0008-B-20M000
123-00009-000-10M000000
VCC1-B2C-33M0000000
TFR600M
311206773-5M000000
WSR-F1-EL-01A
TFS360P
PX-7003-HDC-KZXX-160M000000
TFS750B
TFS265A
TFS351A
EX-4210-EEP-1084-10M0000000
EX-4210-EEJ-2084-10M0000000
TFS482D
TFS506B
TFS530
TFS558
TFS589
TFS619
TX-5500-EAE-106A-64M0000000
TFS1650E
OX-220-0038-A-20M000
C4500C1-0081-M-12M8
MQF75.0-2200/02-01
123-00090-000-10M000000
123-00088-000-10M000000
VS-507-0008-3494M061674
1157R32M00000BD
1187R100M00000BF
TFS2203_EM_paired
TFS2287_EM_paired
TFS2106_EM_paired
1119E80M00000BF
2212E67M18750MBS
TX-7070-EAE-106D-49M1520000
MD-171-0010-30M7200000
TFS1000G
1103E50M00000BA
600-012895-3-120M000000
OX-220-0020-A-10M00

PCN_NTDO-19HYTI032
Affected CPN list
OX-220-0116-A-40M000
EX-219-CAF-157AEN-40M0000000
2202B10M00000KAB
M55310/19-B11A20M00000_SNPB
600-012895-EM-120M000000
VC-709-HDE-FAAN-125M000000_SNPB
TFS44Y
TX-5500-EEE-507A-100M000000
1115D16M00000AX
TX-3210-EAE-106B-50M0000000
PX-369-0239-156M250000
PX-369-0240-200M000000
1187D100M0000BX
2215C100M0000KAB
VT-803-FAE-287B-28M8000000
PX-7021-JA3-WXXX-3M68640000
TX-5500-EAE-507A-100M000000
VCC1-1574-16M0000000
VCC1-1574-16M0000000_SNPB
TX-7070-EAF-506A-50M0000000
TFS125V
TFS1538C
TFS1544
MX-5030-EAE-3081-24M576
OX-249-CAF-107FSS-100M000000
5116D64M51200LX
VCC1-1575-25M0000000
MX-503-0047-40M0
TFS460N
C1250A1-0060
CO-447B-2B-28.032MHZ
1321D211M6800BX
TFS100P
TX-550-0016-50M0000000
OX-5021-EAE-1080-25M000
TFS1375
MQF38.85-1200/02
PX-700-0068-33M0000000
MX-043-0001-10M0000000
HT-MM900AC-7K-EE-24M0000000_SNPB
HT-MM900AC-7K-EE-25M0000000_SNPB
1419R40M00000BF
1419D40M00000BX
600-012895-2-120M000000
5321D100M0000BX

PCN_NTDO-19HYTI032
Affected CPN list
C2260A1-0109-10M0
TX-7070-EAE-106D-30M7200000
1105R62M50000BF
TFS106F
TFS207H
TFS592A
TFS230D
PX-489-0051-25M0000000
TX-5500-DEE-106A-80M0000000
2111R40M96000TBS
PX-489-0052-25M0000000
OX-4011-EAE-0580-25M000
PX-7025-EA1-JXXX-4M09600000
TX-249-0079-10M0000000
PX-3602-DBC-DKXB-12M5000000
TX-249-0080-10M0000000
PX-369-0245-200M000000
VCC6-QAD-32M0000000_SNPB
PX-706-0013-300M0
PX-706-0013-300M0
TFS1795C
TFS630
PX-7005-EDE-FKXB-156M250000
PX-7004-JAE-KXXB-100M000000
MQF21.4-1500/90
4493430001-12M000
4484-96M000
4483-151M000
PX-369-0246-100M000000
PX-369-0247-33M0000000
TFR320D
PX-5000-EAC-FKAB-50M0000000
VCC1-B3D-133M333300
VS-800-EGE-AANN-1G60000000
VS-800-EGE-EANN-2G88_up-sc
VS-800-EGE-EANN-2G8808_up-sc
VS-800-EGE-EANN-1G0016000_up-sc
VS-800-EGE-EANN-1G00000000_up-sc
VS-800-EGE-EANN-2G88_DPA
VS-800-EGE-EANN-2G8808_DPA
VS-800-EGE-EANN-1G0016000_DPA
VS-800-EGE-EANN-1G00000000_DPA
TX-7070-DAE-106A-10M0000000
TFS241G
044-00105-0000-8M192000

PCN_NTDO-19HYTI032
Affected CPN list
1204D122M7600BX
5319D500M0000BX
PX-369-0248-100M000000
PX-4210-DAE-KKXX-16M0000000
1420D115M0000BX
PX-369-0249-200M000000
1102D96M00000AX
TFS1030H
PX-7000-EAC-ZXXX-24M0000000
PX-509-0045-100M000000
PX-509-0046-64M0000000
1103R66M00000BF
1420R115M0000BF11
PX-489-0055-156M250000
TFS1920B
TFS63X
EX-219-DAD-758FSS-10M0000000
MO-9100AE-8E-JE-50M0000000
1116R80M00000BF21
1420R115M0000BF21
1157X20M00000BX
OX-0470-BEE-3082-10M0000000
OX-6011-EAE-2080-12M800
MD-1770-DEE-10E8-10M0000000
MD-1780-DEE-10E8-10M0000000
SP-I-013D-10M000000
MD-999-0042
VS-800-EGE-EANN-2G25792000
TFS370A
1196721-41FM-64M062500
1196721-42FM-64M285714
TFS675A
TFS675B
TFS675C
1157B16M00000BX
PX-369-0250-156M250000
PX-369-0251-156M250000
PX-369-0252-156M250000
5116D100M0000LX
TFS1500F
2133D100M0000DAX
VCC1-H3R-40M0000000_SNPB
VCC1-H3R-40M0000000
PX-369-0253-125M000000
HT-MM900AE-6E-EE-40M0000000

PCN_NTDO-19HYTI032
Affected CPN list
XR-A111-1FC-KKJX-016M670000
EX-219-DJF-107ABS-10M0000000
VS-800-EGE-EANN-2G85937500
VS-800-EGE-EANN-2G83928571
OX-080-0006-10M0000000
VX-701-0046-44M0
1119D25M00000BX
OX-174-0011-10M0000000
2205D40M00000YAX
TX-5000-ECE-1060-100M000000
TFS2510
EX-4210-DEA-7581-60M0000000
PX-7020-EAC-JXUX-32K7680000
1104R24M00000AS
1216D40M00000BX
1216D80M00000BX
1216D200M00000BX
1216D156M2500BX
1216D125M00000BX
1216D160M00000BX
MD-2281-EAE-1590-10M000
054-00586-xxx
TFS2110
TFS2300
TFS1785
TFS1910D
1103R50M00000BF11
TFS1585B
TFS1680B
TFS1975
TFS2005
TFS390H
TX-7070-EAF-506C-32M0000000
PX-4211-EAE-KFXX-62M2080000
2102R16M38400TBS
1157R1M048570AF
TFS482E
TFS452G
TX-7070-EAE-106A-26M0000000
TX-7070-EAE-206A-26M0000000
TX-7070-EAE-506A-26M0000000
5116R80M00000LE
PX-489-0053-25M0000000
TFS294
TFS176A

PCN_NTDO-19HYTI032
Affected CPN list
VX-500-0010-10M0000000
2105D12M28800YAX
TX-7080-EAE-106A-125M000000
TX-7080-EAE-106C-125M000000
TFS312H
XR-2111-1FF-KKJX-016M670000
XR-A111-1FF-KKJX-03M6000000
310514-30-16M000
TFS895D
TFS128E
TFS368C
TFS367A
TFS367B
TFS367C
PX-489-0057-50M0000000
PX-489-0058-50M0000000
1419D25M00000CX
5116R100M0000LB
OX-5021-EAE-2080-12M800
VS-702-1007MV-500M000000
TFS1575AV
1116E96M00000BS
TFS1239
TFS123R
TFS173E
TFS174P
TFS1278B
TFS1980B
TFS374M
2105R16M38400VAF
1187R25M00000BX
TFS50A
M55310/16-B41A50M40000
TX-7070-EAE-506A-50M0000000
OX-221-0137-25M000
TX-7070-EAE-106A-50M0000000_SNPB
TX-7070-EAE-506A-50M0000000_SNPB
OX-5021-EAE-1080-10M000
TX-7070-EAE-106A-50M0000000_SAC
TX-7070-EAE-506A-50M0000000_SAC
MO-9200AE-D5K-EE66M6666660
OX-2211-EAE-1090-25M000
1105R40M00000BS
1105R50M00000BS
TFS300P

PCN_NTDO-19HYTI032
Affected CPN list
TFS700A
1157R16M00000BB
1620F156M2500BG
PX-709-0024-100M000000
TFS654
TFS686
TFS718A
TFS752
TFS790A
TFS844B
TFS942L
TX-708-0002-98M0000000
OX-400-0061-27M000
EX-4211-0008-10M0000000
OX-2281-EAE-5000-20M000
TFS1200E
OX-249-CJF-107FFS-40M9600000
TX-8010-EAE-2870-40M0000000
TX-8010-EAE-2870-50M0000000
TFS434T
CO-447A-7B-8M00000000
PX-609-0003-24M0000000
OX-6011-EAE-1080-12M8000000
11389-02
OX-0480-BEE-1572-100M000000
TFS291
TFS458B
TX-5500-EAE-106A-25M0000000
C1460A1-0010_SNPB
TFS1209A
OX-400-0041-A-25M00
1116R48M00000BG
TX-5500-DEE-507A-50M0000000
VX-501-0297-124M992
VS-800-EEE-EANN-969M000000
VS-800-EEE-EANN-1G20000000
C2260F156DAA2-20.00
TX-700-0028-S-10M0
TX-700-0028-S-10M0
TX-700-0032-10M0
TX-700-0032-10M0
1157R10M00000BD
2205C50M00000TAC
VX-501-0298-125M0
TX-5500-EEE-106A-30M0000000

PCN_NTDO-19HYTI032
Affected CPN list
PX-5000-DAE-KFXX-12M0000000
PX-5000-DAE-KFXX-12M0000000
HT-MM900AC-9K-JE-125M0000000
PX-501-0059-1920M0
OX-305-0001-100M0000000
PX-706-0014-100M0
1240R156M2500BS
TX-7070-DAE-106C-40M0000000
TX-7070-DAE-106C-50M0000000
VC-806-0001-156M250000_SNPB
VC-801-JAC-KAAN-37M0000000_SNPB
VCC1-G3R-25M0000000_SNPB
VCC6-LAP-156M250000_SNPB
VCC6-LAP-200M000000_SNPB
VCC6-QAP-212M500000_SNPB
VCC1-B3P-100M000000_SNPB
VCC6-RAP-106M250000_SNPB
VCC6-VAP-200M000000_SNPB
TFS125W
EX-219-DAF-157FSS-100M0000000
OX-249-CAF-107FSS-64M0000000
5245957-6M0000000
TFS82F
TX-7070-EAE-106C-16M3686400
TX-707-0044-20M00000000
MD-228-0028-10M00000000
OX-249-CAF-107FEN-64M00000000
1157R20M00000BF
1119E80M00000BS
MD-999-0046
VX-805-EAE-KEAN-143M360000
TFS298
1103E20M00000BA
1157E61M38000BA
1157V64M00000BA
OX-221-0138-10M00000000
PX-709-0029-50M00000000
PX-709-0031-50M00000000
PX-3600-DBC-DKXB-20M00000000
PX-369-0261-156M25
PX-7000-DAE-SSXX-20M00000000
VX-701-0047-100M0
VX-504-0014-491M52
EX-219-CAD-107FEN-38M1900000
1101R100M0000BS

PCN_NTDO-19HYTI032
Affected CPN list
XR-R111-3EE-BEAX-30M000000
TX-5500-EAT-106A-20M0000000
MX-171-0002-10M0000000
1196721-43FM-61M666667
1604D125M0000BX
1604F125M0000BA
1118R32M00000BX
MX-6000-EAJ-2081-16M3840000
OX-4000-EAE-2082-20M0000000
TFS457C
TFS467B
TFS535A
5321E106M2500BX
5321E120M0000BX
5321E280M0000BX
PX-409-0034-24M0000000
TFS140BZ
1115D16M00000AB
1121X40M00000BX
TX-707-0045-50M0000000
TX-707-0046-50M0000000
TX-707-0047-50M0000000
1117R50M00000BX
TFS1610
TFS70CG
1117R36M86400BX
TX-707-0048-50M0000000
1680F100M0000BS
VC-827-HDF-FAAN-120M000000
VC-827-HDF-FAAN-125M000000
TX-8010-GFE-2871-40M0000000
TFS921B
1105R2M097152AS
HT-MM900B7-7E-JS-100M000000_SNPB
HT-MM900B7-7E-ES-14M3180000_SNPB
VX-209-0019-156M25
VX-209-0020-156M25-PS186
1157D52M50000BX
PX-5002-EAC-PKXX-27M0000000
PX-5002-EAC-PKXX-33M0000000
PX-7005-JDC-ZKXX-100M000000
VS-800-EGE-AANG-2G46400000
VCC1-B3B-90M0000000_SNPB
2133B100M0000DAB
511126-0504-B

PCN_NTDO-19HYTI032
Affected CPN list
EX-385-0002-10M0000000
EX-385-0002-10M0000000_BOX
EX-219-DAF-157FEN-100M000000
5219R100M0000BS
1420R125M0000CB
1280R100M0000BB
PX-8201-EDF-KXAX-200M000000
M55310/16-B24A400K0000_SNPB
PX-7021-0064-16M0000000
TX-707-0049-50M0000000_SNPB
TFS514B
TX-7070-EAE-506A-16M3840000
TFS400V
TFS400W
1680D100M0000BX
PX-5716-0001-33M3333330
PX-5716-0002-64M0000000
2104D33M554432VAX
2115D87M50000MAX
MC985X1-005Z
TFS246X
TFS1575AW
TFS1278C
TX-7070-EAJ-106B-10M0000000
TFS157B
TFS161D
FX-500-EAE-KNNN-BM-C4
FX-500-EAE-KNNN-C6-E2
1219D80M00000BX
M55310/26-B36A14M31818
M55310/26-B36A12M00000
TFS1575AX
TFS150BC
11007061-022-A-100M000000
11007061-022-A-80M000000
5319D480M0000BX
2101D50M00000YAX
5321E106M2500BA
5321E120M0000BA
5321E280M0000BA
EX-4012-EAE-3080-10M0000000
EX-4012-DEE-1071-98M3040000
EX-4010-EEE-1071-10M0000000
SB7BB
SB7BV

PCN_NTDO-19HYTI032
Affected CPN list
2233D100M0000KAX
TX-7070-EFE-106A-50M0000000
2223R100M0000TAS
TFS1905B
OX-4000-EAE-0580-12M8000000
TFR750C
1157R48M00000AD
1157R48M00000BD
TDX1209B
VX-5040-DAE-3050-50M0000000
TFS1227H
TX-209-0043-48M0000000
1203R96M00000BD
VT-841-JFE-5070-40M0000000_SNPB
OX-041-0048-10M0000000
TX-7070-EAE-106C-30M0000000
VX-706-0009-20M0
ON853284-1
TX-7070-EAF-506A-40M0000000
TX-7070-EFF-506A-40M0000000
5221R125M0000BB
TFS291A
VX-369-0005-96M2500000
VCC1-B3D-50M0000000_SNPB
1204B156M2500BB
SB7BG
SB7BL
SB7BQ
0429CTEX10M00000_SNPB
TX-7070-EAE-106D-19M2000000
1157D45M46800BX
1104R24M00000BS
1177E50M00000BS
TX-8010-EAE-1060-16M3840000
5321R160M0000BS
2205R40M00000YAF
1604F122M7600BA
1157D60M00000BX
1157D78M12500BX
TFS915Z
PX-8203-EDF-KXAX-200M000000
2223B80M00000VAX
EX-219-DAF-157FSS-50M0000000
VX-505-0005-120M0
ON853285-1

PCN_NTDO-19HYTI032
Affected CPN list
XR-B-0002-20M000
1157D10M00000BX
1157R24M00000BF
1157R25M00000BF
1157R60M00000BF
1157R80M00000BF
1157R32M76800BF
XR-U-0001-10M000
VX-369-0006-96M2500000
TX-7070-EAT-106C-40M0000000
TX-7070-EAT-106C-30M0000000
1157D33M33333BX
VX-501-0302-100M0
TFR750CS01
MV-OS904X-2113T-BKLX-27M00000
11389-06
PX-369-0266-100M000000
TX-209-0044-120M114583
1680F100M0000BG
1320R100M0000BA
XR-R-0002-20M000
1117R50M00000BS
TFS942M
13064-702
TX-189-0028-99M2000000
PX-8202-EAE-KXAX-1M25000000
TFS866D
PX-709-0036-52M5000000
VX-5040-EAE-3050-100M0
TX-5500-EFE-507A-100M000000
EX-219-0033-30M0000000
EX-219-SAF-107FEN-10M0000000
MC985X1-006Z
1116V50M00000BA
TFR400X
TFS1220Z
OX-228-0012-10M0000000
2205R50M00000KAX
2205R50M00000KAF
1219R125M0000BF
TX-189-0029-156M250000
OX-208-0010-10M0000000
2105D93M33333KAX
2104R33M554432VAS11
1240B156M2500BX

PCN_NTDO-19HYTI032
Affected CPN list
1103R25M00000BE
TFS1209C
TX-191-0011-200M000000
PX-7004-JAC-ZXXB-100M000000
AXX43-50-10M000
AXX37-04-10M000
1203D96M00000BX
1203D96M00000BG
1320B100M00000BX
1240B125M00000BX
4516-50M000000
4517-75M000000
4518-100M000000
4519-150M000000
4520-200M000000
1604D40M00000BX
1117X50M00000BX
1117R50M00000BF
1103R100M00000BS
1103R24M00000BS
1203D100M00000BX
1203D156M2500BX
5319D320M00000BX
1157D12M00000BX
1240D80M00000BX
1104D66M60000BX
1104D12M00000BX
1104R50M00000BS
1104R66M60000BS
1104R100M00000BS
1104R12M00000BS
MX-5030-DAJ-2081-10M000
PX-5701-JA3-VXXX-4M00000000
TX-801-0073-50M000
1116V90M00000BA
1203D125M00000BX
311206995-80M000
TX-8010-EFE-2871-40M0000000
1116V20M00000BA
SB7AZ
SB7BA
SB7BC
SB7BD
SB7BE
SB7BF

PCN_NTDO-19HYTI032
Affected CPN list
SB7BH
SB7BI
SB7BJ
SB7BK
SB7BM
SB7BN
SB7BO
SB7BP
SB7BR
SB7BS
SB7BT
SB7BU
SB7BW
MX-5030-EAJ-2081-20M0
TX-801-0074-24M576
1157R48M00000BA
1157R24M00000BA
1157R9M216000AX
TX-8010-EFE-1061-10M0000000
PX-369-0128-156M25-PS229
PX-369-0159-200M00-PS229
MC985X1-006H
1116R80M00000BS
PX-8201-EDE-FXXX-150M000000
TFS2052A
OX-228-0014-10M0000000
1177D50M00000BX
1177D80M00000BX
1103R16M00000BS
VT-827-EFH-2060-32M0000000
1395AS301-2
10038581-022-D-97M500000-NI
10038581-022-O-125M000000-NI
10038581-022-D-90M000000-NI
PX-8201-EDE-FXXX-125M000000
1110R100M0000AS
1103R96M00000BS
1404R100M0000BS
1103R40M96000BS
EX-219-DAK-758FEN-50M0000000
EX-219-DJK-758FEN-50M0000000
VXN1-9003-24M0000000
EX-4000-EAA-2570-80M0000000
1157R75M00000BA
1157R50M00000BA

PCN_NTDO-19HYTI032
Affected CPN list
1157R40M00000BA
TX-501-0008-30M00
TX-501-0009-40M96
TX-8010-GFE-2871-24M0000000
1119B64M00000BX
PX-507-0005-111M250000
2212D80M00000ABX
PX-4003-DBC-KKXX-16M0000000
1196721-44EM-60M069444
XR-A-0001-100M000
1157E20M00000BF
OX-200-0171-10M0000000
TX-7090-EAE-106D-50M0000000
1116R70M00000BS
1116R48M00000BS
VC-711-0010-128M0000000
VC-711-0010-128M0000000_SNPB
VC-711-0011-50M0000000
VC-711-0011-50M0000000_SNPB
PX-6100-JA5-WXXX-10M0000000
1103R24M00000AD
5321D341M6830BX
1104B90M00000BC
EX-219-CAD-107FSS-38M1900000
1121E40M00000BE
1116R25M00000BS
1103R20M00000BS
1116R24M00000AS
OX-221-0105-INT-20M000
1103R4M000000AF
VS-504-0006-S1-HFE
1115R33M00000BS
5321R560M4000BS
2205D20M00000TAX
VXD1-1E3-10M2360000
VX-209-0023-197M439000
VX-209-0025-498M055800
VXM7-9039-25M0000000
VC-840-9006-25M0000000
EX-219-SAF-157FEN-100M000000
SO-720-LPF-GDN-312M500000
VX-209-0024-491M040000
SO-720-LPF-GDN-250M000000
VC-820-EAC-KAAN-25M0000000
VC-820-EAC-KAAN-20M0000000

PCN_NTDO-19HYTI032
Affected CPN list
1216B200M0000BE
1116R50M00000BS
PX-369-0256-156M25-PS229
PX-369-0263-200M00-PS229
PX-369-0265-156M25-PS229
M55310/19-B12B32M00000
VC-840-1032-25M0000000
VCC1-9004-114M285000
5116V14M31818LD
1216B40M00000BE
FX-500-EAE-KSNA-J9-J9
2123D200M0000YAX
1117R48M00000BX
2215D100M00000TBX
TX-7090-EAE-106C-50M0000000
MC039A1-001A
MC039A1-002A
MC039A1-003A
1111R60M62400BS
1102R16M38400BS
1103R58M72026BS
TFS276D
1604D125M4000BX
1157R50M00000BS
1157R12M00000BX
VT-840-0049-19M2000000
1103R37M50000BS
1420R125M0000CF
10225-1206-9M600000
MD-999-0030-10M0000
TX-209-0046-48M0000000
5319D187M5000BX
1157R12M00000BC
VCC1-B3F-36M0000000
VTB1-1019-25M0000000
VXM7-1355-25M0_SNPB
5321D197M4390BX
5321D498M0558BX
OSP612206724
OSP612206693
OSP612206704
PX-5070-EAC-FKXX-40M0000000
PX-5072-EAC-FKAB-40M0000000
TX-189-0028-99M2000000_SNPB
1103R32M00000AF

PCN_NTDO-19HYTI032
Affected CPN list
VCC1-B3R-25M0000000_SNPB
1157R38M40000BB
1280R60M00000BS
1121D500K0000BX
1220R200M00000BS
1121R500K00000BS
1157R25M00000BS