



Title of Change:	2Q2017 Product Discontinuance Notice
Last Time Buy Date:	10 January 2018
Last Ship Date:	10 July 2018
Contact information:	Contact your local ON Semiconductor Sales Office or <PCN.Support@onsemi.com >
Type of notification:	Customers must notify ON Semiconductor (<PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, ON Semiconductor is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

ON Semiconductor has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, ON Semiconductor has partnered with Rochester Electronics who will carry any remaining device inventory.

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 5817 1060

Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China



NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of affected Parts: *See attachment*

To access file attachments on pdf copy of PDN, please be guided by the steps below:

- 1. Download pdf copy of the PDN to your computer*
- 2. Open the downloaded pdf copy of the PDN*
- 3. Click on the paper clip icon available on the menu provided in the left/bottom portion of the screen to reveal the Attachment field*
- 4. Then click on the attached file/s*

Affected MPN

NCP78LC27NTRG	LV47009P-E	NCP4671DMX15TCG	NCP4587DMX31TCG
NCP585LSN09T1G	NCP583XV26T2G	LA5779-E	NB4L858MFAR2G
NOA3302CUTAG	NCP582DXV28T2G	STK672-600	NCP694DSAN08T1G
NCP694HSAN10T1G	NCP4680DMX12TCG	NCP4671DMX09TCG	MC10E404FNR2G
NCP693HMN12TCG	PACVGA200QR	BR281Q32A101V1G	LB11988HR-TLM-H
TND316S-TL-2H	NCP4671DMX12TCG	LV4904V-TLM-E	NCP582LXV33T2G
STK672-410C-E	NCP585HSN30T1G	NCP4687DMX18TCG	NCP582DXV18T2G
NCP4624DSQ12T1G	NCP78LC33NTRG	NCV8668ABD250R2G	NCP693HMN08TCG
MC10EP05DTG	NCP4626HMV050TCG	NCP4671DMX13TCG	NCP582LXV18T2G
TND524VS-TL-H	R3710-CEAA-E1	NCP694HSAN08T1G	NCP2860DM277R2G
NCP4626HSN033T1G	NCP5104PG	NCP1587GDR2G	LA79200V-TLM-E
STK681-320	NCP582DXV25T2G	NCP4680DMX28TCG	NCP4626DMX030TCG
NCP4626DMX045TCG	MC10EP01DG	NCP582LSQ15T1G	NCP4586DMU15TCG
NCV380LMU15AATBG	LB1731-H-E	LA5779MP-DL-E	NCP4680DMX10TCG
STK672-400	SMA4306-TL-H	NCP693DMN12TCG	NCP4688DMU30TCG
NBSG16VSMNG	STK672-400B-E	NCP4626DSN045T1G	NCP4687DMX25TCG
TND321VD-TL-H	NCP585DSN09T1G	NCP5304PG	NCP693DMN25TCG
STK760-221A-E	NBSG16VSMNHTBG	MC10EP29MNG	NCP694D08HT1G
LA5752-E	NCP4680DMX15TCG	L78LR05D-LR-E	NCP78LC40NTRG
NBSG16VSMNR2G	TND027SW-TL-2H	NCP1271P100G	NCP694DSAN10T1G
NCP4624DMU33TCG	STK672-410	NCP582DXV33T2G	NCP4626HSN045T1G
AX-SF10-ANT21-868-B1	NCP5106BPG	LC72711LWHS-E	AX-EO01-USB01-868-GEVB
LV5609V-HAS-TLM-E	LC898108B-TBM-H	TND314S-TL-2H	AX-SF-LIB-1-GEVK
MC10EP32MNR4G	LV4904V-MPB-E	LA5774-E	NCP5106APG
TND525SS-TL-2H	LA5774-FA-E	R3710-CEAA-E1T	TND523SS-TL-2H
NCP5359ADR2G	LV4924VH-TLM-H	MC34025PG	LC898108A-N-TBM-H
NCP4623HMV045TCG	MC10LVEP16DTG	NCP4683DMU09TCG	NCP4586DMU30TCG
NCP582LXV29T2G	STK672-610	PACDN004SR	NCP4684EMX25TCG
NCP78LC28NTRG	MC100EL11DTG	NCP693DMN08TCG	NCP78LC50NTRG
NCP582LXV30T2G	L78MR05-FA-E	NCP4586DMU18TCG	NCP4624DMU12TCG
NB4L858MFAG	MC100EP131MNG	NCP78LC25NTRG	STK531-367A-E
L78LR05D-FA-E	MC100EP16TDTR2G	MC10EP116FAG	NCP582LXV28T2G
NCP4626HMV033TCG	NCP4586DMU28TCG	MC33025PG	NCP585DSN28T1G
AX-SF-LIB-1-GEVK	MC10LVEP11DG	NCP4352SNT1G	NCP583XV29T2G
NCP4683HMU185TCG	STK672-401C-E	NCP4680DMX23TCG	SZPACDN004SR
NCP4586DSQ30T1G	LC749880T-E	NCP4588DMX10TCG	NCP4588DMX15TCG
MBR3045STG	TND322VD-TL-H	NCP4671DMX06TCG	NCP4626HSN030T1G
NCP78LC30NTRG	NCP4687DMX33TCG	NCP81109BMNTXG	LA5771MP-DL-E
NCP582LXV25T2G	LB1205-L-E	LV5609V-MPB-E	NCP4681DMX35TCG
AX8052F143-2-TB05	NCP4626DSN030T1G	NCP1252APG	NCP582DXV15T2G
STK531-344A-E	NCP582DSQ25T1G	NCP4684EMX33TCG	NCP5111PG
NCP694DSAN25T1G	STK5F4U3C2D-E	TND027SW-TL-2H-Z	NCP4682DMU19TCG
NCP693HMN25TCG	TND315S-TL-2H	NCP4626DMX033TCG	LB11693JH-TLM-E
NCP4624DSN12T1G	NCP584LSN09T1G	NCP4624DSN18T1G	LV56081GP-TE-L-E
STK5F4U3E2D-E	STK672-400C-E	STK672-600A	NCP1271P65G
NCP5359DR2G	NCP4620HSQ15T1G	NCP582LXV15T2G	TND323VD-TL-H
MC10E164FNR2G	AX8052F143-2-TX30	NCP4302BDR2G	