

Cypress Semiconductor Corporation, 198 Champion Court, San Jose, CA 95134. Tel: (408) 943-2600

# **PRODUCT CHANGE NOTIFICATION**

PCN: PCN153903

Date: September 24, 2015

**Subject:** Qualification of Cypress Bangkok as an Additional Assembly Site for Select 48-Lead TSOP I Products

To: PCN ADMIN CYPRESS pcn\_adm@cypress.com

## Change Type: Major

## **Description of Change:**

Cypress announces the qualification of Cypress Bangkok (formerly Spansion Bangkok) for the assembly of select 48-lead Thin Small Outline Package Type I (TSOP I) products. Cypress Bangkok is a world-class assembly facility, qualified to build standard grade as well as automotive grade products consistent with AEC-Q100. Cypress Bangkok is certified to several international quality standards, including ISO/TS16949, OHSAS18001 and ANSI/ESD S20.20. The qualification of this facility will enable Cypress to tailor assembly operations to meet our customers' stringent quality and reliability requirements in our effort to continually provide world-class service. 48-lead TSOP I packages assembled at Cypress Bangkok will use the following Bill of Materials (BOM).

48-Lead TSOP I					
Assembly Site	OSE Taiwan		ASE Taiwan		CY Bangkok
Mold Compound	Hitachi Cel 9200HF-U	Hitachi Cel 9200HF-U	Hitachi Cel 9200THF-U	Sumitomo EME-G631	Hitachi Cel 9200HF10-U
Die Attach	Sumitomo 4900G	Ablebond 8340	Ablebond 8340	Sumitomo CR1076	Sumitomo CRM-1150B
Bond Wire	0.8 mil Au	0.8 mil Au	0.8 mil Au	0.8 mil Cu	0.9 mil Cu
Lead Finish	NiPdAu	Pure Sn	Pure Sn	Pure Sn	Pure Sn

There are no changes to ordering part numbers. Product datasheets remain the same and can be downloaded from the Cypress Website (www.cypress.com).

## Benefit of Change:

The addition of Cypress Bangkok as a manufacturing location allows Cypress to leverage additional manufacturing expertise and quality focus. This in turn provides the means for Cypress to continue to meet our customers' requirements and meet our delivery commitments in dynamic market conditions.

### Affected Part Numbers: 36

**Affected Parts:** See the attached file for a list of all part numbers affected by this change. Note that any new 48-lead TSOP I parts that are introduced after the publication of this PCN may also be manufactured at the Cypress Bangkok facility.

#### **Qualification Status:**

Cypress Bangkok has been qualified through a series of tests documented in the Qualification Test Plan (QTP) report 152916. The qualification report can be found as an attachment to this notification or by visiting <u>www.cypress.com</u>, and typing the QTP number in the keyword search window.

### Sample Status:

Qualification samples are not built ahead of time for all part numbers affected by this change. Please review the attached file for a list of affected part numbers with their associated sample ordering part numbers. Sample requests for products without sample order part numbers are not built ahead of time, they will be built to order and subject to standard lead times. Please contact your sales representative as soon as possible, but within 30 days of the date of this PCN, to place any sample orders.

### Approximate Implementation Date:

Effective 90 days from the date of this notification or upon customer approval, whichever comes first, all shipments of the affected part numbers in the attached file will be supplied from Cypress Bangkok or any other approved assembly sites.

### Anticipated Impact:

Products manufactured at Cypress Bangkok are completely compatible with existing product from a functional, parametric, and quality performance perspective.

Cypress recommends that customers take this opportunity to review these changes against current application notes, system design considerations and customer environment conditions to assess impact (if any) to their application.

## Method of Identification:

There will be no changes to the part number. Cypress maintains traceability of product to wafer level, including wafer fabrication location, through the lot number marked on the package.

#### **Response Required:**

No response is required.

For additional information regarding this change, contact your local sales representative or contact the PCN Administrator at <u>pcn\_adm@cypress.com</u>.

Sincerely,

Cypress PCN Administration