



Product Change Notification - SYST-22WRBQ127

Date:

23 Aug 2018

Product Category:

Temperature Sensors

Affected CPNs:



Notification subject:

Data Sheet - MCP9808 0.5C Maximum Accuracy Digital Temperature Sensor

Notification text:

SYST-22WRBQ127

Microchip has released a new DeviceDoc for the MCP9808 0.5C Maximum Accuracy Digital Temperature Sensor of devices. If you are using one of these devices please read the document located at [MCP9808 0.5C Maximum Accuracy Digital Temperature Sensor](#).

Notification Status: Final

Description of Change: 1) Updated "Features". 2) Updated the "Temperature Sensor DC Characteristics" table. 3) Various typographical edits.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 23 Aug 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[MCP9808 0.5C Maximum Accuracy Digital Temperature Sensor](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

MCP9808-E/MS

MCP9808T-E/MC

MCP9808T-E/MS