

Precision Component Sales Division http://pewa.panasonic.com/components

Product Discontinuation Notice


March 2012

Discontinuation of RK Relays



1. Reason: Replacement part

2. Affected parts:



3. Last time buy: End of August 2012

4. Substitution:

RS (ARS) relays (The terminal pitch is different.)	ARSO
--	------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-32)