



115 Northeast Cutoff
Worcester, MA 01606

Date: 12/16/2014

Customer Notification of Product Status Change

Customer: DIGI-KEY

Device	Reason for Status Change	Suggested Replacement
A3932SLDTR-T	Low volume sales	A3938SLDTR-T
ATS616LSGTN-T	Low volume sales	ATS617LSGTN-T

Originator: J.Hurley

Local Contact: Fran Brockway

Contact E-mail: Fbrockway@allegromicro.com

Current Status: **ACTIVE**

Revised Status: **NOT FOR NEW DESIGN**

Reason for Status Change: Please see table above

Alternative Allegro Solutions: Please see table above

For the listed replacement part PPAPs are available upon request. Processing time for PPAP may be up to three weeks. Allegro does not represent that the suggested replacement part is suitable for customer's application(s). Customer shall conduct its own qualification and validation testing on any suggested replacement part prior to the sale of customer's product.

Customer Notification Confirmation

Received by:

Title:

Date:

cc: Allegro Sales/Marketing