



AKM Semiconductor, Inc.

End of Life Notice

Document ID : AKMSPK170420A_rev.1 (* 5 parts removed from the affected part list)
 Product affected : Listed below
 Date of notification : 04/20/2017 (revised on 06/06/2017)

Last Time Buy date : 9/30/2017
 Last shipment date : 9/30/2018

AKM will discontinue below listed products due to closure of assembly site.

Affected Part Number	Suggested Replacement Part Number
1. AK2301 *Removed	AK2300 http://www.akm.com/akm/en/file/datasheet/AK2300.pdf AK2301A http://www.akm.com/akm/en/file/datasheet/AK2301A.pdf
2. AK2307 *Removed	AK2306/AK2306LV http://www.akm.com/akm/en/file/datasheet/AK2306VM.pdf
3. AK2307LV *Removed	
4. AK4121AVF *Removed	AK4136VQ http://www.akm.com/akm/en/file/datasheet/AK4136VQ.pdf (recommended)
5. AK4121VF	AK4127VF http://www.akm.com/akm/en/file/datasheet/AK4127VF.pdf
6. AK4366VT	AK4376AECB (recommended) Contact AKM sales for details AK4376ECB http://www.akm.com/akm/en/file/datasheet/AK4376ECB.pdf
7. AK4381VT	AK4432VT http://www.akm.com/akm/en/file/datasheet/AK4432VT.pdf
8. AK4385VT	AK4452VN http://www.akm.com/akm/en/file/datasheet/AK4452VN.pdf
9. AK4389VT *Removed	AK4482VT http://www.akm.com/akm/en/file/datasheet/AK4482VT.pdf
10. AK4565VF	AK4556VT http://www.akm.com/akm/en/file/datasheet/AK4556VT.pdf
11. AK5359ET	AK5720VT http://www.akm.com/akm/en/file/datasheet/AK5720VT.pdf
12. AK5380VT	AK5552VN http://www.akm.com/akm/en/file/datasheet/AK5552VN.pdf
	AK5522VN Contact AKM sales for details *AK5359 has an Automotive grade version : AK5359VT
13. AK7353	N/A
14. AK8130	AK8130x http://www.akm.com/akm/en/file/datasheet/AK8130AH.pdf
	http://www.akm.com/akm/en/file/datasheet/AK8130B.pdf
	http://www.akm.com/akm/en/file/datasheet/AK8130C.pdf
15. AK8134A	N/A
16. AK8411VT	N/A

AKM will consider this notice fully noticed and approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice.

AKM Semiconductor, Inc.
 1731 Technology Drive, Suite 500
 San Jose, CA 95110